

**RW AUTOMOTIVE APPRAISERS SERVICES**

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

INVOICE

Soon Lee Choon Auto Services Pte. Ltd. Invoice No : 200045
Blk 5032, Ang Mo Kio Industrial
Park 2, #01-283 Date : 20.08.2020
Singapore 569535
On behalf of Muhammad Firdauz Bin Mohamed Salleh

Being:	
Survey Fees (including 26 photographs and transport charges)	\$ 406.00
S'pore Dollars : Four Hundred and Six only.	<u>\$ 406.00</u>
Our Reference No. : RW/0045/20TP	
Vehicle No. : SLM 8130 U	

SURVEYED WITHOUT PREJUDICE

RICHARD WONG
(Licensed Appraiser)



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: +65 6553 3912

Reg. No. 52821270B

Muhammad Firdauz Bin Mohamed Salleh
c/o Soon Lee Choon Auto Services Pte. Ltd.
Blk 5032, Ang Mo Kio Industrial
Park 2, #01-283
Singapore 569535

Report No : RW/0045/20TP

Date : 20.08.2020

VEHICLE INSPECTION REPORT

REFERENCE

Requested by : Workshop, owner's behalf
Date of Request : 17.08.2020
Date of Accident : 13.08.2020
Date of Inspection : 17.08.2020
Inspected at : Soon Lee Choon Auto Services Pte. Ltd.
Blk 5032, Ang Mo Kio Industrial Park 2
#01-283, Singapore 569535

VEHICLE DETAILS

Vehicle No.	: SLM 8130 U	Make & Model	: Kia Cerato K3
Year Make	: 2017	Colour	: Grey
Engine No.	: G4FGGH651278	Chassis No.	: KNAFZ411MH5708126
Engine Capacity	: 1591 cc	Mileage	: 89,996 km
Air-Con	: Yes	Radio/CD/Cassette	: Yes
Seat Belt	: Yes	Rims	: Sport

GENERAL CONDITION OF VEHICLE

General Condition	: Good	Modification	: Nil
Brakes	: Serviceable	Handbrake	: Serviceable
Steering	: Serviceable		

Tyres	Make	Size	Rim	Tread Balance
Front Right	Roadstone	215/45 ZR17	Sport	4 mm
Front Left	Roadstone	215/45 ZR17	Sport	4 mm
Rear Right	Roadstone	215/45 ZR17	Sport	4 mm
Rear Left	Roadstone	215/45 ZR17	Sport	4 mm

ASSESSMENT

	Repairer's Estimate	Recommendation
Spare Parts	: \$ 4,192.60	\$ 3,165.70
Labour Charges	: \$ 1,080.00	\$ 780.00
Paint Work	: \$ 900.00	\$ 700.00
Towing Charges	: \$ -	\$ -
Total	: \$ 6,172.60	\$ 4,645.70
Recommend lump sum repairs		: \$ 3,710.00
Reduction		: \$ 2,462.60
Estimated Period Required for Repair (Working Day)		: 3 days

Subst 1/5 @ 2500
3 days

Front tyre can't be crooked.

**RW AUTOMOTIVE APPRAISERS SERVICES**

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: +65 6553 3912

Reg. No. 52821270B

Page : 1

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SLM 8130 U

Report No.: RW/0045/20TP

<u>S/No</u>	<u>QTY</u>	<u>Description</u>	<u>Condition/ Remarks</u>	<u>Repairer's Estimates</u>	<u>My Recommendation</u>
-------------	------------	--------------------	-------------------------------	---------------------------------	------------------------------

REPLACEMENT OF DAMAGED PARTS

1)	1	Front bumper	Cracked	\$ 639.00 N	\$ 639.00 X
2)	1set	Front bumper clips	Necessary	\$ 30.00 N	\$ 30.00 ✓
3)	2	Front bumper side holders	Necessary	\$ 66.00 N	\$ 66.00 X
4)	1	Front bumper reinforcement	Repairable	\$ 410.00 N	- X
5)	1	Front bumper lower beam	Repairable	\$ 125.00 N	- X
6)	1	Front bumper sponge	Serviceable	\$ 145.00 N	- X
7)	1	Front bumper logo	Necessary	\$ 48.00 N	\$ 48.00 ✓
8)	1	Front bumper sensor	Failed	\$ 220.00 N	\$ 220.00 X
9)	1	Front bumper fog lamp	Serviceable	\$ 205.00 N	- X
10)	1	Front grille	Serviceable	\$ 256.00 N	- X
11)	1	Front headlamp RH	Cut	\$ 1,870.00 N	\$ 1,870.00 ✓
				<u>\$ 4,014.00</u>	<u>\$ 2,873.00</u>
Less 10%				<u>\$ 401.40</u>	<u>\$ 287.30</u>
				<u>\$ 3,612.60</u>	<u>\$ 2,585.70</u>

12)	1	Front bumper lower spoiler	Cracked	\$ 580.00 SN	\$ 580.00 ✓
Total (Parts):				\$ 4,192.60	\$ 3,165.70

LABOUR CHARGES

13)	Panel beat front right fender and front support panel. Straighten front right chassis. Remove and replace all damaged parts.	\$ 800.00	\$ 600.00	300
14)	Check lightings and wiring.	\$ 60.00	\$ 40.00	20
15)	Remove and reinstall front bumper sensors.	\$ 100.00	\$ 60.00	50
16)	Rust proofing treatment on affected area.	\$ 120.00	\$ 80.00	X
17)	Spray painting on affected area.	\$ 900.00	\$ 700.00	400
Total (Labour):		\$ 1,980.00	\$ 1,480.00	

Total:	<u>\$ 6,172.60</u>	<u>\$ 4,645.70</u>
---------------	---------------------------	---------------------------

1948
102
1753.20
3103.20
2482



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 528212708

Page : 2

Vehicle No: SLM 8130 U

Report No.: RW/0045/20TP

POINT OF IMPACT

At the front portion right side of the vehicle.

RECOMMENDATION

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is \$4,645.70.

CONCLUSION

The repairer has agreed to undertake repairs at a lump sum of \$3,710.00 corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE



RICHARD WONG
(Licensed Appraiser)