



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 5956Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
1	REAR BUMPER (SN)	CRUSHED	675.00	675.00
1	CENTRAL STRIP, BPR/R (SN)	NOT NECESSARY	371.70	-
1	OVERRIDE - RH REAR BUMPER (SN)	NOT NECESSARY	248.40	-
1	OVERRIDE - LH REAR BUMPER (SN)	NOT NECESSARY	248.40	-
1	RECESS DOOR-REAR BUMPER (TOW HOOK) (SN)	NOT NECESSARY	49.50	-
1	BRACKET-CENTRAL REAR BUMPER (SN)	NOT NECESSARY	108.00	-
1	BUMPER BRACKET LH (SN)	NOT NECESSARY	82.80	-
1	REINFORCEMENT - REAR BUMPER (SN)	NOT NECESSARY	441.00	-
1	BRACKET - OVERRIDE RHR BUMPER (SN)	NOT NECESSARY	82.80	-
			2,407.60	695.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & REPLACE REAR BUMPER AND ALL OTHER AFFECTED AREAS.		600.00	600.00
	TO CONDUCT RE-PROGRAMMING AND RESETTING OF ECU INCLUDING CLEARING OF FAULT CODES.		600.00	600.00
			1,200.00	1,200.00
<b>GRAND TOTAL</b>			<b>3,607.60</b>	<b>1,895.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,895.00</b>

Report Ref No. CS/SMR22000770/Eqf3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.