

Date: 20.01.2022
Vehicle No: SGD4466J
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA1MC385378
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SBV2121G
Date of Accident: 19.01.2022
Estimator: Victor
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	Bucl/nd	\$763.55
2	FRONT BUMPER SIDE BRACKET RH	1	R	\$29.33
3	FRONT FENDER BRACKET RH	1	R	\$21.83
4	FRONT BUMPER UNDERCOVER	1	CRA	\$216.92
5	HEADLAMP RH	1	mgmt	\$1,308.41
6	HEADLAMP BRACKET RH	1	Sm	\$65.93
7	FOG LAMP ASSY RH	1	Sm	\$291.03
8	FRONT FENDER RH	1	R	\$548.60
9	FRONT SENSORS	2	\$198.88	Short \$397.76
10	FRONT SENSORS HOLDER	2	\$20.67	nu \$41.34
11	FRONT RIM 19 INCH	1		nu \$978.50
12	FRONT FENDER SHIELD RH	1		cm \$176.82
13	FRONT KNUCKLE ARM RH	1		Bj \$520.56
14	FRONT BEARING HUB RH	1		nu \$189.53
15	FRONT UPPER CONTROL ARM RH	1		Dij \$156.82
16	FRONT LOWER ARM RH	1		Bj \$264.30
17	FRONT LOWER LATERAL LINK RH	1		Dij \$283.64
18	FRONT SWAYBAR LINKAGE RH	1		Sm \$18.13
19	STEERING GEAR TIE ROD RH	1		Sm \$171.50
20	FRONT DAMPER RH	1		Sm \$277.57
	4 fog lamp cover RH	816.54	nd	
	4 bumper sponge	\$66.73	cm	
SUB TOTAL				\$6,722.07
LESS 10%				-\$672.21
PARTS TOTAL				\$6,049.86

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		nu \$100.00
2	FRONT UNDER COVER CLIPS	1		nu \$120.00
3	FRONT INNER SHIELD CLIPS	1		nu \$50.00
S/N TOTAL				\$270.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR FRONT ACCIDENT AREA.

\$1,000.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 20.01.2022
Vehicle No: SGD4466J
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA1MC385378
Reg. Year: 2021

Third Party Insurer: DIRECT ASIA
Third Party Veh No: SBV2121G
Date of Accident: 19.01.2022
Estimator: Victor
Surveyor:

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT ACCIDENT ARI	\$1,000.00	4801
TO REMOVE AND INSTALL FRONT UNDERCARRIAGE.	\$250.00	2001
TO CONDUCT WHEEL ALIGNMENT AND BALANCING.	\$150.00	601
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$200.00	201
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$350.00	1501
LABOUR TOTAL		\$2,950.00

TOTAL **\$9,269.86**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

