

NINETEEN AUTOWERKS PTE LTD
436 TAMPINESS STREET 43 #07-97
SINGAPORE 520436
 HP: 96741991(Vessie Foo)

Estimate for SLF1213Y(Toyota Vios)

1 *BONNET	X R				\$798.40
1 *BONNET LOCK	X nn				\$295.20
② *BONNET HINGE L/R	BT				\$390.40
1 *BONNET OUTER SEAL	X nn			216/	\$128.70
1 *BONNET INSULATOR	X nn				\$225.70
1 *FR BUMPER	BR				\$721.40
1 *FR BUMPER REINFORCEMENT	DD			483/	\$499.20
1 *LH FR BUMPER RETAINER	BR			381/	\$128.50
1 *RH FR BUMPER RETAINER	BR			70/	\$128.50
1 *FR BUMPER GRILLE	X nn			70/	\$598.70
1 *FR BUMPER LOGO	AK				\$120.50
1 *FR BUMPER LOWER GRILLE	X nn			65/	\$315.20
1 *LH FR BUMPER SIDE GRILLE	X nn				\$89.70
1 *FR BUMPER LOWER COVER	X nn				\$187.90
1 *RH FR FOG LIGHT GARNISH CHROME	X nn				\$97.60
1 *LH FR FOG LIGHT GARNISH CHROME	X nn				\$97.60
1 *LH HEADLIGHT	BR				\$602.80
1 *LH HEADLIGHT SUPPORT PANEL	X R DD				\$187.90
1 *RH HEADLIGHT	BR				\$602.80
1 *RH HEADLIGHT SUPPORT PANEL	X R DD (photo)				\$187.90
1 *FR SUPPORT PANEL	X R DD				\$684.50
1 *FR SUPPORT PANEL TOP GARNISH	BR			350/	\$97.60
1 *AIRCON CONDENSER	X nn				\$984.50
1 *RADIATOR	X nn				\$754.80
1 *RADIATOR TOP GARNISH	X nn				\$269.70
1 *REAR BOOTLID	DD			794/	\$985.90
1 *REAR BOOTLID RUBBER	CR4				\$212.20
1 *REAR BOOTLID LOCK	BT				\$152.20
1 *REAR BOOTLID LOCK CATCH	X nn				\$82.50
2 *REAR BOOT HINGE	X nn				\$170.00
1 *REAR BOOT CENTRE GARNISH	BR				\$185.20
1 *REAR BOOT CENTRE GARNISH EMBLEM	AK				\$42.50
1 *REAR BOOT EMBLEM (VIOS)	X AK no photo				\$42.50
1 *REAR BOOT EMBLEM (E)(TRD)	AK				\$42.50
② *REAR TAIL LAMP	BR				\$771.60
2 *REAR TAIL LAMP PANEL	X R				\$470.00
2 *REAR TAIL LAMP GASKET	X nn				\$70.40
1 *REAR END PANEL	? DD			598/	\$695.00
1 *REAR END PANEL TOP GARNISH	CUT				\$76.30
2 *REAR FENDER	X R				\$1,970.40
2 *REAR FENDER INNER GARNISH	X nn				\$754.00

1 *REAR FENDER AIR DUCT LH	X nn	\$42.70	
1 *REAR FENDER UNDER SHIELD	X CLH) ml	\$76.40	/
1 *REAR SPARE TYRE PANEL	X nn	\$1,012.20	
1 *REAR SPARE TYRE PANEL TOP CENTRE COVER BOARD	X nn	\$195.60	
2 *REAR SPARE TYRE PANEL TOP SIDE TRAY	X nn	\$402.60	
1 2 *REAR NUMBER PLATE LAMP	? (LH) / BR	\$131.20	65.60 /
1 *REAR WINDSCREEN MOULDING	X nn	\$68.00	
1 *REAR BUMPER	DD	\$785.60	545 /
2 *REAR BUMPER SIDE RETAINER	BR	\$91.00	/
2 *REAR BUMPER BRACKET	BR	\$96.40	/
1 *REAR EXTENSION CHASSIS BEAM	X nn	\$365.20	
1 *REAR SPARE TYRE PANEL SIDE PANEL	X nn	\$130.40	
2 *REAR BUMPER REFLECTOR	X nn	\$105.40	
1 *RR AXLE	X nn	\$1,380.00	
1 *LH REAR WHEEL BEARING	X nn	\$486.00	
1 *LH REAR SHOCK ABSORBER	X nn	\$180.00	
*RH REAR WHEEL BEARING	X nn	\$486.00	
*RH REAR SHOCK ABSORBER	X nn	\$180.00	
Less 25%		\$22,133.60	
		\$5,533.40	
		\$16,600.20	
*FR BUMPER CLIP	mc	\$50.00	30 /
*RH FR FENDER SHIELD CLIP	X nn	\$50.00	
*LH FR FENDER SHIELD CLIP	mc	\$50.00	10 /
*BONNET INSULATOR CLIP	X nn	\$50.00	
*FR BUMPER NO PLATE W CASING	X nn	\$50.00	
*REAR BUMPER CLIP	mc	\$50.00	30 /
*END PANEL TOP GARNISH CLIP	mc	\$50.00	10 /
*REAR NO PLATE W CASING	X nn	\$50.00	
*REVERSE SENSOR	BR	\$300.00	200 /
*END PANEL SEALANT	? / nec	\$80.00	30 /
*ENGINE COOLANT	X nn	\$85.00	
*BOOTLID SPOILER	BR	\$800.00	300 /
*FR BUMPER LOWER	X nn	\$600.00	
*RR BUMPER LOWER	BR	\$600.00	300 /
		\$2,865.00	
TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS MENTION REPAIR PARTS, INCLUSIVE OF REPLACEMENT PARTS		\$2,500.00	1200
TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS		\$1,800.00	1600
APPLY RUST PROOFING ON THE ADJACENT PANELS		\$50.00	30
TO SUPPLY UNDER COATING / PUTTY ON PARTS REPLACED		\$50.00	30
TO PERFORM WATER SEEPAGE TEST AFTER REPAIR		\$80.00	30
TO CHECK WIRING & LIGHTING SYSTEM		\$80.00	30
RE-ADJUST WHEEL ALIGNMENT		\$100.00	60
TO REMOVE & FIT FR UNDERCARRIAGE		\$150.00	X
TO REMOVE & REFIT REVERSE SENSOR		\$80.00	30

7054.90
-25%
5291.17

910

TO REMOVE AND REFIT REAR TRIM, GARNISH ASSY
 TO REMOVE AND REFIT AIRCON CONDENSER, RADIATOR ASSY
 TO TOP UP 134A REFRIGERANT

\$250.00	50
\$250.00	50
\$150.00	120
<u>\$5,540.00</u>	

Total

\$25,005.20

3230

= 9431.17

Steve CLKK)

24/1/22, 3:27pm

WL PL

L/S

My AL by

12 djs

L/S-7544.93

= 7550

limit repair 6k

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: