

160 Sin Ming Drive
#04-05
Sin Ming Autocity
S575722

TP claim against China Taiping Insurance (Your insured: YN8519Z)

Parts

QTY	DESCRIPTION	UNIT	PRICE	TOTAL
1	Rear bumper Distorted	n	1300	1,300
2	Bumper towing cover		110	110
3	Bumper clips		5	50
4	Bumper retainers	n	100	200
5	Reverse PDC sensors (set of 2)	sn	400	400
6	Rear bumper reflector		85	170
7	Boot lid Distorted		1620	1,620
8	Rear logo	n	120	120
9	Boot top spoiler assembly		700	700
10	Rear boot 3rd brake light		350	350
11	Fender clips		3	60
12	Rear emblem	n	90	90
13	Rear end panel Distorted	n	950	950
14	Boot lock Damaged		420	420
15	Boot latch		200	200
16	Boot hinge		340	680
17	Boot Spare tyre Cover Distorted		850	850
18	Boot Spare tyre mounting bracket		740	740
19	Spare tyre		400	400
20	Rear wiper motor		550	550
21	Rear wiper assembly		500	500
22	Boot inner garnish	n	420	420
23	Boot inner rubber	n	400	400
24	Rear Outer Tail lights	n	480	960
25	Rear reinforcement bar		800	800
26	Rear exhaust muffler		1600	1,600
27	Rear exhaust rubber mounts	n	95	380
28	Rear Windscreen with demist function		1400	1,400
29	Windscreen moulding		500	500
30	End panel and windscreen gum		120	360
31	Iroad rear recording camera		450	450
32	Rear fender LH & RH		1300	2,600
33	Inner boot floorboard panel		1100	1,100
34	License plate light module		190	190
35	New number plate with casing		90	90
Parts Total:			\$	21,710.00

Not Authen
61 Pgs &
Revery After Pains

Denise

7783

less 25% : 5837.25

S.N: 640

Labor

1	Check wiring and system function	1	480	480 30
2	Rust proofing on affected areas	1	420	420 80
3	Removal and refit rear windscreen	1	500	500 120
4	Labor to remove and refit rear bumper, boot, reverse sensors, end panel, rear exhaust and tail lights. Include pulling out frame of rear undercarriage	1	1800	1,800 800
5	To cut and weld RH & LH fender, boot floorboard panel	1	1600	1,600 400
6	To respray damaged and refitted parts (rear bumper, spoiler, rear fenders, boot, interior of rear boot frame, end panel and boot floorboard)	1	2400	2,400 1000
Labor Total:			\$	7,200.00

TOTAL: \$ 28,910.00

2430

*Supplementary items would be included if noticed during the course of repair

Contact:

Mr Chai - 96250518

James - 92960289

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 8907.25

H/S : 7.1K.

09 Days.

10DAYS