

**Section A - Accident Details**

Registration Number	SHB5139X
Case Reference Number	TAX/01/22/2030
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	CHANG JIA MING (ZHANG JIAMING)
Type of Accident	Head To Side
Accident Date and Time	16/1/2022 12:15 AM
Accident Reported Date and Time	17/1/2022 11:07 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113711
Special Instruction to ARC, if any	TOWED \$90 / LEFT PORTION
Prepared Date and Time	18/1/2022 11:00 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$800.00
Total Spray Cost	\$2,232.00	\$1,020.00
Total Spare Part Cost	\$11,339.17	\$1,413.97
Total Other Cost	\$1,496.00	\$170.00
<b>TOTAL COST</b>	<b>\$16,081.17</b>	<b>\$3,403.97 (P/P)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	10.0	8.0
Prepared / Adjusted By	<b>Tuck Foo Kok</b>	<b>RASUL (LKK) / NTUC</b>
ARC / Surveyor Sign Off Date	<b>24/01/2022 10:21 AM</b>	<b>24/01/2022 1:14 PM</b>
Signature		
Remarks	Total number of repair days = 8 days. SUP = + 1 day.	PART BY PART REPAIR / RESURVEY BEFORE PAINT PHOTO.

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2202-0078	<b>Invoice Number</b>	
<b>Quotation Date</b>	10.02.2022	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$800.00
<b>Total Labour</b>	<b>\$1,014.00</b>	<b>\$800.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	\$180.00	\$70.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY RIM	\$360.00	\$50.00
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$2,232.00</b>	<b>\$1,020.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$126.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$240.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO CHECK & RESET SYSTEM FUNCTION	\$250.00	\$0.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$40.00
<b>Total Other Costs</b>	<b>\$1,496.00</b>	<b>\$170.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$332.70	0.00	\$0.00	Replace	Not Given
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Replace	Replace
		52462-47130	PAD, RR BUMPER, RH & LH , 3	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52462-47030	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52462-47020	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Check

X  
✓  
✓  
✓  
✓  
X  
X

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/02/2022

User ID : PohSuan

	52592-47080	SEAL, RR BUMPER , LH	0.00	\$118.30	0.00	\$0.00	Replace	Check	X
	81561-47471	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$339.60	0.00	\$0.00	Replace	Not Given	X
	81456-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$261.00	0.00	\$0.00	Replace	Not Given	X
	81590-47070	LAMP ASSY, REAR, LH	0.00	\$293.60	0.00	\$0.00	Replace	Not Given	X
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
	62332-47050	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	0.00	\$97.50	0.00	\$0.00	Replace	Not Given	X
	67918-47070-C0	PLATE, REAR DOOR SCUFF, LH	0.00	\$113.50	0.00	\$0.00	Replace	Not Given	X
	67004-47211	PANEL SUB-ASSY, REAR DOOR , LH	1.00	\$1,294.90	100.00	\$0.00	Replace	Repair	R
	68630-47050	CHECK ASSY, REAR DOOR	0.00	\$183.80	0.00	\$0.00	Replace	Not Given	X
	67872-47051	WEATHERSTRIP, REAR DOOR LH	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	X
	68189-47030	WEATHERSTRIP, REAR DOOR QUARTER WINDOW ,	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
	69211-47021-A1	DOOR OUTER HANDLE REAR , LH	0.00	\$97.40	0.00	\$0.00	Replace	Not Given	X
	69060-52280	DOOR LOCK REAR , LH	0.00	\$561.90	0.00	\$0.00	Replace	Not Given	X
	69410-20110	DOOR LOCK STRIKER	0.00	\$39.30	0.00	\$0.00	Replace	Not Given	X
	68760-20122	HINGE ASSY, REAR DOOR , UPPER LH	0.00	\$98.90	0.00	\$0.00	Replace	Not Given	X
	68780-52031	HINGE ASSY, REAR DOOR , LOWER LH	0.00	\$87.10	0.00	\$0.00	Replace	Not Given	X
	85710-47150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$926.00	0.00	\$0.00	Replace	Not Given	X
	69804-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	0.00	\$206.70	0.00	\$0.00	Replace	Not Given	X
	82154-47380	WIRE, REAR DOOR, LH	0.00	\$247.40	0.00	\$0.00	Replace	Not Given	X
	61602-47180	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$871.50	25.00	\$653.63	Replace	Replace	√
	65638-47060	LINER, REAR FENDER , LH	0.00	\$139.80	0.00	\$0.00	Replace	Not Given	X
	62940-47010	DUCT ASSY, QUARTER VENT , RH & LH	0.00	\$67.00	0.00	\$0.00	Replace	Not Given	X
	62332-47050	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	0.00	\$97.50	0.00	\$0.00	Replace	Not Given	X
	62552-47050-C0	GARNISH, REAR SEAT SIDE, LH	0.00	\$241.90	0.00	\$0.00	Replace	Not Given	X
	4261147450	WHEEL, DISC	1.00	\$1,879.40	100.00	\$0.00	Replace	Repair	R
		TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	√
	43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$668.90	0.00	\$0.00	Replace	Not Given	X
	67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,300.70	100.00	\$0.00	Replace	Repair	R
		STICKER STRIDES TAXI ( DOOR )	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
	42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>				<b>\$14,168.28</b>		<b>\$1,233.07</b>			

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52576-47060	RETAINER, RR BUMPER, LH	1.00	\$132.60	25.00	\$99.45	Replace	Replace
		87945-47060-A1	COVER, OUTER MIRROR, LH	1.00	\$108.60	25.00	\$81.45	Replace	Replace
<b>Total</b>					<b>241.20</b>		<b>180.90</b>		

1,413.97  
+ 800.00  
+ 1190.00  

---

3,403.97