



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2204790
3 ANSON ROAD #16-00	INV Date	03/08/2022
SPRINGLEAF TOWER	Reference	CC6/CTI22000786/Apa3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SJL 8885D
Insured Veh.	PC 4539G
Claim No.	SNM22D200538/C02
Policy No.	DMB1SNW00014662101
Accident Date	20/01/2022
Inspection Date	21/01/2022

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI22000786/Apa3q2 Date: 03/08/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PC 4539G	Veh. Inspected	SJL 8885D
Policy No.	DMB1SNW00014662101	Coverage (\$)	0.00
Claim No.	SNM22D200538/C02	Excess (\$)	0.00
Assign From		Assign Date	21/01/2022
2. Vehicle Particulars & Condition			
Make & Model	mitsubishi LANCER	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JMYSTCY4A9U000574	Colour	WHITE
Odometer	141650 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/01/2022	Inspection Date	21/01/2022
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 8885D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER SIDE HOLDER LH	DAMAGED	42.00	42.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	326.00	-
1	HEADLAMP LH	CUT	1,036.00	1,036.00
1	HEADLAMP LOWER BRACKET LH	NOT NECESSARY	68.00	-
1	FRONT LH FENDER	DENTED	496.00	496.00
1	FRONT LH FENDER INNER SHIELD	DEFORMED	145.00	145.00
1	FRONT LH LOWER ARM	BENT	321.00	321.00
1	FRONT LH KNUCKLE ARM	NOT NECESSARY	35.80	-
1	FRONT LH WHEEL HUB C/W BEARING	DAMAGED	235.00	235.00
1	STEERING RACK AND PINION	NOT NECESSARY	1,828.00	-
	LESS 10% DISCOUNT		-	-227.50
			4,532.80	2,047.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT BUMPER (SN)	DISTORTED	1,500.00	900.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER STICKER WRAP (SN)	NECESSARY	350.00	250.00
1	FRONT BUMPER LOWER SPOILER (SN)	CUT	1,200.00	800.00
1	HEADLAMP OUTER GARNISH LH (SN)	CUT	150.00	80.00
1	FRONT LH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT LH WHEEL RIM (SN)	CUT	820.00	500.00
1	FRONT LH TYRE (SN)	NOT NECESSARY	300.00	-
1	FRONT LH SHOCK ABSORBER (SN)	BENT	600.00	400.00
			4,980.00	2,990.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		800.00	500.00
	SPRAY PAINTING .		800.00	400.00
	WIRING.		50.00	30.00
	TO REMOVE FRONT UNDERCARRIAGE.		350.00	200.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
			2,150.00	1,210.00
	<b>GRAND TOTAL</b>		<b>11,662.80</b>	<b>6,247.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,000.00</b>

Report Ref No. CC6/CTI22000786/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



# LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJL 8885D

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJL 8885D

RE-INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJL 8885D

RE-INSPECTION

