

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 60601**
Date Estimated : **13/01/2022**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Lim Kai Seong
4E Lim Ah Pin Road

Singapore 547853

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ586G	WBA6V12090ED056	27/12/2018	216i Gran Tourer	79211

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
Replace rear boot lid rear bumper includ e remove attachment etc	1,700.00	0.00	1,700.00
Painting rear boot lid and rear bumper	1,731.00	0.00	1,731.00
To replace rear windscreen glass.	574.00	0.00	574.00
To conduct water leak tests.	75.00	0.00	75.00
To check electrical wiring system and lighting at the rear section for proper function.	168.00	0.00	168.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To carry out body cavity preservation. (Per panel).	112.00	0.00	112.00
Sundries.	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,239.35	1.00	0.00	1,239.35
REAR BUMPER PANEL PRIMED (LINES PDC	1,035.00	1.00	0.00	1,035.00
LETTERING 216 I	65.60	1.00	0.00	65.60
GROMMET	0.80	2.00	0.00	1.60
PLAQUE 74MM	72.85	1.00	0.00	72.85
REAR BUMPER TRIM STRIP CHROM	109.40	1.00	0.00	109.40
(DG) CLEANER R1 (100ML)	26.15	1.00	0.00	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	0.00	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML	27.85	1.00	0.00	27.85

SUPPLEMENTARY ITEMS

Total Labour :	4,678.00
Total Parts :	2,840.90
Total Labour & Parts :	7,518.90
Deduction for Excess :	

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Total Repair Costs less Excess:	7,518.90
GST @7%:	526.32
Grand Total :	<u>8,045.22</u>

LOSS OF USE=\$100X5
LTA SEARCH FEE=\$7.45