



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22000350/Gty3e2-1	
			Date: 08/03/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 7771G	Veh. Inspected	SGP 4442P
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/22/22/VC00/025351	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	24/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV 1.5	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JHMRU1810GX200398	Colour	BLUE
	Odometer	80825 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/01/2022	Inspection Date	11/01/2022
	Survey held at	M.S LLH 1, KAKI BUKIT AVENUE 6 #01-67 AUTOBAY@KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	