

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0042/2021/JT
DATE : 17-Jan-22
WIP : 63788

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/2/22**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WONG CHIN WAH
ADDRESS : 81 PASIR RIS GROVE
#07-44
SINGAPORE 518210
TELEPHONE : HP +65 94301556
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900179022-01
VEHICLE NO : **SFU 5183 R**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 31/10/2019
ENGINE NO : CZD 886423
CHASSIS NO : WAUZZZF3XL1013109
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Jan-22
PLACE OF ACCIDENT : SLIP ROAD FROM AIRPORT ROAD
INTO KPE

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFU 5183 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	? ✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESURRISE COOLING SYSTEM, VACUUM AND REGAS.	S/N \$ 1,700.00	✓ ✓
4	TO DISMANTLE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	2500 ✓
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDER.	\$ 4,000.00	1100 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 12,772.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFU 5183 R

ESTIMATED LABOUR CHARGES

S & PRICES

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Regis</i>	1	\$ 2,308.00	<i>✓</i> 858.40
2	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 132.00	<i>✓</i>
3	FRONT BUMPER GRILLE - CENTER ?	1	\$ 242.00	<i>?</i>
4	FRONT BUMPER GRILLE LOWER COVER ?	1	\$ 58.00	<i>?</i>
5	FRONT BUMPER GRILLE - LH / RH <i>new</i>	2	\$ 248.00	<i>✓</i>
6	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 212.00	<i>✓</i>
7	FRONT BUMPER SPOILER <i>new</i>	1	\$ 426.00	<i>✓</i>
8	FRONT BUMPER BRACKET ?	1	\$ 24.00	<i>?</i>
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH ?	2	\$ 342.00	<i>?</i>
10	RADIATOR GRILLE <i>used</i>	1	\$ 1,594.00	<i>✓</i> 1275.2
11	RADIATOR STRIKER PLATE ?	1	\$ 271.00	<i>✓</i> 216.8
12	RADIATOR GRILLE COVER CAP ?	1	\$ 47.00	<i>?</i>
13	RADIATOR BRACKET ?	1	\$ 46.00	<i>?</i> X
14	RADIATOR SECURING PLATE ?	1	\$ 37.00	<i>?</i>
15	FRONT CAMERA ?	1	\$ 1,261.00	<i>?</i> X
16	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 114.00	<i>?</i>
17	FRONT BUMPER REINFORCEMENT BEAM ? BENT	1	\$ 974.00	<i>✓</i> 778.8
18	FRONT BUMPER GRUIDE SECTION - LH / RH <i>new</i>	2	\$ 86.00	<i>+</i>
19	FRONT BUMPER TOP COVER <i>used</i>	1	\$ 137.00	<i>✓</i> 109.6
20	AIR COND STICKER <i>new</i>	1	\$ 9.00	<i>✓</i> 6.54
SUB TOTAL SPARE PARTS		:	\$ 8,568.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFU 5183 R

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	CAUTION STICKER <i>NEW</i> TORN	1	\$ 16.00 ✓	12.40
22	HORN - LH / RH <i>NEW</i>	2	\$ 298.00 ✗	
23	HORN BRACKET - LH / RH <i>NEW</i>	2	\$ 50.00 ✗	
24	FRONT PARKING AID SENSOR <i>NEW</i>	2	TBC	
25	FRONT PARKING AID SENSOR SEAL RING <i>NEW</i>	4	\$ 10.00 ✗	
26	FRONT BUMPER WIRING SET <i>NEW</i>	1	\$ 750.00 ✗	
27	BONNET <i>Dented</i>	1	\$ 3,695.00 ✓	2956.00
28	BONNET HINGE - LH / RH <i>NEW</i>	2	\$ 162.00 ✗	
29	BONNET ATTACHMENT PARTS <i>NEW</i>	1	\$ 309.00 ✗	
30	BONNET STRIKER - LH / RH <i>NEW</i>	2	\$ 246.00 ✗	
31	BONNET IMPACT PROTECTION - CENTER <i>NEW</i>	1	\$ 31.00 ✓	24.24
32	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00 ✗	
33	BONNET SWITCH - LH / RH <i>NEW</i>	2	\$ 455.00 ✗	
34	BONNET RELEASE ELEMENT <i>NEW</i>	1	\$ 65.00 ✗	
35	BONNET RELEASE LEVER <i>NEW</i>	1	\$ 16.00 ✗	
36	BONNET LOCK COVER <i>NEW</i>	1	\$ 11.00 ✗	
37	BONNET LOCK CABLE <i>NEW</i>	1	\$ 82.00 ✗	
38	HEADLIGHT MOUNTING - LH / RH	2	\$ 264.00 ✓	210.4
39	HEADLIGHT - LH / RH	2	\$ 11,904.00 ✓	4761.6
40	LIFT CYLINDER - LH / RH <i>NEW</i>	2	\$ 462.00 ✗	
SUB TOTAL SPARE PARTS		:	\$ 18,890.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFU 5183 R

DAMAGED PARTS & PRICES					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
41	LIFT CYLINDER HOSE <i>new</i>	1	\$ 92.00	+	73.44	
42	LOCK CARRIER <i>cracked</i>	1	\$ 1,412.00	✓	1129.6	
43	A/C CONDENSER ?	1	\$ 569.00	?	454.8	
44	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 9.00	?		
45	ADDITIONAL RADIATOR ?	1	\$ 982.00	?		
46	RADIATOR ?	1	\$ 1,090.00	?		
47	RADIATOR RUBBER BUSH - UPPER <i>new</i>	2	\$ 90.00	+		
48	RADIATOR BUSH - LOWER <i>new</i>	2	\$ 22.00	+		
49	RADIATOR COOLANT <i>new</i>	6	\$ 282.00	✓	225.6	
50	RADIATOR AIR GUIDE - LH / RH ?	2	\$ 86.00	?	68.16	
51	RADIATOR AIR GUIDE - UPPER / LOWER ?	2	\$ 96.00	?	37.84	
52	FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>	2	\$ 520.00	+		
53	FRONT WHEEL HOUSING LINER - ATTACHMENT PARTS <i>new</i>	1	\$ 105.00	+		
54	FRONT WHEEL HOUSING LINER COVER - LH / RH <i>new</i>	2	\$ 36.00	+		
55	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 566.00	✓	452	
56	FRONT NO PLATE <i>dented</i>	S/N	\$ 60.00	✓	60	
57	SUNDRIES ?		\$ 350.00	?	45.48	
TOTAL SPARE PARTS			:	\$ 33,825.00		
TOTAL LABOUR CHARGES			:	\$ 12,772.00		
GRAND TOTAL			:	\$ 46,597.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME OF PARTS & PRICE/DAMAGED PARTS

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Mr. Adam Lim
21/01/22

Not Authorised, OT Pays

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Denise

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

Adrian L.
Resurveyed
H.S.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6842 1183

EMAIL : NORA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFU 5183 R

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	LIFT CYLINDER HOSE <i>new torn</i>	1	\$ 92.00	✓	<i>H.S.</i>
42	LOCK CARRIER <i>crushed</i>	1	\$ 1,412.00	✓	
43	A/C CONDENSER ?	1	\$ 569.00	?	
44	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 9.00	?	
45	ADDITIONAL RADIATOR ?	1	\$ 982.00	?	
46	RADIATOR ?	1	\$ 1,090.00	?	
47	RADIATOR RUBBER BUSH - UPPER <i>new</i>	2	\$ 90.00	+	
48	RADIATOR BUSH - LOWER <i>new</i>	2	\$ 22.00	+	
49	RADIATOR COOLANT <i>new</i>	6	\$ 282.00	✓	
50	RADIATOR AIR GUIDE - LH / RH ?	2	\$ 86.00	?	
51	RADIATOR AIR GUIDE - UPPER / LOWER ?	2	\$ 96.00	?	
52	FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>	2	\$ 520.00	+	
53	FRONT WHEEL HOUSING LINER - ATTACHMENT PARTS <i>new</i>	1	\$ 105.00	+	
54	FRONT WHEEL HOUSING LINER COVER - LH / RH <i>new</i>	2	\$ 36.00	+	
55	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 566.00	✓	
56	FRONT NO PLATE <i>dented</i>	S/N	\$ 60.00	✓	
57	SUNDRIES ?		\$ 350.00	?	
TOTAL SPARE PARTS		:	\$ 33,825.00		
TOTAL LABOUR CHARGES		:	\$ 12,772.00		
GRAND TOTAL		:	\$ 46,597.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

*Adrian Lim,
Resurveyed
H.S.*

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

Revised

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0042/2022/TF

1-Mar-22

Tony

1 of 1

SFU 5183 R

AUDI Q3 1.4 TFSI S TRONIC

Quantity	Description	Unit Price	Amount
Parts			
1	INTAKE AIR GUIDE <i>checked.</i>	\$ 59.00	✓ 46.48
GRAND TOTAL		\$ 59.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
[Signature]

PREMIUM AUTOMOBILES

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFU 5183 R

S/N	NATURE OF JOBS	ESTIMATE / CHARGES	SUR- RECOMM
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. AMS.	S/N \$ 250.00	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESURRISE COOLING SYSTEM, VACUUM AND REGAS	S/N \$ 1,700.00	
4	TO DISMANTLE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDER.	\$ 4,000.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 12,772.00	

250 *AMS*

(Car in)

28/2/22

wip: 63788

Kiam/

PREMIUM AUTOMOBILES

AIG-Adrian

- 7 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFU 5183 R

S/N	PARTS DESCRIPTION	QTY	S/NET	REMARKS
1	FRONT BUMPER <i>delud</i>	1	\$	1073 <i>H.S.</i>
2	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$	
3	FRONT BUMPER GRILLE - CENTER	1	\$	
4	FRONT BUMPER GRILLE LOWER COVER	1	\$	
5	FRONT BUMPER GRILLE - LH / RH	2	\$	
6	FRONT BUMPER CLOSING ELEMENT	1	\$	
7	FRONT BUMPER SPOILER	1	\$	
8	FRONT BUMPER BRACKET	1	\$	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$	
10	RADIATOR GRILLE <i>delud</i>	1	\$	✓ <i>H.S.</i>
11	RADIATOR STRIKER PLATE <i>crushd</i>	1	\$	
12	RADIATOR GRILLE COVER CAP	1	\$	
13	RADIATOR BRACKET	1	\$	
14	RADIATOR SECURING PLATE	1	\$	
15	FRONT CAMERA	1	\$	
16	FRONT BUMPER FOAM FILLER PIECE	1	\$	
17	FRONT BUMPER REINFORCEMENT BEAM	1	\$	
18	FRONT BUMPER CRUISE SECTION - LH / RH	2	\$	
19	FRONT BUMPER TOP COVER <i>delud</i>	1	\$	
20	AIR COND STICKER	1	\$	
SUB TOTAL SPARE PARTS			\$	8,568.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) - APPROVED, REMARKS (X) - NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILE

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SEU 5183 R

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	CAUTION STICKER <i>new</i>	1	5	10.00
22	HORN - LH / RH <i>new</i>	2	5	298.00
23	HORN BRACKET - LH / RH <i>new</i>	2	5	50.00
24	FRONT PARKING AID SENSOR <i>new</i>	2		TBC
25	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	4	5	10.00
26	FRONT BUMPER WIRING SET <i>new</i>	1	5	750.00
27	BONNET <i>new</i>	1	5	1,695.00
28	BONNET HINGE - LH / RH <i>new</i>	2	5	162.00
29	BONNET ATTACHMENT PARTS <i>new</i>	1	5	109.00
30	BONNET STRIKER - LH / RH <i>new</i>	2	5	246.00
31	BONNET IMPACT PROTECTION - CENTER <i>new</i>	1	5	31.00
32	BONNET BOWDEN CABLE - CENTER	1	5	54.00
33	BONNET SWITCH - LH / RH <i>new</i>	2	5	115.00
34	BONNET RELEASE ELEMENT <i>new</i>	1	5	65.00
35	BONNET RELEASE LEVER <i>new</i>	1	5	16.00
36	BONNET LOCK COVER <i>new</i>	1	5	11.00
37	BONNET LOCK CABLE <i>new</i>	1	5	82.00
38	HEADLIGHT MOUNTING (LH / RH) <i>new</i>	2	5	264.00
39	HEADLIGHT (LH / RH) <i>new</i>	2	5	11,904.00
40	LIFT CYLINDER - LH / RH <i>new</i>	2	5	462.00
SUB TOTAL SPARE PARTS			\$	18,890.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 (REMARKS) (X) - APPROVED, REMARKS (X) - NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

✓ *sls*
 5952 *sls*



Order - CT161066
Date: 28 November 2016

TO WHOM IT MAY CONCERN

MAINTENANCE COST FOR ACCIDENT VEHICLE REPAIRING - SEMENJANG ROAD JUST AFTER TRANSIT RD

S/N	PARTS DESCRIPTION	QTY	S/NET	REMARKS
41	LEFT CYLINDER HOSE	1	\$	
42	LOCK CARRIER	1	\$	
43	A/C CONDENSER	1	\$	569 ✓ <i>Replaced.</i>
44	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	
45	ADDITIONAL RADIATOR	1	\$	982.00
46	RADIATOR	1	\$	1,000.00
47	RADIATOR RUBBER BUSH - UPPER	2	\$	90.00
48	RADIATOR BUSH - LOWER	2	\$	22.00
49	RADIATOR COOLANT	6	\$	282.00
50	RADIATOR AIR GUIDE - LH / RH	2	\$	86 ✓ <i>torn</i>
51	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$	96 ✓ <i>torn</i>
52	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	520.00
53	FRONT WHEEL HOUSING LINER - ATTACHMENT PARTS	1	\$	105.00
54	FRONT WHEEL HOUSING LINER COVER - LH / RH	2	\$	48.00
55	FRONT WHEEL ARCH COVER - LH / RH	2	\$	564.00
56	FRONT NO PLATE	S/N	\$	50.00
57	SUNDRIES		\$	350.00
TOTAL SPARE PARTS		:	\$	33,825.00
TOTAL LABOUR CHARGES		:	\$	12,772.00
GRAND TOTAL		:	\$	46,597.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

This is a computer generated invoice. No signature is required.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0042/2021/JT
DATE : 17-Jan-22
WIP : 63788

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

7 days - ok - Jy - 13 Apr 22

OWNER'S NAME : MR WONG CHIN WAH
ADDRESS : 81 PASIR RIS GROVE
#07-44
SINGAPORE 518210
TELEPHONE : HP +65 94301556
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900179022-01
VEHICLE NO : SFU 5183 R
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 31/10/2019
ENGINE NO : CZD 886423
CHASSIS NO : WAUZZZF3XL1013109
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Jan-22
PLACE OF ACCIDENT : SLIP ROAD FROM AIRPORT ROAD
INTO KPE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFU 5183 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	\$	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESURRISE COOLING SYSTEM, VACUUM AND REGAS.	S/N \$	1,700.00	\$	1,700.00
4	TO DISMANTLE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	\$	2,500.00
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDER.	\$	4,000.00	\$	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 12,772.00	\$	6,222.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFU 5183 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,308.00	\$ 858.40
2	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 132.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 242.00	
4	FRONT BUMPER GRILLE LOWER COVER	1	\$ 58.00	
5	FRONT BUMPER GRILLE - LH / RH	2	\$ 248.00	
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00	
7	FRONT BUMPER SPOILER	1	\$ 426.00	
8	FRONT BUMPER BRACKET	1	\$ 24.00	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 342.00	
10	RADIATOR GRILLE	1	\$ 1,594.00	\$ 1,275.20
11	RADIATOR STRIKER PLATE	1	\$ 271.00	\$ 216.80
12	RADIATOR GRILLE COVER CAP	1	\$ 47.00	
13	RADIATOR BRACKET	1	\$ 46.00	
14	RADIATOR SECURING PLATE	1	\$ 37.00	
15	FRONT CAMERA	1	\$ 1,261.00	
16	FRONT BUMPER FOAM FILLER PIECE	1	\$ 114.00	
17	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 974.00	\$ 778.80
18	FRONT BUMPER GRUIDE SECTION - LH / RH	2	\$ 86.00	
19	FRONT BUMPER TOP COVER	1	\$ 137.00	\$ 109.60
20	AIR COND STICKER	1	\$ 9.00	\$ 6.64
SUB TOTAL SPARE PARTS		:	\$ 8,568.00	\$ 3,245.44

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFU 5183 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 3,245.44
21	CAUTION STICKER	1 \$	16.00	\$ 12.40
22	HORN - LH / RH	2 \$	298.00	
23	HORN BRACKET - LH / RH	2 \$	50.00	
24	FRONT PARKING AID SENSOR	2	TBC	
25	FRONT PARKING AID SENSOR SEAL RING	4 \$	10.00	
26	FRONT BUMPER WIRING SET	1 \$	750.00	
27	BONNET	1 \$	3,695.00	\$ 2,956.00
28	BONNET HINGE - LH / RH	2 \$	162.00	
29	BONNET ATTACHMENT PARTS	1 \$	309.00	
30	BONNET STRIKER - LH / RH	2 \$	246.00	
31	BONNET IMPACT PROTECTION - CENTER	1 \$	31.00	\$ 24.24
32	BONNET BOWDEN CABLE - CENTER	1 \$	64.00	
33	BONNET SWITCH - LH / RH	2 \$	455.00	
34	BONNET RELEASE ELEMENT	1 \$	65.00	
35	BONNET RELEASE LEVER	1 \$	16.00	
36	BONNET LOCK COVER	1 \$	11.00	
37	BONET LOCK CABLE	1 \$	82.00	
38	HEADLIGHT MOUNTING - LH / RH	2 \$	264.00	\$ 210.40
39	HEADLIGHT - LH / RH	2 \$	11,904.00	\$ 4,761.60
40	LIFT CYLINDER - LH / RH	2 \$	462.00	
SUB TOTAL SPARE PARTS		:	\$ 18,890.00	\$ 11,210.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFU 5183 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	11,210.08
41	LIFT CYLINDER HOSE	1	\$ 92.00	\$	73.44
42	LOCK CARRIER	1	\$ 1,412.00	\$	1,129.60
43	A/C CONDENSER	1	\$ 569.00	\$	454.80
44	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 9.00		
45	ADDITIONAL RADIATOR	1	\$ 982.00		
46	RADIATOR	1	\$ 1,090.00		
47	RADIATOR RUBBER BUSH - UPPER	2	\$ 90.00		
48	RADIATOR BUSH - LOWER	2	\$ 22.00		
49	RADIATOR COOLANT	6	\$ 282.00	\$	225.60
50	RADIATOR AIR GUIDE - LH / RH	2	\$ 86.00	\$	68.16
51	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 96.00	\$	37.84
52	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 520.00		
53	FRONT WHEEL HOUSING LINER - ATTACHMENT PARTS	1	\$ 105.00		
54	FRONT WHEEL HOUSING LINER COVER - LH / RH	2	\$ 36.00		
55	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 566.00	\$	452.00
56	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
57	SUPPLEMENTARY		\$ 59.00	\$	46.48
58	SUNDRIES		\$ 350.00	\$	20.08
TOTAL SPARE PARTS			\$ 33,884.00	\$	13,778.08
TOTAL LABOUR CHARGES			\$ 12,772.00	\$	6,222.00
GRAND TOTAL			\$ 46,656.00	\$	20,000.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-30/03/22



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0042/2022/TF 01-Mar-22 Tony 1 of 1 SFU 5183 R AUDI Q3 1.4 TFSI S TRONIC	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	INTAKE AIR GUIDE	\$ 59.00	\$	46.48
GRAND TOTAL		\$ 59.00	\$	46.48

For Premium Automobiles Pte Ltd

Authorized Signature