

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD3065C

DATE 20/01/2022 10:20

MAKE HYUNDAI

MVA CHIANG/ CHINA

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR RH DOOR PANEL			\$1,789.90
1	REAR DOOR GEAR/REGULATOR			\$660.90
1	REAR DOOR POWER MOTOR			\$158.60
2	REAR DOOR HINGE UPPER /LOWER		\$123.50	\$247.00
1	REAR DOOR CHECK			\$92.90
1	REAR DOOR TRIM BOARD RH			\$743.80
1	CENTRE DOOR PILLAR			\$1,224.20
1	REAR FENDER RH			\$2,171.40
1	RH ROCKER GARNISH			\$732.80
1	REAR BUMPER BRACKET RH			\$35.60
1	REAR WHEEL CAP RH			\$214.20
	SUB TOTAL			\$8,071.30
	20.00%			\$1,614.26
	DISCOUNTED TOTAL			\$6,457.04
1	FRONT LH DOOR COMFORT LOGO			\$75.00
1	REAR LH DOOR COMFORT APP			\$80.00
				\$155.00
	Labour Charge			
	Panel Beating			\$1,120.00
	Spray Painting Charge			\$800.00
	Transfer Door part			\$60.00
	Remove/refix upholstery rear			\$90.00
	Tuff coat			\$120.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$2,250.00
	ESTIMATE TOTAL			\$8,862.04
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Thevan @ Lkh auto . com
 8223 5769
 21/1/22 1630
 L/S after repair photo
 for 4 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: