

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0049/2022/JT
DATE : 20-Jan-22
WIP : 64112

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/1/22

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/ Windscreen

Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME : MR LIM KHONG SHEE
ADDRESS : BLK 135 SUNSET WAY
#02-08
SINGAPORE 597158
TELEPHONE : HP +65 96380049
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : DMPCSNW00216942100
VEHICLE NO : **SDJ 428 A**
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 16/10/2020
ENGINE NO : DEM 025560
CHASSIS NO : WAUZZZF55MA003252
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Jan-22
PLACE OF ACCIDENT : PURVIS STREET

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDJ 428 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS.	S/N \$	2,200.00	
4	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	
5	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,800.00	
6	TO DISLODGE AND REINSTALL GEARBOX ASSY TO FACILITATE RENEWAL OF GEARBOX MOUNTING.	S/N \$	780.00	
SUB TOTAL LABOUR CHARGES		:	\$ 7,060.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDJ 428 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANNTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS, LHS FRONT DOOR, LHS SILL PANEL TRIM AND RHS HEADLIGHT. TO REPAIR LHS A-PILLAR AND LHS SILL PANEL. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	8,800.00	
8	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDERS, LHS FRONT DOOR, LHS SILL PANEL TRIM, LHS A-PILLAR AND LHS SILL PANEL.	\$	7,800.00	
9	TO RENEW BOTH FRONT RIMS WITH TYRES. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	560.00	
10	TO TOW BACK THE VEHICLE FROM THE ACCIDENT SCENE.	S/N \$	280.00	
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	
TOTAL LABOUR CHARGES		:	\$ 24,884.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 428 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	
2	FRONT BUMPER SECURING STRIP	2	\$ 79.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 293.00	
5	FRONT BUMPER SPOILER	1	\$ 599.00	
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	
9	FRONT BUMPER TRIM - RH	1	\$ 54.00	
10	FRONT BUMPER TRIM - CENTER	1	\$ 127.00	
11	RADIATOR GRILLE	1	\$ 1,881.00	
12	RADIATOR GRILLE COVER	1	\$ 141.00	
13	RADIATOR BRACKET	1	\$ 19.00	
14	RADIATOR SECURING PLATE	1	\$ 12.00	
15	FRONT "360 CAMERA	1	\$ 1,261.00	
16	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00	
17	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
18	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	
19	FRONT BUMPER BRACKET - RH	1	\$ 254.00	
20	FRONT BUMPER TOP COVER	1	\$ 143.00	
SUB TOTAL SPARE PARTS		:	\$ 9,194.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 428 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	"CAUTION" STICKER	1	\$ 16.00	
22	AIR COND STICKER	1	\$ 9.00	
23	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	
24	FRONT BUMPER LOCK CARRIER SUPPORT - LH / RH	2	\$ 64.00	
25	POP RIVET	4	\$ 4.00	
26	FRONT BUMPER PARKING AID SENSOR - INNER / OUTER	3	\$ 488.00	
27	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00	
28	FRONT BUMPER WIRING SET	1	\$ 449.00	
29	HORN - RH	1	\$ 139.00	
30	HORN BRACKET - RH	1	\$ 33.00	
31	FRONT FENDER - LH / RH	2	\$ 2,378.00	
32	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00	
33	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 166.00	
34	FRONT FENDER BRACKET - LH / RH	2	\$ 82.00	
35	POP RIVET	10	\$ 38.00	
36	FRONT FENDER BRACE - LH / RH	2	\$ 264.00	
37	FRONT FENDER BRACKET CENTER - LH / RH	2	\$ 110.00	
38	FRONT FENDER BRACKET CENTER - LH / RH	2	\$ 79.00	
39	FRONT FENDER BRACKET END - LH	1	\$ 65.00	
40	FRONT FENDER CLOSING ELEMENT - LH / RH	1	\$ 37.00	
SUB TOTAL SPARE PARTS		:	\$ 4,640.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 428 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER TRIM - LH / RH	2	\$ 342.00	
42	BONNET	1	\$ 3,491.00	
43	BONNET RETAINING STRIP	3	\$ 5.00	
44	BONNET ATTACHMENT PARTS	1	\$ 128.00	
45	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	
46	BONNET STRIKER - RH	1	\$ 56.00	
47	BONNET LOCK	1	\$ 228.00	
48	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	
49	BONNET RELEASE LEVER	1	\$ 15.00	
50	BONNET BOWDEN CABLE INNER - CENTER	1	\$ 64.00	
51	BONNET RELEASE CABLE COVER	1	\$ 11.00	
52	HEADLIGHHT MATRIX BEAM - RH	1	\$ 8,172.00	
53	HEADLIGHT HOSE - RH	1	\$ 42.00	
54	HEADLIGHT SPACER - RH	3	\$ 136.00	
55	LIFT CYLINDER - RH	1	\$ 217.00	
56	LIFT CYLINDER BRACKET - RH	1	\$ 17.00	
57	LIFT CYLINDER CORRUGATED PIPE - CENTER	1	\$ 107.00	
58	LIFT CYLINDER CORRUGATED PIPE - LH	1	\$ 53.00	
59	LOCK CARRIER	1	\$ 1,127.00	
60	LOCK CARRIER SUPPORT - LH / RH	2	\$ 85.00	
SUB TOTAL SPARE PARTS		:	\$ 14,453.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 428 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	CHARGE AIR COOLER	1	\$ 654.00	
62	AIR COOLER PRESSURE HOSE - RH	1	\$ 413.00	
63	A/C CONDENSER	1	\$ 683.00	
64	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	
65	RADIATOR	1	\$ 1,010.00	
66	RADIATOR FAN RING	1	\$ 291.00	
67	RADIATOR CONTROL UNIT	1	\$ 2,483.00	
68	RADIATOR COOLANT	6	\$ 282.00	
69	RADIATOR AIR GUIDE - RH	1	\$ 36.00	
70	RADIATOR AIR GUIDE INNER - RH	1	\$ 19.00	
71	RADIATOR AIR GUIDE UPPER	1	\$ 19.00	
72	RADIATOR AIR GUIDE LOWER	1	\$ 25.00	
73	INTAKE AIR DUCT - RH	1	\$ 25.00	
74	INTAKE AIR DUCT TOP - RH	1	\$ 61.00	
75	INTAKE HOSE - RH	1	\$ 110.00	
76	AIR FILTER BOX	1	\$ 418.00	
77	AIR MASS METER	1	\$ 627.00	
78	CLAMP	1	\$ 10.00	
79	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 598.00	
80	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 176.00	
SUB TOTAL SPARE PARTS		:	\$ 7,961.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 428 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	FRONT WHEEL SPOILER - LH / RH	2	\$ 164.00	
82	FRONT WHEEL SPOILER TRIM - LH / RH	2	\$ 79.00	
83	STONE CHIP GUARD - LH	1	\$ 57.00	
84	FRONT SPOILER TRIM BRACKET - LH	1	\$ 27.00	
85	NOISE INSULATION	1	\$ 640.00	
86	FRONT DOOR - LH	1	\$ 3,977.00	
87	FRONT DOOR OUTER SEAL - LH	1	\$ 247.00	
88	BONDING AGENT	1	\$ 51.00	
89	CLEANING SOLUTION	1	\$ 74.00	
90	APPLICATOR	1	\$ 8.00	
91	FRONT DOOR CATCH - LH	1	\$ 120.00	
92	FRONT DOOR HINGE UPPER PART - LH LOWER	1	\$ 47.00	
93	FRONT DOOR HINGE HALVES - LH LOWER	1	\$ 45.00	
94	FRONT DOOR TRIM - LH	1	\$ 171.00	
95	A-PILLAR - LH	1	\$ 916.00	
96	FRONT SILL PANEL TRIM ATTACHMENT PARTS - LH	1	\$ 136.00	
97	FRONT SILL PANEL ADHESIVE TAPES - LH	1	\$ 221.00	
98	REAR NOISE INSULATION - CENTER	1	\$ 437.00	
99	UNDERBODY TRIM - LH FRONT	1	\$ 51.00	
100	UNDERBODY TRIM - LH CENTER	1	\$ 376.00	
SUB TOTAL SPARE PARTS		:	\$ 7,844.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 428 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	ALUMINIUM RIM	2	\$ 3,778.00	
102	ASSEMBLY CARRIER	1	\$ 2,096.00	
103	FRONT WISHBONE LINK - LH	1	\$ 605.00	
104	WISHBONE SUSPENSION GUIDE - LH FRONT	1	\$ 1,057.00	
105	WISHBONE GUIDE UPPER - LH FRONT / REAR	2	\$ 1,150.00	
106	WISHBONE WHEEL BEARING HOUSING - LH	1	\$ 1,070.00	
107	WISHBONE SWIVEL JOINT	1	\$ 214.00	
108	WISHBONE WHEEL HUB	1	\$ 498.00	
109	WISHBONE FLANGE DOUBLE BALL BEARING	1	\$ 273.00	
110	SUSPENSION FORKS - LH	1	\$ 293.00	
111	COUPLING ROD	2	\$ 258.00	
112	ANTI-ROLL BAR MARKED GREEN	1	\$ 478.00	
113	GAS SHOCK ABSORBER	1	\$ 342.00	
114	FRONT SPEED SENSOR	1	\$ 129.00	
115	DRIVE SHAFT - LH	1	\$ 2,999.00	
116	TRACK ROD	1	\$ 109.00	
117	TIE ROD END - LH	1	\$ 217.00	
118	STERRING GEAR	1	\$ 7,318.00	
119	GEARBOX SUPPORT	1	\$ 90.00	
120	GEARBOX MOUNTING	1	\$ 235.00	
SUB TOTAL SPARE PARTS		:	\$ 23,209.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 428 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
121	GEARBOX CONSOLE - LH	1	\$ 523.00	
122	GEARBOX GUARD PLATE - LH	1	\$ 35.00	
123	FRONT NO PLATE	S/N	\$ 60.00	
124	BOTH FRONT TYRES	S/N	\$ 550.00	
125	SUNDRIES		\$ 700.00	
TOTAL SPARE PARTS		:	\$ 69,169.00	
TOTAL LABOUR CHARGES		:	\$ 24,884.00	
GRAND TOTAL		:	\$ 94,053.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT