

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408609

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0049/2022/JT
DATE : 20-Jan-22
WIP : 64112

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/1/22

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/ Windscreen

Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME : MR LIM KHONG SHEE
ADDRESS : BLK 135 SUNSET WAY
#02-08
SINGAPORE 597158
TELEPHONE : HP +65 96380049
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : DMPCSNW00216942100
VEHICLE NO : SDJ 428 A
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 16/10/2020
ENGINE NO : DEM 025560
CHASSIS NO : WAUZZZF55MA003252
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Jan-22
PLACE OF ACCIDENT : PURVIS STREET

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6366 1183

EMAIL: NOR & KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDJ 428 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 /	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS.	S/N \$ 2,200.00 ?	
4	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00 /	
5	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,800.00 ?	
6	TO DISLODGE AND REINSTALL GEARBOX ASSY TO FACILITATE RENEWAL OF GEARBOX MOUNTING.	S/N \$ 780.00 ?	
SUB TOTAL LABOUR CHARGES		: \$ 7,060.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAL@PREMIUMAUTO.COM.SG CLAIM@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SOJ 428 A

ESTIMATED LABOUR CHARGES FOR A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS, LHS FRONT DOOR, LHS SILL PANEL TRIM AND RHS HEADLIGHT. TO REPAIR LHS A-PILLAR AND LHS SILL PANEL. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	6 v 800	
7		\$ 8,800.00	4800
8	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDERS, LHS FRONT DOOR, LHS SILL PANEL TRIM, LHS A-PILLAR AND LHS SILL PANEL.	6 x 800 + 100 + 100	5000
9	TO RENEW BOTH FRONT RIMS WITH TYRES. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 560.00	✓
10	TO TOW BACK THE VEHICLE FROM THE ACCIDENT SCENE.	S/N \$ 280.00	✓ Bill
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 24,884.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408692

TEL: 6386 2323 FAX: 6841 1183

EMAIL: NORA.N@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408692

TEL: 6386 2323 FAX: 6841 1183

EMAIL: NORA.N@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ABOUT MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ428 AND LABOUR ESTIMATED LABOUR CHARGES FOR A

PRICES

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>BR</i>	1	\$ 2,493.00	
2	FRONT BUMPER SECURING STRIP <i>MC</i>	1	\$ 79.00	
3	FRONT BUMPER GRILLE - CENTER <i>BR</i>	1	\$ 219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 293.00	
5	FRONT BUMPER SPOILER	1	\$ 599.00	
6	FRONT BUMPER AIR GUIDE - RH <i>CKU</i>	1	\$ 72.00	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>BR</i>	1	\$ 151.00	
9	FRONT BUMPER TRIM - RH <i>CKT</i>	1	\$ 54.00	
10	FRONT BUMPER TRIM - CENTER	1	\$ 127.00	
11	RADIATOR GRILLE <i>BR</i>	1	\$ 1,881.00	
12	RADIATOR GRILLE COVER <i>MC</i>	1	\$ 141.00	
13	RADIATOR BRACKET	1	\$ 19.00	
14	RADIATOR SECURING PLATE	1	\$ 12.00	
15	FRONT "360 CAMERA	1	\$ 1,261.00	
16	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00	
17	FRONT BUMPER REINFORCEMENT BEAM <i>BT</i>	1	\$ 899.00	
18	FRONT BUMPER GUIDE SECTION - RH <i>MC</i>	1	\$ 41.00	
19	FRONT BUMPER BRACKET - RH	1	\$ 254.00	
20	FRONT BUMPER TOP COVER <i>BR</i>	1	\$ 143.00	
SUB TOTAL SPARE PARTS			\$ 9,194.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

65 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6941 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM SG/CLAIMS@PREMIUMAUTO.COM

65 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6941 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM SG/CLAIMS@PREMIUMAUTO.COM

ST. FOR MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 478 / WED LABOUR MATERIAL LISTH 06/06/2014 NO WORK

S/N	PARTS DESCRIPTION	QTY	PRICE/NETT	REMARKS
21	"CAUTION" STICKER ✓ MC	1	\$ 16.00	
22	AIR COND STICKER ✓ MC	1	\$ 9.00	
23	FRONT BUMPER LOCK CARRIER BRACKET ✓ BR	1	\$ 154.00	
24	FRONT BUMPER LOCK CARRIER SUPPORT - LH / RH ✓ MC	2	\$ 64.00	
25	POP RIVET ✓ MC	4	\$ 4.00	
26	FRONT BUMPER PARKING AID SENSOR - INNER / OUTER	2 ✓ MC	\$ 488.00	
27	FRONT PARKING AID SENSOR SEAL RING ✓ MC	4	\$ 10.00	
28	FRONT BUMPER WIRING SET ?	1	\$ 449.00	
29	HORN - RH ?	1	\$ 139.00	
30	HORN BRACKET - RH ?	1	\$ 33.00	
31	FRONT FENDER - LH / RH ✓ MC	2	\$ 2,378.00	
32	FRONT FENDER ATTACHMENT PARTS ?	1	\$ 55.00	
33	FRONT FENDER CLOSING ELEMENT - LH / RH ✓ MC	2	\$ 166.00	
34	FRONT FENDER BRACKET - LH / RH ?	2	\$ 82.00	
35	POP RIVET ✓ MC	10	\$ 38.00	
36	FRONT FENDER BRACE - LH / RH ?	2	\$ 264.00	
37	FRONT FENDER BRACKET CENTER - LH / RH ?	2	\$ 110.00	
38	FRONT FENDER BRACKET CENTER - LH / RH ?	2	\$ 79.00	
39	FRONT FENDER BRACKET END - LH ?	1	\$ 65.00	
40	FRONT FENDER CLOSING ELEMENT - LH / RH ?	1	\$ 37.00	
SUB TOTAL SPARE PARTS		:	\$ 4,640.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1133

EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SD1478A

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER TRIM - LH / RH <i>rec (chnc)</i>	2	\$ 342.00	
42	BONNET <i>DD</i>	1	\$ 3,491.00	
43	BONNET RETAINING STRIP <i>X</i>	3	\$ 5.00	
44	BONNET ATTACHMENT PARTS <i>X</i>	1	\$ 128.00	
45	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>ma (3)</i>	3	\$ 93.00	
46	BONNET STRIKER - RH <i>X</i>	1	\$ 56.00	
47	BONNET LOCK <i>X</i>	1	\$ 228.00	
48	BONNET BOWDEN CABLE - CENTER <i>X</i>	1	\$ 64.00	
49	BONNET RELEASE LEVER <i>X</i>	1	\$ 15.00	
50	BONNET BOWDEN CABLE INNER - CENTER <i>X</i>	1	\$ 64.00	
51	BONNET RELEASE CABLE COVER <i>X</i>	1	\$ 11.00	
52	HEADLIGHT MATRIX BEAM - RH <i>GR</i>	1	\$ 8,172.00	
53	HEADLIGHT HOSE - RH <i>?</i>	1	\$ 42.00	
54	HEADLIGHT SPACER - RH <i>?</i>	3	\$ 136.00	
55	LIFT CYLINDER - RH <i>GR</i>	1	\$ 217.00	
56	LIFT CYLINDER BRACKET - RH <i>GR</i>	1	\$ 17.00	
57	LIFT CYLINDER CORRUGATED PIPE - CENTER <i>?</i>	1	\$ 107.00	
58	LIFT CYLINDER CORRUGATED PIPE - LH <i>?</i>	1	\$ 53.00	
59	LOCK CARRIER <i>?</i>	1	\$ 1,127.00	
60	LOCK CARRIER SUPPORT - LH / RH <i>?</i>	2	\$ 85.00	
SUB TOTAL SPARE PARTS			\$ 14,453.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.NHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

GOOD MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SD4420A

DAMAGED PARTS & PRICES				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
61	CHARGE AIR COOLER ?	1	\$ 654.00		
62	AIR COOLER PRESSURE HOSE - RH ?	1	\$ 413.00		
63	A/C CONDENSER ?	1	\$ 683.00		
64	OUTSIDE TEMPERATURE SENSOR BRACKET ? - 1/2	1	\$ 21.00		
65	RADIATOR ?	1	\$ 1,010.00		
66	RADIATOR FAN RING ?	1	\$ 291.00		
67	RADIATOR CONTROL UNIT ?	1	\$ 2,483.00		
68	RADIATOR COOLANT ?	6	\$ 282.00		
69	RADIATOR AIR GUIDE - RH ?	1	\$ 36.00		
70	RADIATOR AIR GUIDE INNER - RH ?	1	\$ 19.00		
71	RADIATOR AIR GUIDE UPPER ?	1	\$ 19.00		
72	RADIATOR AIR GUIDE LOWER ?	1	\$ 25.00		
73	INTAKE AIR DUCT - RH ?	1	\$ 25.00		
74	INTAKE AIR DUCT TOP - RH ?	1	\$ 61.00		
75	INTAKE HOSE - RH ?	1	\$ 110.00		
76	AIR FILTER BOX ?	1	\$ 418.00		
77	AIR MASS METER ?	1	\$ 627.00		
78	CLAMP ?	1	\$ 10.00		
79	FRONT WHEEL HOUSING LINER - LH / RH ✓ TN	2	\$ 598.00		
80	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?	1	\$ 176.00		
SUB TOTAL SPARE PARTS			\$ 7,961.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHA@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

PREMIUM AUTOMOBILES

FOR MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDJ 423 A

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	FRONT WHEEL SPOILER - LH / RH <i>OK</i>	(2)	\$	164.00
82	FRONT WHEEL SPOILER TRIM - LH / RH <i>X</i>	2	\$	79.00
83	STONE CHIP GUARD - LH <i>MC</i>	1	\$	57.00
84	FRONT SPOILER TRIM BRACKET - LH <i>?</i>	1	\$	27.00
85	NOISE INSULATION <i>?</i>	1	\$	640.00
86	FRONT DOOR - LH <i>OK</i>	1	\$	3,977.00
87	FRONT DOOR OUTER SEAL - LH <i>MC</i>	1	\$	247.00
88	BONDING AGENT <i>MC</i>	1	\$	51.00
89	CLEANING SOLUTION <i>MC</i>	1	\$	74.00
90	APPLICATOR <i>X</i>	1	\$	8.00
91	FRONT DOOR CATCH - LH <i>?</i>	1	\$	120.00
92	FRONT DOOR HINGE UPPER PART - LH LOWER <i>?</i>	1	\$	47.00
93	FRONT DOOR HINGE HALVES - LH LOWER <i>?</i>	1	\$	45.00
94	FRONT DOOR TRIM - LH <i>MC (chiru)</i>	1	\$	171.00
95	A-PILLAR - LH <i>?</i>	1	\$	916.00
96	FRONT SILL PANEL TRIM ATTACHMENT PARTS - LH <i>MC</i>	1	\$	136.00
97	FRONT SILL PANEL ADHESIVE TAPES - LH <i>MC</i>	1	\$	221.00
98	REAR NOISE INSULATION - CENTER <i>?</i>	1	\$	437.00
99	UNDERBODY TRIM - LH FRONT <i>?</i>	1	\$	51.00
100	UNDERBODY TRIM - LH CENTER <i>?</i>	1	\$	376.00
SUB TOTAL SPARE PARTS		:	\$	7,844.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408693

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



STOCK MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO: SDJ 428 AL

PARTS & DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
-----	-------------------	-----	--------	---------

121	GEARBOX CONSOLE - LH	1	\$ 523.00	
122	GEARBOX GUARD PLATE - LH	1	\$ 35.00	
123	FRONT NO PLATE	S/N	\$ 60.00	
124	BOTH FRONT TYRES	S/N	\$ 550.00	
125	SUNDRIES		\$ 700.00	

TOTAL SPARE PARTS	:	\$ 69,169.00
TOTAL LABOUR CHARGES	:	\$ 24,884.00
GRAND TOTAL	:	\$ 94,053.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES PTE LTD



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6941 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Steve (LKK)
24/1/12 3:27 PM

JD-MAL
EXCESS - ?
PIP

~ BL L
12 dys

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT