



**Auto Insure Pte. Ltd.**  
6 Marsiling Lane  
Singapore (739145)  
E: claims01@autoinsure.com.sg  
W: www.autoinsure.com.sg  
T: 3157 2626 F: 6368 0081  
**GST No.: 201437380M**

**Page No.1**

**AUTOMOBILE ASSESSMENT REPORT**

Our Ref: **SJW7831H (SIEW)**

Date: **21-Jan-22**

BY EMAIL ONLY  
(claims01@autoinsure.com.sg)

**ATTENTION: MOTOR CLAIMS DEPT**

**Allianz Insurance Singapore Pte. Ltd**

79 Robinson Road  
#09-01,  
Singapore 068897

**Assessed Vehicle No : SJW7831H**  
**Car Make and Model : KIA CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR**  
**Date of Accident : 18-Jan-22**  
**Date of Assessment : 21-Jan-22**

We have carried out a physical assessment of SJW7831H at our workshop Auto Insure Pte Ltd sustained damages to the FRONT RH portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the FRONT RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **P/P**  
Adjusted Amount : **\$ 11,714.68**  
Est. Repair Days : **9**



Pursuant to your instruction, we have **AUTHORIZED to** repair.  
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

**AUTO INSURE PTE. LTD.** For any reliance on this report by any third party.

Our Ref: **SJW7831H**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
		<b><u>PARTS REPLACEMENT - LIST ITEMS</u></b>		
1	1	FRONT WINDSCREEN		\$ 400.00
2	1	FRONT WINDSCREEN MOULDING		\$ 40.00
3	1	FRONT WIPER GARNISH SIDE COVER RH		\$ 8.00
4	1	BONNET		\$ 625.00
5	1	BONNET HINGE RH		\$ 20.00
6	1	BONNET HINGE LH		\$ 20.00
7	1	HEADLAMP RH		\$ 265.00
8	1	HEADLAMP LOWER BRACKET RH		\$ 18.00
9	1	FRONT GRILLE		\$ 145.00
10	1	FRONT GRILLE LOGO KIA		\$ 35.00
11	1	FRONT BUMPER		\$ 290.00
12	1	FRONT BUMPER FOG LAMP RH		\$ 70.00
13	1	FRONT BUMPER FOG LAMP LH		\$ 70.00
14	1	FRONT BUMPER FOG LAMP COVER RH		\$ 18.00
15	1	FRONT BUMPER FOG LAMP COVER LH		\$ 18.00
16	1	FRONT BUMPER LOWER GRILLE		\$ 25.00
17	1	FRONT BUMPER SPONGE		\$ 45.00
18	1	FRONT BUMPER SIDE RETAINER RH		\$ 10.00
19	1	FRONT BUMPER SIDE RETAINER LH		\$ 10.00
20	1	FRONT SUPPORT PANEL		\$ 235.00
21	1	FRONT BUMPER LOWER LIPS		\$ 40.00
22	1	FRONT BUMPER LOWER COVER		\$ 20.00
23	1	WIPER TANK		\$ 30.00
24	1	FRONT WIPER MOTOR HOSE		\$ 36.00
25	1	FRONT FENDER RH		\$ 190.00
26	1	FRONT FENDER INNER SHIELD RH		\$ 35.00
27	1	FRONT FENDER LH		REPAIR
28	1	FRONT FENDER INNER SHIELD LH		\$ 35.00
29	1	FRONT WHEEL HOUSE RH		REPAIR
30	1	FRONT PILLAR RH		REPAIR
31	1	FRONT DOOR RH		REPAIR

32	1	FRONT AIR BAG SENSOR RH		\$	66.00
33	1	FRONT AIR BAG SENSOR LH		\$	66.00
34	1	DRIVER SIDE AIR BAG		\$	780.00
35	1	AIR BAG CLOCK SPRING		\$	110.00
36	1	AIR BAG ECU		\$	480.00
37	1	FRONT SEAT BELT RH		\$	340.00
38	1	CENTRE PILLAR UPPER TRIM RH		\$	40.00
39	1	CENTRE PILLAR LOWER TRIM RH		\$	70.00
40	1	FRONT SEAT BELT LH		\$	340.00
41	1	CENTRE PILLAR UPPER TRIM LH		\$	40.00
42	1	CENTRE PILLAR LOWER TRIM LH		\$	70.00
43	1	FRONT WHEEL RIM RH		\$	480.00
44	1	FRONT ABSORBER RH		\$	150.00
45	1	FRONT ABSORBER MOUNTING RH		\$	48.00
46	1	FRONT KNUCKLE RH		\$	160.00
47	1	FRONT KNUCKLE BEARING RH		\$	70.00
48	1	FRONT STABILIZER LINK ROD RH		\$	35.00
49	1	STEERING TIE ROD RH		\$	45.00
50	1	STEERING TIE ROD END RH		\$	45.00
51	1	STEERING RACK		CHECK PRICES	
52	1	FRONT DRIVESHAFT RH		\$	480.00
53	1	FRONT LOWER ARM RH		\$	135.00
54	1	FRONT SUBFRAME		\$	550.00
			SUB TOTAL	\$	7,353.00
			MARGIN 10%	\$	735.30
			TOTAL AMOUNT	\$	8,088.30

Our Ref: **SJW7831H**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT WINDSCREEN SEALANT		\$ 80.00
	1	FRONT BUMPER CLIPS		\$ 60.00
2	1	FRONT NUMBER PLATE & HOLDER		\$ 60.00
3	2	FRONT FENDER INNER SHIELD CLIPS RH & LH		\$ 50.00
4	1	RADIATOR COOLANT		\$ 60.00
			SUB TOTAL	\$ 310.00
			TOTAL PARTS COST	\$ 8,398.30

Our Ref: **SJW7831H**

S/NO	DESCRIPTION	EST. BY WORKSHOP
	<b><u>LABOUR &amp; PAINTWORK</u></b>	
1	REMOVE, REFIX AND REPAIR AFFECTED DAMAGED PARTS	\$ 1,000.00
2	TO REMOVE & REFIT FRONT WINDSCREEN	\$ 120.00
3	SIMPLE WIRING	\$ 20.00
4	TO REMOVE & REFIT AIR CON CONDENSER, PIPES & VACUUM, INCLUDING RECHARGING GAS	\$ 100.00
5	ANTI RUST COATING	\$ 50.00
6	PAINT MATERIALS PER PANEL	\$ 1,200.00
7	SUNDRIES	\$ 60.00
TOTAL BEFORE GST		\$ 10,948.30
LESS EXCESS		\$ -
TOTAL BEFORE GST		\$ 10,948.30
7% GST		\$ 766.38
TOTAL REPAIR COST		<b>\$ 11,714.68</b>

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

**\*\*This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.**

**\*\*\*On a separate note, please let us have your authorize repair confirmation and/or approval for the above OD case in your next reply.**

Yours Faithfully,

Jason Heng  
Claims Director