

Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Thursday, 6 October 2022 7:35 PM
To: AutoInsure (Claims); Huey Yon (LKKAUTO)
Cc: SUR
Subject: RE: SJW7831H OD AIS
Attachments: SJW 7831-Supp.pdf

Dear Sir,

Please proceed the supplementary as attached with our surveyor marking.

Best Regards,

Celine Fong on behalf of Huey Yon

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Wednesday, 26 January 2022 10:14 AM
To: AutoInsure (Claims) <claims01@autoinsure.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SJW7831H OD AIS

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJW7831H (Excess \$600/-). LUMP SUM REPAIR**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)