

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMK3563K
Tarkun

at Workshop m/s

of

Insured:

SGU 6201D

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$70k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

08664

Vehicle: IN / OUT

Date:

Person Contacted:

LTN 626311

Date / Time

Action / Instruction

CNY 1-2-22

21/2/22 4/5 @ 6200 returned willian

Veh No:

SMK3563K

Yr Regn:

05/04/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA1

Make:

Honda Shuttle

c.c

1496

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp Reading

64945

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK8200 1459

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

7

Rear

7

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

23/1/22

D.O.I.

24/1/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

not Authorized
Name

Morris

24/1/22

L/s \$6200
6 days

cec'lie



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SGU6201D
Date of Accident : 23 January 2022

Messrs VIVI AUTO TRADING

Date : 25 January 2022

Estimate To Repair SMK3563K - Honda SHUTTLE 1.5G CVT
Chassis No : GK82001459

S/No	Quantity	Description	Amount	
<u>LIST ITEMS</u>				
DIS 01	1 pc	rear bumper	\$ 1,150.60	✓
nei 02	12 ps / set	rear bumper clips @ \$3.80	\$ 45.60	✓
Re 03	1 pc	rear bumper tow cover	\$ 18.80	✓
11 04	2 ps	rear bumper reflector @ \$45.00	\$ 90.00	X
o/s twi 05	2 ps	rear bumper reflector cover @ \$45.00	\$ 90.00	1 pc
11 06	2 ps	rear bumper bracket @ \$23.50	\$ 47.00	X
Body 07	1 pc	tailgate assy	\$ 1,193.00	✓
Swf 08	1 pc	tailgate lock	\$ 256.00	✓
11 09	1 pc	tailgate outer chrome moulding	\$ 383.00	X
o/s cre 10	2 ps	tailgate reflector @ \$395.00	\$ 790.00	1 pc
11 11	1 pc	tailgate logo	\$ 38.00	X
nei 12	1 pc	tailgate shuttle emblem	\$ 55.00	✓
Torn 13	1 pc	tailgate inner trim board	\$ 220.00	✓
11 14	1 pc	tailgate keyless switch antenna	\$ 58.00	X
11 15	2 ps	tailgate hinge @ \$50.00	\$ 100.00	X
11 16	2 ps	tailgate damper @ \$165.00	\$ 330.00	X
twi 17	1 pc	tailgate weatherstrip	\$ 168.50	✓
o/s cre 18	2 ps	taillamp @ \$520.50	\$ 1,041.00	1 pc
11 19	4 ps	taillamp clips @ \$5.00	\$ 20.00	X
Body 20	1 pc	rear end panel	\$ 601.50	✓
DIS 21	1 pc	rear end panel top garnish	\$ 155.50	✓
NS 22	1 pc	rear end panel buzzer	\$ 85.50	X
crumpled 23	1 pc	floor panel	\$ 1,180.00	✓
Swf 24	1 pc	floor wooden board	\$ 585.00	X
DIS 25	1 pc	tools compartment	\$ 285.00	✓
DIS 26	1 pc	rear fender inner trim board o/s	\$ 489.60	✓
nei 27	2 ps	rear windscreen moulding @ \$28.00	\$ 56.00	✓
Less 20 %			\$ 9,532.60	
			\$ 1,906.52	
			\$ 7,626.08	
<u>SPECIAL NETT ITEMS</u>				
NS 28	2 ps	rear windscreen moulding - top @ \$56.50	\$ 113.00	X
Swf 29	1 pc	rear number plate	\$ 50.00	X
nei 30	1 pc	rear windscreen primer	\$ 50.00	40
nei 31	1 pc	rear windscreen sealant	\$ 60.00	40
11 32	1 pc	insulation padding	\$ 180.00	X



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SGU6201D

Date of Accident : 23 January 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs VIVI AUTO TRADING

Date : 25 January 2022

Estimate To Repair SMK3563K - Honda SHUTTLE 1.5G CVT

Chassis No : GK82001459

S/No	Quantity	Description	Amount
<u>SPECIAL NETT ITEMS</u>			
33	1 pc Set	parking sensor	\$ 250.00
			\$ 703.00
<u>LABOUR & MISC. CHARGES</u>			
01		To remove upholstery	\$ 200.00
02		To rust-proofing of the affected areas.	\$ 300.00
03		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 350.00
04		To reinstall of rear bumper parking sensor.	\$ 100.00
05		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00
06		To remove and refit rear windscreen glass.	\$ 140.00
07		To check electrical lighting concerned.	\$ 100.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,500.00
09		Putty and spray painting of the affected portion.	\$ 1,400.00
			\$ 4,210.00
		Total	\$ 12,539.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

P - 6232.60
202
P - 4986.08
S.N - 280.00
L - 2530.00
7796.08
202
1236