

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22000809/Aqf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	05/05/2022	
			Code:	AGI	
1.					
	Insured Veh.	SLA 7090X	Veh. Inspected	SMQ 1066K	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10013541/EE	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	24/01/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	MR053REH104556965	Colour	WHITE	
	Odometer	167693 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
	L/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
	R/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
	L/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/01/2022	Inspection Date	24/01/2022	
	Survey held at	MG SOLUTION PTE LTD			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

**8 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: