



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000810/Uvf3n2	
			Date: 23/02/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	FBM 3894A	Veh. Inspected	SJL 4519M
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200314/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	24/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	KIA CARENS (A)	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KNAHU815VJ7205590	Colour	BROWN
	Odometer	38604 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	YOKOHAMA	7 mm
	L/H Front Tyre	225/45 R17	YOKOHAMA	7 mm
	R/H Rear Tyre	225/45 R17	YOKOHAMA	7 mm
	L/H Rear Tyre	225/45 R17	YOKOHAMA	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	24/01/2022	Inspection Date	24/01/2022
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	