

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SJL 4579M  
 at Workshop m/s Rp.  
 of FBM 3894A  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. CMTD2200314/THE  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$76k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: LIA \$ 40820 Vehicle: IN / OUT

Veh No: SJL 4579M Yr Regn: 13/6/18  
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA  
 Make: KIA Carens c.c. 1685  
 Colour: Brown A/C: Insured / Std / NI / NA  
 Sp. Reading: 38604 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KNAH0815VJ\*7205590  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: \_\_\_\_\_ R: 225/45 R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front R/Bal. 7 mm Rear R/Bal. 7 mm  
 L/Bal. 7 mm L/Bal. 7 mm  
 D.O.A. 24/1/22 D.O.I. 24/1/22  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
See n/s  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Deplok.  
21/2/22 HS \$5200 informed Alan. (Red 9897, 65%)  
CNY 1-2-22 hang G.A

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 5  
 Resurvey No. of Trip: 2

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) 22/2/22-typist

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 ) \_\_\_ S + RS, \_\_\_ SI  
 ) Photos  
 ) Others  
 )  
 TOTAL

Report Format : TP  
 Lump Sum / +B+ (\$ 5200 )

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	439H
<b>Vehicle Details</b>	
Vehicle No.:	SJL4519M
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jan 2022
Vehicle Make:	KIA
Vehicle Model:	CARENS 1.7 DCT DIESEL 5DR FWD
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	D4FDJH551776
Chassis No.:	KNAHU815VJ7205590
Maximum Power Output:	104.0 kW (139 bhp)
Open Market Value:	\$21,888.00
Original Registration Date:	13 Jun 2018
First Registration Date:	13 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$22,644.00 11322
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2028
PARF Rebate Amount:	\$16,983.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,389.00
COE Rebate Amount:	\$23,837.00
<b>Total Rebate Amount:</b>	<b>\$40,820.00</b>

The information contained herein is correct as at 24 Jan 2022

OK

**FASTECH AUTO PTE LTD**  
 1 Kaki Bukit Ave 6 #01-48 Autobay  
 Singapore 417883  
 Tel No: 67452063/ 67467158 Fax No: 67458520  
 Tax Reg No : 200006262D

Not Approved  
 24/1/22  
 H/S \$ 5200  
 5 days.

VEHICLE NO: SJL 4519M

NETT ITEM

1PC	REAR WINDSCREEN	11		\$905.00 X
1PC	REAR WINDSCREEN MOULDING	neu	60.80	\$182.00 /
1PC	TAILGATE	Body ID	1218	\$1,715.00 /
1PC	TAILGATE REAR LOGO	neu		\$68.00 /
1PC	REAR TAILGATE C&C LOGO	neu		\$50.00 /
1PC	TAILGATE 'CAREN' EMBLEM	neu	52	\$62.00 /
1PC	TAILGATE 'CRDI' EMBLEM	neu	60	\$80.00 /
1PC	TAILGATE INNER LOCK	11		\$295.00 X
1PC	TAILGATE WEATHERSTRIP	11		\$211.00 X
1PC	TAILGATE REFLECTOR N/S	CRG SVC		\$680.00 X
1PC	REAR BUMPER	Dis	605	\$875.00 /
1PC	REAR BUMPER BOTTOM	Dis	245	\$615.00 /
1PC	REAR BUMPER DIFFUSER	Torn	180	\$305.00 /
1PC	REAR BUMPER REFLECTOR N/S	320	142	\$182.00 /
1PC	REAR BUMPER REINFORCEMENT	CRG	341	\$685.00 /
1PC	REAR BUMPER REINFORCEMENT BRACKET N/S	twi	95	\$220.00 /
1PC	REAR BUMPER PDC SENSOR	shorted	168	\$188.00 /
1PC	REAR BUMPER SIDE HOLDER N/S	sent		\$68.00 /
1PC	REAR BUMPER LOWER COVER N/S	Torn	92.50	\$102.00 /
1SET	REAR BUMPER LOWER COVER CLIPS N/S	neu		\$45.00 /
1PC	REAR BUMPER SPLASH SHIELD N/S	Dis	135.00	\$215.00 /
1PC	TAILLAMP N/S	CRG		\$895.00 /
1PC	REAR END PANEL	100	10%	\$755.00 /
1PC	REAR END PANEL TOP GARNISH	11		\$302.00 X
1PC	REAR FENDER N/S	R		\$1,587.00 X
				\$11,287.00

S.NETT ITEM

1PC	REAR WINDSCREEN SEALANT	neu		\$50.00 40
1PC	REAR WINDSCREEN INNER SEAL	neu		\$50.00 40
1PC	REAR END PANEL SEALANT	neu		\$50.00 ✓
1PC	REAR FLOOR PANEL SEALANT	11		\$80.00 X
	TO CHECK WIRING			\$50.00 20
	TO DISMANTLE & REPLACED REAR PDC SENSOR			\$80.00 50
	TO DISMANTLE & REPLACED REAR WINDSCREEN			\$150.00 120
	TO DISMANTLE & REFIX TAILGATE MECHANISM			\$100.00 60

TO DISMANTLE & REFIX CUSHION UPHOLSTERY  
TO RESET & REPROGRAMME SYSTEM  
TO SPRAY RUST PROOFING  
LABOUR FOR PANEL BEATING & REPLACED PARTS  
TO PUTTY & SPRAY PAINTING

\$120.00 80  
\$180.00 50  
\$120.00 60  
\$1,280.00 800  
\$1,500.00 1000  
TOTAL \$15,097.00

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4593-30  
102  
P-4133-97  
S.N-130  
L-2240  
6503.97  
202  
5703