

ASS. REC. BY:

REF:

C12/22000814/1/cg43

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. SNM220700547/002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 810816

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 70 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PMV 59374 Yr Regn: 12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagenMake: Volkswagen Tiguan c.c. 1395Colour: White A/C: Insured / Std / NI / NASp. Reading: 02043 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG 8885 N8 JW 973840Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 235/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 2011/122 D.O.I. 24/1/2022Survey held at ✓Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or& Br

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got BI, Bonnet jammed.

4/3 11pm @ 14,000 Cahr 9/3/22 Crad @ 70768.20, 68%.

14/3/22 @ 5.17pm revised to Adeline Chang via Newman.

Date/Time, File Pass to?

☐

: Prell. Report

1) 14/3 11pm

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 10Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format:

Lump Sum / L.B.I. (\$)

Mer TP
14000

S THREE AUTOMOTIVE RECOVERY PTE LTD

Blk 8 Sin Ming Industrial Estate

#01-64/66 Singapore 575643

Tel : 6284 1542 / 6284 1575

Fax : 6487 5315

sthreeautomotive@gmail.com

Not Notwithstanding
11 Pm @ 14,000h
Recovery After Pain
10 days

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : YN6371C

ESTIMATE REPORT 1st QUOTATION

OWNER'S PARTICULAR

NAME : ER KOK KHOON ALDRICH

ADDRESS :

LICENSE NO. SMV5937U TRANS. :

MAKE / MODEL : VW TIGUAN

OWNER'S INSURER DIRECT ASIA

JOB-CODE : TP S/A : JOEY

JOB NO. :

CONTACT : 83382828

CHASSIS NO. :

ENGINE NO. :

ACCIDENT DATE : 20-Jan-21

Link Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	%	PRICE	DISC	DISC	SUR	REV. PRICE
1 FRONT BUMPER	1.00	\$ 1,475.00	10.00	\$ 1,327.50	Y			1132.50
2 FRONT BUMPER SIDE RETAINER LH	1.00	\$ 60.00	10.00	\$ 54.00	Y			
3 FRONT BUMPER SIDE RETAINER RH	1.00	\$ 60.00	10.00	\$ 54.00	Y			
4 FRONT BUMPER BRACKET LH	1.00	\$ 45.00	10.00	\$ 40.50	Y			
5 FRONT BUMPER BRACKET RH	1.00	\$ 45.00	10.00	\$ 40.50	Y			
6 FRONT BUMPER TOWING COVER	1.00	\$ 180.00	10.00	\$ 162.00	Y			
7 FRONT BUMPER FOG LAMP LH	1.00	\$ 250.00	10.00	\$ 225.00	Y			
8 FRONT BUMPER FOG LAMP RH	1.00	\$ 250.00	10.00	\$ 225.00	Y			
9 FRONT BUMPER FOGLAMP COVER LH	1.00	\$ 95.00	10.00	\$ 85.50	Y			
10 FRONT BUMPER FOGLAMP COVER RH	1.00	\$ 95.00	10.00	\$ 85.50	Y			
11 FRONT BUMPER LOWER CENTRE GRILLE	1.00	\$ 240.00	10.00	\$ 216.00	Y			
12 FRONT BUMPER REINFORCEMENT UPPER	1.00	\$ 650.00	10.00	\$ 585.00	Y			366.10
13 FRONT BUMPER REINFORCEMENT LOWER	1.00	\$ 270.00	10.00	\$ 243.00	Y			
14 FRONT GRILLE ASSY (WITH LOGO)	1.00	\$ 490.00	10.00	\$ 441.00	Y			
15 FRONT BONNET	1.00	\$ 1,065.00	10.00	\$ 958.50	Y			
16 FRONT BONNET SIDE RUBBER SEAL LH	1.00	\$ 30.00	10.00	\$ 27.00	Y			
17 FRONT BONNET SIDE RUBBER SEAL RH	1.00	\$ 30.00	10.00	\$ 27.00	Y			
18 FRONT BONNET INSULATOR	1.00	\$ 380.00	10.00	\$ 342.00	Y			
19 FRONT BONNET LOCK ASSY	1.00	\$ 185.00	10.00	\$ 166.50	Y			
20 FRONT BONNET HINGE LH	1.00	\$ 230.00	10.00	\$ 207.00	Y			
21 FRONT BONNET HINGE RH	1.00	\$ 230.00	10.00	\$ 207.00	Y			
22 FRONT BONNET LOCK CATCH	1.00	\$ 105.00	10.00	\$ 94.50	Y			
23 FRONT HEADLAMP ASSY LH HID	1.00	\$ 1,880.00	10.00	\$ 1,692.00	Y			
24 FRONT HEADLAMP ASSY RH HID	1.00	\$ 1,880.00	10.00	\$ 1,692.00	Y			
25 FRONT HEADLAMP LOWER BRACKET RH	1.00	\$ 25.00	10.00	\$ 22.50	Y			
26 FRONT HEADLAMP LOWER BRACKET LH	1.00	\$ 25.00	10.00	\$ 22.50	Y			

27	FRONT HEADLAMP HID BULB LH	1.00	\$	300.00	10.00	\$	270.00	Y	X
28	FRONT HEADLAMP HID BULB RH	1.00	\$	300.00	10.00	\$	270.00	Y	X
29	FRONT SUPPORT PANEL ASSY 902	1.00	\$	990.00	10.00	\$	891.00	Y	✓
30	FRONT SUPPORT PANEL TOP GARNISH 310	1.00	\$	770.00	10.00	\$	693.00	Y	✓
31	FRONT BRACE PANEL	1.00	\$	300.00	10.00	\$	270.00	Y	✓
32	FRONT FENDER LH	1.00	\$	650.00	10.00	\$	585.00	Y	X
33	FRONT FENDER RH	1.00	\$	650.00	10.00	\$	585.00	Y	X
34	FRONT FENDER INNER SHIELD LH	1.00	\$	130.00	10.00	\$	117.00	Y	X
35	FRONT FENDER INNER SHIELD RH	1.00	\$	130.00	10.00	\$	117.00	Y	X
36	FRONT FENDER WHEELARCH GARNISH LH	1.00	\$	280.00	10.00	\$	252.00	Y	✓
37	FRONT FENDER WHEELARCH GARNISH RH	1.00	\$	280.00	10.00	\$	252.00	Y	✓
38	FRONT DOOR LOWER GARNISH LH	1.00	\$	270.00	10.00	\$	243.00	Y	✓
39	FRONT DOOR LOWER GARNISH RH	1.00	\$	270.00	10.00	\$	243.00	Y	✓
40	RADIATOR ASSY	1.00	\$	390.00	10.00	\$	351.00	Y	✓
41	RADIATOR FAN ASSY 1210	1.00	\$	1,330.00	10.00	\$	1,197.00	Y	✓
42	RADIATOR TOP HOSE	1.00	\$	247.00	10.00	\$	222.30	Y	X
43	AC CONDENSOR ASSY 615	1.00	\$	810.00	10.00	\$	729.00	Y	✓
44	AC FAN ASSY	1.00	\$	1,230.00	10.00	\$	1,107.00	Y	✓
45	WIPER TANK	1.00	\$	180.00	10.00	\$	162.00	Y	X
46	REAR BUMPER TOP 1345.60	1.00	\$	1,520.00	10.00	\$	1,368.00	Y	✓
47	REAR BUMPER CENTRE	1.00	\$	230.00	10.00	\$	207.00	Y	✓
48	REAR BUMPER LOWER	1.00	\$	450.00	10.00	\$	405.00	Y	✓
49	REAR BUMPER SIDE CHROME MOULDING LH	1.00	\$	195.00	10.00	\$	175.50	Y	✓
50	REAR BUMPER SIDE CHROME MOULDING RH	1.00	\$	195.00	10.00	\$	175.50	Y	✓
51	REAR BUMPER CENTRE CHROME MOULDING	1.00	\$	255.00	10.00	\$	229.50	Y	✓
52	REAR BUMPER REFLECTOR SMALL LH	1.00	\$	65.00	10.00	\$	58.50	Y	X
53	REAR BUMPER REFLECTOR SMALL RH	1.00	\$	65.00	10.00	\$	58.50	Y	X
54	REAR BUMPER REFLECTOR BIG LH	1.00	\$	65.00	10.00	\$	58.50	Y	✓
55	REAR BUMPER REFLECTOR BIG RH	1.00	\$	65.00	10.00	\$	58.50	Y	X
56	REAR BUMPER RETAINER LH	1.00	\$	45.00	10.00	\$	40.50	Y	X
57	REAR BUMPER RETAINER RH	1.00	\$	45.00	10.00	\$	40.50	Y	X
58	REAR BUMPER BRACKET LH	1.00	\$	45.00	10.00	\$	40.50	Y	✓
59	REAR BUMPER BRACKET RH	1.00	\$	45.00	10.00	\$	40.50	Y	✓
60	REAR BUMPER REINFORCEMENT 450	1.00	\$	480.00	10.00	\$	432.00	Y	✓
61	REAR BUMPER SPONGE	1.00	\$	280.00	10.00	\$	252.00	Y	✓
62	REAR BUMPER TOWING COVER	1.00	\$	36.00	10.00	\$	32.40	Y	✓
63	REAR END PANEL	1.00	\$	530.00	10.00	\$	477.00	Y	✓

64	REAR END PANEL GARNISH	<i>Sn</i>	1.00	\$	330.00	10.00	\$	297.00	Y	<i>X</i>
65	REAR BUMPER LOWER COVER	<i>Rd</i>	1.00	\$	320.00	10.00	\$	288.00	Y	<i>✓</i>
66	TAILGATE <i>1552.30</i>	<i>By</i>	1.00	\$	2,490.00	10.00	\$	2,241.00	Y	<i>✓</i>
67	TAILGATE EMBLEM TIGUAN	<i>na</i>	1.00	\$	120.00	10.00	\$	108.00	Y	<i>✓</i>
68	TAILGATE LOGO	<i>na</i>	1.00	\$	130.00	10.00	\$	117.00	Y	<i>✓</i>
69	TAILGATE RUBBER BEARING	<i>Sn</i>	1.00	\$	240.00	10.00	\$	216.00	Y	<i>X</i>
70	TAILGATE INNER TRIMBOARD	<i>Sn</i>	1.00	\$	380.00	10.00	\$	342.00	Y	<i>X</i>
71	REAR NO.PLATE LAMP LH	<i>Sn</i> <i>Sn</i>	1.00	\$	90.00	10.00	\$	81.00	Y	<i>X</i>
72	REAR NO.PLATE LAMP RH	<i>Sn</i> <i>Sn</i>	1.00	\$	90.00	10.00	\$	81.00	Y	<i>X</i>
73	TAILLAMP RH	<i>Sn</i>	1.00	\$	650.00	10.00	\$	585.00	Y	<i>X</i>
74	TAILLAMP LH	<i>Sn</i>	1.00	\$	650.00	10.00	\$	585.00	Y	<i>X</i>
75	TAILLAMP INNER PANEL LH	<i>n</i>	1.00	\$	325.00	10.00	\$	292.50	Y	<i>X</i>
76	TAILLAMP INNER PANEL RH	<i>n</i>	1.00	\$	325.00	10.00	\$	292.50	Y	<i>X</i>
77	TAILLAMP INNER RH	<i>n</i>	1.00	\$	485.00	10.00	\$	436.50	Y	<i>X</i>
78	TAILLAMP INNER LH	<i>n</i>	1.00	\$	485.00	10.00	\$	436.50	Y	<i>X</i>
79	TAILGATE LOCK	<i>n</i>	1.00	\$	180.00	10.00	\$	162.00	Y	<i>X</i>
80	TAILGATE REFLECTOR RH <i>385.20</i>	<i>Sn</i>	1.00	\$	480.00	10.00	\$	432.00	Y	<i>✓</i>
81	TAILGATE REFLECTOR LH <i>385.20</i>	<i>Sn</i>	1.00	\$	480.00	10.00	\$	432.00	Y	<i>✓</i>
82	TAILGATE CATCH	<i>n</i>	1.00	\$	70.00	10.00	\$	63.00	Y	<i>X</i>
83	TAILGATE OUTER HANDLE GARNISH	<i>Sn</i>	1.00	\$	180.00	10.00	\$	162.00	Y	<i>X</i>
84	TAILGATE INNER HANDLE GARNISH	<i>Sn</i>	1.00	\$	180.00	10.00	\$	162.00	Y	<i>X</i>
85	TAILGATE AUTO SWITCH	<i>Sn</i>	1.00	\$	930.00	10.00	\$	837.00	Y	<i>X</i>
86	KEYLESS SENSOR	<i>Sn</i>	1.00	\$	450.00	10.00	\$	405.00	Y	<i>X</i>
87	REAR WIPER ARM	<i>Sn</i>	1.00	\$	85.00	10.00	\$	76.50	Y	<i>X</i>
88	REAR WIPER MOTOR	<i>Sn</i>	1.00	\$	375.00	10.00	\$	337.50	Y	<i>X</i>
89	REAR WINDSCREEN GLASS WITH MOULDING	<i>nn</i>	1.00	\$	1,030.00	10.00	\$	927.00	Y	<i>X</i>
90	SPARE TYRE PANEL	<i>n</i>	1.00	\$	1,680.00	10.00	\$	1,512.00	Y	<i>X</i>
91	SPARE TYRE TOP BOARD	<i>Sn</i>	1.00	\$	1,260.00	10.00	\$	1,134.00	Y	<i>X</i>
92	REAR EXHAUST PIPE MOUNTING LH & RH	<i>Sn</i>	1.00	\$	55.00	10.00	\$	49.50	Y	<i>X</i>
93	REAR EXHAUST PIPE SILENCER	<i>By</i>	1.00	\$	1,080.00	10.00	\$	972.00	Y	<i>✓</i>
94	REAR EXHAUST HEAT SHIELD	<i>n</i>	1.00	\$	185.00	10.00	\$	166.50	Y	<i>X</i>

TOTAL (PARTS) :

\$ 40,198.00

\$36,178.20

SPECIAL NETT ITEM

1	FRONT NO. PLATE	<i>CRD</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>455M ✓</i>
2	FRONT NO. PLATE GARNISH	<i>Rd</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>✓</i>

3	FRONT PARKING SENSOR	Sh	1.00	\$	480.00	0.00	\$	480.00	Y	X
4	FRONT BUMPER CLIPS	na	1.00	\$	50.00	0.00	\$	50.00	Y	✓
5	FRONT GRILLE CLIPS	na	1.00	\$	50.00	0.00	\$	50.00	Y	✓
6	FRONT SUPPORT PANEL GARNISH CLIPS	na	1.00	\$	50.00	0.00	\$	50.00	Y	X
7	FRONT DOOR LOWER GARNISH CLIPS	na	1.00	\$	50.00	0.00	\$	50.00	Y	X
8	COOLANT	na	1.00	\$	50.00	0.00	\$	50.00	Y	25%
9	TAILGATE INNER TRIM CLIPS	na	1.00	\$	50.00	0.00	\$	50.00	Y	X
10	REAR BUMPER CLIPS	na	1.00	\$	50.00	0.00	\$	50.00	Y	✓
11	REAR BUMPER LOWER COVER CLIPS	na	1.00	\$	50.00	0.00	\$	50.00	Y	—
12	REAR PANEL SEALANT		1.00	\$	80.00	0.00	\$	80.00	Y	30sn
13	REAR PANEL INNER GARNISH CLIPS	na	1.00	\$	50.00	0.00	\$	50.00	Y	X
14	REAR REVERSE SENSOR	Sh	1.00	\$	480.00	0.00	\$	480.00	Y	✓ 320sn
15	REAR NO PLATE	Sh	1.00	\$	50.00	0.00	\$	50.00	Y	X
16	REAR NO. PLATE GARNISH	Sh	1.00	\$	50.00	0.00	\$	50.00	Y	X
17	SPARE TYRE PANEL SEALANT	na	1.00	\$	80.00	0.00	\$	80.00	Y	X
18	REAR WINDSCREEN INNER SEAL	na	1.00	\$	50.00	0.00	\$	50.00	Y	30sn
19	REAR WINDSCREEN CLEANER & PRIMER	na	1.00	\$	50.00	0.00	\$	50.00	Y	30sn
20	REAR WINDSCREEN SEALANT	na	1.00	\$	50.00	0.00	\$	50.00	Y	40sn
TOTAL (PARTS) :				\$	1,920.00		\$	1,920.00		

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA - FRONT		1.00	\$	1,200.00	0.00	\$	1,200.00	Y	600l
2	STRAIGHTEN & PANEL BEAT ACCIDENT AREA - FRONT	na	1.00	\$	1,200.00	0.00	\$	1,200.00	Y	600l
3	SPRAY PAINTING ON ACCIDENT AREA - FRONT		1.00	\$	1,200.00	0.00	\$	1,200.00	Y	660l
4	SPRAY PAINTING ON ACCIDENT AREA - REAR		1.00	\$	1,200.00	0.00	\$	1,200.00	Y	1100l
5	CHECK & REPAIR WIRING SYSTEM		1.00	\$	120.00	0.00	\$	120.00	Y	40l
6	R&R AIRCON CONDENSOR & CHARGE UP GAS		1.00	\$	120.00	0.00	\$	120.00	Y	700l
7	R&R RADIATOR ASSY TO ASSIST REPAIR		1.00	\$	120.00	0.00	\$	120.00	Y	50l
8	RESPRAY TUFF KOTE ON ACCIDENT AREA		1.00	\$	120.00	0.00	\$	120.00	Y	60l
9	R&R REVERSE SENSOR AND CALIBRATION SYSTEM		1.00	\$	120.00	0.00	\$	120.00	na	X
10	R&R FRONT PARKING SENSOR AND CALIBRATION SYSTEM		1.00	\$	120.00	0.00	\$	120.00	Y	60l
11	R&R TAILGATE COMPONENTS		1.00	\$	120.00	0.00	\$	120.00	Y	60l
12	R&R CARPET AND INNER TRIM TO ASSIST REPAIR	na	1.00	\$	150.00	0.00	\$	150.00	Y	X
13	LABOUR TO REMOVE AND REFIT EXHAUST PIPE WITH INSTALL		1.00	\$	380.00	0.00	\$	380.00	Y	80l
TOTAL (LABOUR) :				\$	6,170.00		\$	6,170.00		

TOTAL PARTS & LABOUR

\$ 48,288.00

\$44,268.20

EXCESS : : S\$ _____

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINTING

~~PART~~ BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : 24 / 1 / 22

SURVEY BY : Kenneth

CONTACT NO: _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/01/2022 17:20 (SGT)
Date of Accident	20/01/2022 15:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	MANDAI ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMV5937U
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ER KOK KHOON ALDRICH (YU GUOJUN)
NRIC No	S7705669F
Email Address	ALDRICH@83382828.COM
Mobile Phone No	(Phone) +65-83382828
Alternative Phone No	+65-83382828

VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	TIGUAN HIGHLINE 280 TSI
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1395

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MT/00996216
Cover Note Number	-

DRIVER

Name of Driver	ER KOK KHOON ALDRICH (YU GUOJUN)
NRIC No	S7705669F

Date Of Birth	23/02/1977
Occupation	Indoor
Date Of Driving Pass	22/11/2010
Driving experience	11 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-83382828
Alt. Phone Number	+65-83382828
Email Address	ALDRICH@83382828.COM
Address	452B SENGKANG WEST WAT #18-405
Address complement	-
Postcode	792452
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	NG BAN HOCK
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN6371U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBG7952X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

to be written by me, to be done, and as the Answer of Mine.

3. = Industrial and Commercial Bank of Japan
Industrial and Commercial Bank

Any false report made to the Police is a criminal offence.

CONFIDENTIAL - SECURITY INFORMATION

- - - - -

[illegible]

“是，是，”他连连点头，又接着说：“那您看，我是不是应该先去买点吃的？”

— 10 —

参考文献

[illegible]

(The following information was obtained from the above-mentioned sources.)

॥ श्रीगणेशाय नमः ॥

$$\log_{10} \left(\frac{1}{1 - \frac{1}{10^{\frac{1}{10}}}} \right) = \log_{10} \left(\frac{1}{1 - 0.917} \right) = \log_{10} \left(\frac{1}{0.083} \right) = \log_{10} 12.05 = 1.08$$

2. "What If" Response

[illegible]

此以爲「道」，要「道」者，「道」也。此以爲「道」，要「道」者，「道」也。

一、二、三、四、五、六、七、八、九、十、十一、十二、十三、十四、十五、十六、十七、十八、十九、二十、二十一、二十二、二十三、二十四、二十五、二十六、二十七、二十八、二十九、三十、三十一、三十二、三十三、三十四、三十五、三十六、三十七、三十八、三十九、四十、四十一、四十二、四十三、四十四、四十五、四十六、四十七、四十八、四十九、五十、五十一、五十二、五十三、五十四、五十五、五十六、五十七、五十八、五十九、六十、六十一、六十二、六十三、六十四、六十五、六十六、六十七、六十八、六十九、七十、七十一、七十二、七十三、七十四、七十五、七十六、七十七、七十八、七十九、八十、八十一、八十二、八十三、八十四、八十五、八十六、八十七、八十八、八十九、九十、九十一、九十二、九十三、九十四、九十五、九十六、九十七、九十八、九十九、一百。

[illegible]

Skeletal Proton

Figure 1

分門古今類事

$$= \frac{1}{2} \left(\frac{1}{2} + \frac{1}{2} \right) = \frac{1}{2}$$

Y. A. Izrael

附录



SINGAPORE POLICE FORCE



T20220122/0030

1 of 4

Police Station Of Origin
Hougang NPP
357 Hougang Avenue 7 #01-805
SINGAPORE 530357
Tel No: 1800-2869999

Report No. T20220122/0030

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 22/01/2022 13:50	Video Report No.	Station Diary No. 9
---	------------------	------------------------

Informant's Particulars

Name of Informant ER KOK KHOON ALORICH			Address APT BLK 452B SENGKANG WEST WAY #18-405 SINGAPORE 792452		
ID Type / ID No : NRIC NO / S7705689F			Contact No : Home/Office Mobile: 83382629		
Nationality SINGAPORE CITIZEN			Email		
Sex: Male	Age 44	Date of Birth: 23/02/1977	Type of Informant Driver		
Race Chinese			Language: English		Institution / School Name:
Occupation: PROPERTY AGENT			Driving Licence Information Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident	Non-Injury Others	Drink Drive No	Date/Time of Accident 20/01/2022 15:00	Type of Location T-Junction
Location MANDAI ROAD				
Weather Clear		Road Surface Wet		Road Speed Limit
Traffic Flow		Traffic Control		Traffic Volume: Moderate
Type of Collision Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SMV5937U	Car	VOLKSWAGO N	TIGUAN HIGHLINE 280 TSI	White	Totally Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMV5937U	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MT/00096210	26/12/2021	27/12/2022



SINGAPORE POLICE FORCE



1/20220122/2030

2 of 4

Police Station Of Origin:
Hougang NPP
357 Hougang Avenue 7 #01-805
SINGAPORE 530357
Tel No: 1800-2609999

Report No: 1/20220122/2030

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ER KOK KHOON ALDRICH	ID No.	57705609F
Related Vehicle	SMV5937U (Car)	Contact No.	83382828
Hospital/Clinic	ETERN MEDICAL CLINIC (SENGKANG)	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	21/01/2022	Date Discharge	21/01/2022
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Passenger			
Name	NG BAN HOCK	ID No.	NIL
Related Vehicle	SMV5937U (Car)	Contact No.	93204010
Hospital/Clinic	PROHEALTH MEDICAL GROUP @ HOUGANG	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	21/01/2022	Date Discharge	21/01/2022
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 20/01/2022 at about 1500hrs, I was driving my vehicle Volkswagen Tiguan, white in colour Registration Plate No. SMV5937U along Mandai Road towards Yishun Ave 1. In my vehicle there was a one passenger which is my friend name Ng Ban Hock Hp: 93204010 seating at the front left passenger seat. I then came to a junction at the Mandai Road, near Mandai Train Depot as the traffic light was red. Everything was normal and nothing amiss. I wished to state that the weather was clear, the road surface was slight wet.

While we were stationery at the junction of Mandai Road near to Mandai Train Depot traffic light, suddenly I felt a hard impact at the rear of my vehicle which my vehicle then moved forward to hit on the front vehicle Registration Plate No. G8G7952X. Both me and my friend came out of the vehicle to make a check and discovered that it was a chain collision accident which involve six vehicles. The vehicles that involve the accident as follow, SLS2415C, G8G7952X, SMV5937U, YN6371U, G8E9999J, XD9720R.

Prior to Traffic Police arrival, I manage to take photos of the vehicle involve in the collision accident. I also discovered my front and rear portion of the vehicle were damaged. No one was injured during the accident. All the drivers exchange details in view of the presence of Traffic Police and left the location.

I wished to state that both me and my passenger, Ng Ban Hock Hp: 93204010 went to see doctor on the next day and was given medical leave (myself 2 days MC) passenger 3 days MC).



**SINGAPORE
POLICE FORCE**



T/20220122/2030

3 of 4

Report No. T/20220122/2030

Police Station Of Origin:
Hougang NPP
357 Hougang Avenue 7 #01-805
SINGAPORE 530357
Tel No: 1800-2869999

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20220122/2030

Police Station Of Origin:
Hougang NPP
357 Hougang Avenue 7 #01-805
SINGAPORE 530357
Tel No: 1800-2869999

4 of 4

Report No. T/20220122/2030

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report

F /

Sr Staff Sgt MUHAMMAD
ASHIEK BIN KUMAR

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

22/01/2022 13:50

Officer In Charge Of Case:

TP / GIA /

DSP (2) YIP YEW SENG NELSON

Contact No.: 65476182

Classification Of Case:

SN 085

Authentication Stamp

NP168



Signature:

Singapore Police Force