

RESTRICTED

ANNEX A**STATEMENT OF SSG EDMUND LOW ZHONG WEI**

STATEMENT OF	SSG LOW ZHONG WEI, EDMUND				ALIASES		-		
NRIC NO	SXXXX173Z	AGE	33		MALE/FEMALE		MALE		
EMPLOYMENT	REGULAR	DRIVING LICENSE NO.	SAF/TPT/N/ 01988/11		NATIONALITY		SINGAPOREAN		
DIALECT	-	LANGUAGE SPOKEN	ENGLISH		TEL NO		[REDACTED]		
ADDRESS	[REDACTED]								
INTERPRETED BY	-	RANK	-	TIME	-	DATE	-	-	-
RECORDED BY	-	RANK	-	TIME	-	DATE	-	SIGN	-
<p>I, SXXXX173Z, SSG EDMUND LOW hereby report an accident on 060120, 1745 hrs at transit road (NEE SOON CAMP GATE). While I was waiting for the traffic to be clear along transit road, a red BMW (SJK7696X) driven by LTC (DR) SOH TECK HWEE hit my landrover (MID 33311) from the back. I was heading back to TP7W after helping my superior to collect some documents to facilitate the training on the ground. After the impact, the driver of the red BMW vehicle, LTC (DR) SOH TECK HWEE admitted that it his fault.</p>									
DATE	060120/ 1830hr		SIGNATURE OF DRIVER/ WITNESS						

Additional Note: Police Report made by SSG Edmund no: [T/20200106/2215](#).

RESTRICTED

ANNEX ASTATEMENT OF LTC SOH TECK HWEE

STATEMENT OF	LTC SOH TECK HWEE				ALIASES		-		
NRIC NO	SXXXXX818C	AGE	40		MALE/FEMALE		MALE		
EMPLOYMENT	REGULAR	DRIVING LICENSE NO.	-		NATIONALITY		SINGAPOREAN		
DIALECT	-	LANGUAGE SPOKEN	ENGLISH		TEL NO		[REDACTED]		
ADDRESS									
INTERPRETED BY	-	RANK	-	TIME	-	DATE	-	-	-
RECORDED BY	-	RANK	-	TIME	-	DATE	-	SIGN	-
<p>I, SXXXXX818C, LTC SOH TECK HWEE was outside Nee Soon Camp and there was heavy traffic leaving camp and cars were moving slowly in start stop traffic. There was a MILITARY LAND ROVER MID 33311 (Driven by SSG EDMUND LOW from ETI) which was stationary while waiting for traffic to move in front of my car. I was clearing the hump outside the camp gate and accelerated a bit too hard and came down the hump and rear ended the land rover. There was no injuries and minor scratches on the tailboard and my front was slightly dented.</p>									
DATE	060120/ 1830hr		SIGNATURE OF DRIVER/ <u>WITNESS</u>						

RESTRICTED


ANNEX B

PHOTOS OF THE ACCIDENTS

<p>Location of accident</p>	<p><u>Nee Soon Camp exiting to Transit Road</u></p>  <p>Location of Accident</p>
-----------------------------	---


B-1
SECURITY CLASSIFICATION

RESTRICTED





B-2
SECURITY CLASSIFICATION

RESTRICTED

<p>Photos of Landrover</p>	<div data-bbox="539 414 1278 990"></div> <div data-bbox="699 990 1120 1030"><p><u>FRONT VIEW OF MID 33311</u></p></div> <div data-bbox="533 1176 1287 1765"></div> <div data-bbox="708 1765 1110 1805"><p><u>REAR VIEW OF MID 33311</u></p></div>
---------------------------------------	---

B-3
SECURITY CLASSIFICATION

RESTRICTED

	 <p><u>There is a slight dent to the bottom of tailboard MID 33311</u></p>
Photos of Civilian Vehicle	 <p><u>The civilian car's bonnet and engine cover of SJX 7698X sustained a small upwards dent.</u></p>

B-4
SECURITY CLASSIFICATION

RESTRICTED



B-5

SECURITY CLASSIFICATION