FINAL COST OF REPAIR
(To be completed for only one type of item)

То:	From:	From:		BB70/D/NS/02/20			
HD TP HD TI RESO	_	MAO/NSCSW					
Description of Item:	TRUCK,UTILITY:L/R,LWB,1 TON,4X4,FFR,110"		"	SAF 1222:		1	BB70/D/NS/02/20
Part/Reg No:	MID33311	Original Value:	-	Date:			06.01.2020
Quantity:	01	CE/Non CE:	-				8202384704/18537003 07 January 2020
Description of Damages and Costs of Repairs:					ent Job	No:	8202384704/18537003
				Date:			07 January 2020
S/N Incident Repair 1) Tailboard centre portion dented and cracked				Man-hours 0.50			
<u>S/N</u> 1) TAILGA	<u>Materials</u> TE,VEHICLE BO	<u>Cost</u> DDY:C/W FITTINGS	<u>Unit Price</u> \$1,100.91	Oty 1		<u>COST</u> \$1,100.91	
Base/LEO Area Office's Assessment of Damages							
T S	Labour Charges @ Cotal Cost of Parts Sub-contractor Assessment Fee Cowing Service		hrs	= = = =		\$14.32 \$1,100.91 - \$28.19	_
Total						\$1,143.42	
Estimated Time for Repair:				0.5 Hr			

RESTRICTED Page 1 of 1

^{*}Delete whichever is not applicable FINAL COST OF REPAIR