



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM22000829/Dea3q2 Date: 20/06/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SJA 835J	<b>Veh. Inspected</b>	SLV 5722J
	<b>Policy No.</b>	GA369718	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	S2M03RT4	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	24/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	MERCEDES BENZ 200E	<b>c.c</b>	1997
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	1989
	<b>Chassis No.</b>	WDB1240212A933956	<b>Colour</b>	GREY
	<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195/65 R15	MICHELIN	5 mm
	<b>L/H Front Tyre</b>	195/65 R15	MICHELIN	5 mm
	<b>R/H Rear Tyre</b>	195/65 R15	MICHELIN	5 mm
	<b>L/H Rear Tyre</b>	195/65 R15	MICHELIN	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	21/01/2022	<b>Inspection Date</b>	25/01/2022
	<b>Survey held at</b>	ALFRED AUTO SERVICES & SUPPLIES BLK 5035 ANG MO KIO 3 #01-355 ANG MO KIO INDUSTRIAL PARK 2 . SINGAPORE 569538		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	