

D

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: GBE9024Y

Make & Model: Nissan NV350

Chassis number: JN1MC2E26Z0006087

2016

No.	Description of spare parts	Qty	List price	Amount
1	Front windscreen glass	1	991.00	\$ 1,190.30
2	Front windscreen glass rubber moulding	1	130.00	\$ 183.00
3	Front windscreen glass RH wiper arm	1		\$ 116.40
4	Front windscreen glass RH wiper arm blade	1		\$ 32.00
5	Front windscreen glass LH wiper arm	1		\$ 116.40
6	Front windscreen glass LH wiper arm blade	1		\$ 32.00
7	Front windscreen glass wiper motor	1	352.00	\$ 435.60
8	Front windscreen glass wiper motor linkage	1	184.50	\$ 232.60
9	Front windscreen glass wiper garnish	1	123.50	\$ 451.20
10	Front windscreen glass wiper garnish panel	1		\$ 833.50
11	Front panel	1	996.50	\$ 1,221.50
12	Front panel insulator	1		\$ 54.00
13	Front inner RH panel	1	286.00	\$ 341.30
14	Front inner centre panel	1	300.00	\$ 472.00
15	Front inner LH panel	1	286.00	\$ 386.80
16	Front RH corner panel	1	467.60	\$ 535.50
17	Front RH corner side panel	1		\$ 155.40
18	Front LH corner panel	1	467.60	\$ 535.50
19	Front LH corner side panel	1		\$ 155.40
20	Front bumper	1	541.40	\$ 571.90
21	Front bumper centre grille	1	760.00	\$ 940.00
22	Front bumper towing cover	1		\$ 32.10
23	Front bumper RH fog lamp	1	215.20	\$ 311.80
24	Front bumper RH fog lamp cover	1	105.10	\$ 114.20
25	Front bumper LH fog lamp	1	215.20	\$ 311.80
26	Front bumper LH fog lamp cover	1	105.10	\$ 114.20
27	Front bumper reinforcement	1	345.40	\$ 630.20
28	Front bumper RH side retainer	1	24.90	\$ 164.90
29	Front bumper LH side retainer	1	24.90	\$ 164.90
30	Front bumper RH bracket	1		\$ 32.00
31	Front bumper LH bracket	1		\$ 32.00
32	Front bumper inner bar	1	224.00	\$ 235.00
33	Front bumper armature assy	1		\$ 705.00
34	Front bumper RH stay bracket	1	39.90	\$ 117.20
35	Front bumper LH stay bracket	1	39.90	\$ 117.20

BRV
NECV
NDX
SCV
BRV
BRV
DDV NDX
NSX
DDV
DDV
DPV
DDV
DDV
BRV
BRV
BRV
BRV
BTV
NECV
NSX
BTV
NSX
BTV

2016

36	Front bumper lower air guide	1		\$ ✓ 99.70
37	Front RH chassis member extension panel	1	250.00	\$ -393.00
38	Front RH chassis member extension panel side spalsh shield	1		\$ ✓ 63.20
39	Front LH chassis member extension panel	1	250.00	\$ 393.00
40	Front LH chassis member extension panel side spalsh shield	1		\$ ✓ 63.20
41	RH headlamp assy	1		\$ ✓ 397.90
42	LH headlamp assy	1		\$ ✓ 397.90
43	IPDM cover	1		\$ 37.50
44	Horn	1	50.00	\$ 92.70
45	Front grille	1	479.30	\$ -596.20
46	Front grille emblem	1	42.80	\$ 79.90
47	Turbo intercooler	1	1909.40	\$ -2,121.60
48	Turbo intercooler lower pipe	1	220.00	\$ 431.00
49	Turbo intercooler lower pipe hose	1	56.00	\$ 67.30
50	Turbo intercooler lower pipe hose clamps	2		\$ ✓ 44.00
51	Turbo intercooler upper pipe	1	140.00	\$ 193.50
52	Turbo intercooler upper pipe hose	1	56.00	\$ 67.30
53	Turbo intercooler upper pipe hose clamps	2		\$ ✓ 44.00
54	Radiator assy	1		\$ ✓ 716.60
55	Radiator fan upper cowling	1	48.00	\$ 135.80
56	Radiator fan lower cowling	1		\$ ✓ 14.00
57	Radiator fan blade	1	93.20	\$ 169.00
58	Radiator lower splash shield	1		\$ ✓ 167.40
59	Front air duct	1	180.00	\$ 195.60
60	Aircon heater assy	1	1376.10	\$ 2,211.30
61	Aircon heater pipe	1	117.70	\$ 225.30
62	Aircon heater hose	1	80.00	\$ 162.70
63	Aircon blower assy	1	219.50	\$ 714.60
64	Thermostat sensor	1	150.00	\$ 261.60
65	Aircon cooling valve	1		\$ 139.50
66	Aircon cooling pipe	1	117.00	\$ 171.20
67	Aircon high pressure pipe	1	117.70	\$ 235.60
68	Aircon low pressure pipe	1	168.00	\$ 178.20
69	Aircon receiver drive <i>drive</i>	1	140.30	\$ 199.80
70	Aircon receiver drive bracket	1		\$ ✓ 49.50
71	Power steering cooling pipe	1	135.00	\$ 289.80
72	Air cleaner box	1	276.90	\$ 453.10
73	Air cleaner box lower air duct	1	367.20	\$ 495.60
74	Air cleaner box upper air duct	1	59.90	\$ 242.20
75	Front RH door	1		\$ ✓ 1,085.70
76	Front RH door step garnish	1		\$ ✓ 117.70
77	Front RH door upper hinge	1		\$ ✓ 69.10
78	Front RH door lower hinge	1		\$ ✓ 69.10
79	Front LH door	1		\$ ✓ 1,085.70
80	Front LH door side mirror	1	487.10	\$ 520.30
81	Front LH door step garnish	1		\$ ✓ 117.70
82	Front LH door step garnish inner panel	1		\$ ✓ 128.60
83	Front LH door upper hinge	1		\$ ✓ 69.10
84	Front LH door lower hinge	1		\$ ✓ 69.10
85	Front LH door checker	1		\$ ✓ 88.20
86	Front LH door outer pillar	1	693.00	\$ 931.00
87	Front LH door inner pilar	1	435.90	\$ 803.50
88	Front LH door lock	1		\$ ✓ 166.70

BR ✓
 DD ✓
 DD ✓
 BR ✓
 DD ✓
 BR ✓
 NSX
 SC ✓
 BR ✓
 NEC ✓
 DD ✓
 NEC ✓
 BT ✓
 BR ✓
 BR ✓
 BR ✓
 BR ✓
 DD ✓
 RPT X
 NEC ✓
 NEC ✓
 BT ✓
 BR ✓
 NEC ✓
 DD ✓
 DD ✓
 BT ✓
 DD ✓
 MIS ✓
 DD ✓
 BT ✓
 MIS ✓
 BT ✓
 JM ✓

13	Front LH door company detail sticker	1		\$20.00 35.00	} NECV
14	Front RH door company detail sticker	1		\$20.00 35.00	
15	Brake fluid	1		\$40.00 60.00	
16	Radiator coolant	1		\$40.00 70.00	
17	Front number plate	1		\$40.00 70.00	

	Labour and painting			Amount	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas		3000.00	\$ 3,600.00	✓
2	Spray painting on affected areas and panels		1800.00	\$ 2,200.00	✓
3	Check wiring and lighting system		80.00	\$ 120.00	✓
4	Apply rust coating chemical on affected areas and panels		120.00	\$ 240.00	✓
5	Remove and replace front windscreen glass, sealants and ERP bracket		120.00	\$ 200.00	✓
6	Remove and replace aircon blower, aircon heater, pipes, hoses and sensors to assist repair. To refill aircon gas		200.00	\$ 380.00	✓
7	Remove and replace radiator assy, hoses, pipes and fan assy to assist repair. To refill coolant		80.00	\$ 280.00	✓
8	Remove and replace dashboard, speakers and all dashboard attachments parts to assist repair		250.00	\$ 350.00	✓
9	Remove and replace airbag, sensors, seat belt and control unit to assist repair		300.00	\$ 500.00	✓
10	Reset, activate and diagnose control unit and fault codes		120.00	\$ 450.00	✓
11	Remove and replace brake booster, brake master pump, brake pipes, brake connectors and sensors to assist repair. To bleed brake system and check for functional		200.00	\$ 320.00	✓
12	Remove and reinstall steering wheel, steering coupling, steering shaft, steering bracket and sensors to assist repair		120.00	\$ 300.00	✓
13	Mount vehicle on chassis alignment bench to repair both front chassis frames		200.00	\$ 550.00	✓
14	Remove and replace turbo intercooler, intercooler pipes, intercooler hoses and sensors to assist repair		80.00	\$ 300.00	✓
15	Remove and replace front undercarriage parts to assist repair		80.00	\$ 350.00	✓
16	Test drive and adjust wheel alignment system			\$ 100.00	NNX

16	Remove and reinstall LH front door back panel inner trim, carpet, seats and boards to assist repair	100.00	\$ 380.00
17	Remove and replace LH front door inner mechanism to new door	80.00	\$ 120.00

Total: \$ 52,607.55

Survey
9/2/2022
TCU in Min
1424 hrs

Resurvey
9/3/2022
TCU in Min
1530 hrs

Parts 2,8689.21
SN 496.00
Labour 6,930.00

36,115.21
@ 20% 7,223.04

28,892.17

Lump sum repair
Repair days 24

LS 28,900/2

NV 14,000/2

TCU in Min
30/3/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: