

**SR AUTOWORKS PTE LTD.**

Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875

Email: srautoworks.claims@gmail.com

Tel: 6286 6060 Fax : 6286 7060

**Office Use Only**

|           |     |
|-----------|-----|
| Parts -5% |     |
| SN        |     |
| Labour    |     |
| TOTAL     |     |
| LUMSUM    |     |
| ERV       | 41k |

TO: CHINA TAIPING

Vehicle No : SMX 8973 J

Make &amp; Model : BMW 218i

DATE: 15/1/2022

WBA2F12070V758119

| No.           | DESCRIPTION - PARTS                            | QTY | UNIT PRICE  | PRICE        |
|---------------|------------------------------------------------|-----|-------------|--------------|
| 1             | BOOTLID <i>Revised</i>                         | 1   | \$ 1,216.40 | \$ 1,216.40  |
| 2             | BOOTLID LOGO <i>3 new</i>                      | 1   | \$ 98.00    | \$ 98.00     |
| 3             | BOOTLID EMBLEM(218)                            | 1   | \$ 128.00   | \$ 128.00    |
| 4             | BOOTLID INNER LOCK <i>Revised</i>              | 1   | \$ 312.00   | \$ 312.00    |
| 5             | BOOTLID INNER LOCK MOTOR <i>new</i>            | 1   | \$ 698.00   | \$ 698.00    |
| 6             | BOOTLID LOCK CATCH <i>new</i>                  | 1   | \$ 65.00    | \$ 65.00     |
| 7             | BOOTLID WEATHERSTRIP <i>new cut</i>            | 1   | \$ 219.00   | \$ 219.00    |
| 8             | BOOTLID DETECTOR SENSOR <i>new</i>             | 1   | \$ 383.70   | \$ 383.70    |
| 9             | TAIL LAMP <i>LH cancelled</i>                  | 2   | \$ 898.00   | \$ 1,796.00  |
| 10            | REAR BUMPER <i>Revised</i>                     | 1   | \$ 1,245.00 | \$ 1,245.00  |
| 11            | REAR BUMPER CENTER CHROME <i>at</i>            | 1   | \$ 311.00   | \$ 311.00    |
| 12            | REAR BUMPER REFLECTOR <i>LH cancelled</i>      | 2   | \$ 174.00   | \$ 348.00    |
| 13            | REAR BUMPER SIDE RETAINER <i>new</i>           | 2   | \$ 123.00   | \$ 246.00    |
| 14            | REAR BUMPER CENTER RETAINER <i>cancelled</i>   | 2   | \$ 155.00   | \$ 310.00    |
| 15            | REAR BUMPER REINFORCEMENT <i>Revised</i>       | 1   | \$ 745.00   | \$ 745.00    |
| 16            | REAR BUMPER TOW COVER <i>new</i>               | 1   | \$ 56.00    | \$ 56.00     |
| 17            | REAR BUMPER SENSOR <i>2 pieces damaged</i>     | 4   | \$ 415.00   | \$ 1,660.00  |
| 18            | REAR BUMPER SENSOR WIRE HARNESS <i>new new</i> | 1   | \$ 845.00   | \$ 845.00    |
| 19            | REAR FENDER INNER TRIM <i>new</i>              | 2   | \$ 698.00   | \$ 1,396.00  |
| 20            | REAR FENDER COWLING <i>new new</i>             | 2   | \$ 217.72   | \$ 435.44    |
| 21            | REAR END PANEL <i>Revised</i>                  | 1   | \$ 698.00   | \$ 698.00    |
| 22            | REAR END PANEL TOP GARNISH <i>cancelled</i>    | 1   | \$ 357.00   | \$ 357.00    |
| 23            | REAR FLOOR PANEL TOP BOARD <i>new new</i>      | 1   | \$ 845.00   | \$ 845.00    |
| 24            | REAR EXHAUST PIPE <i>2</i>                     | 1   | \$ 954.00   | \$ 954.00    |
| 25            | REAR EXHAUST BRACKET                           | 1   | \$ 52.00    | \$ 52.00     |
| 26            | REAR EXHAUST PIPE MOUNTING <i>new</i>          | 1   | \$ 54.00    | \$ 54.00     |
| 27            | REAR EXHAUST HEAT SHIELD <i>new</i>            | 1   | \$ 327.40   | \$ 327.40    |
| 28            | SRS UNIT                                       | 1   | \$ 2,154.00 | \$ 2,154.00  |
| Subtotal :    |                                                |     |             | \$ 17,954.94 |
| Less 5% :     |                                                |     |             | \$ 897.75    |
| Parts Total : |                                                |     |             | \$ 17,057.19 |

1018

888685

174

548

500

6161

5544.90



[illegible]

**APPROVED DETAILS**  
**NO. OF WORKING DAYS**  
**PART BY PART OR LUMP SUM**  
**DATE & TIME OF SURVEY**  
**SURVEYED BY**  
**CONTACT NUMBER**  
**FAX NUMBER**