

ASS. REC. BY:

Store

REF:

CS/AIS22000851/AT3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. 2022 22003808

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SMD 2631R

Yr Regn:

10/8/18

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Audi A5

c.c

1984

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

26435

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAV222FL4JA098351

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

275/30R20

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

23/1/22

D.O.I.

26/1/22

Survey held at

Premium

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-145X

Confirm repair cost of \$34,663.80 @ 9 days

red:25907.20:42%

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0061/2022/JT
DATE : 24-Jan-22
WIP : 64700

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 26/1/22

ALLIANZ INSURANCE Singapore Pte. Ltd.

12 MARINA VIEW

#14-01 ASIA SQUARE TOWER 2

SINGAPORE 018961

Attn: Motor Claims Dept

Tel: 65 6297 8802

OWNER'S NAME : MR JOHNY TJHENG
ADDRESS : 35 AMBER GARDENS
#09-10
SINGAPORE 439966
TELEPHONE : HP +65 81579518
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : SP2000439978
VEHICLE NO : SMD 2631 R
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 10/8/2018
ENGINE NO : CVK 060939
CHASSIS NO : WAUZZZF54JA098351
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Jan-22
PLACE OF ACCIDENT : ALONG EAST COAST ROAD (AFTER CEYLON
ROAD AND OPPOSITE ROXY SQUARE)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 2631 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT'S HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. <i>2 x 800</i>	S/N \$ 800.00 <i>400</i>	
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS.	S/N \$ 560.00 <i>280</i>	
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACCUM AND REGAS.	S/N \$ 1,700.00 ?	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>800 x 2</i>	\$ 5,600.00 <i>1600</i>	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS. <i>800 900</i>	\$ 6,000.00 <i>2500</i>	
SUB TOTAL LABOUR CHARGES <i>LH 800</i>		: \$ 15,140.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 2631 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00 /	
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 /	
TOTAL LABOUR CHARGES		: \$ 15,804.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 2631 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>BR</i>	1	\$ 1,987.00	
2	FRONT BUMPER FIXING PARTS <i>?</i>	1	\$ 425.00	
3	FRONT BUMPER SECURING STRIP <i>?</i>	2	\$ 79.00	
4	FRONT BUMPER GRILLE - CENTER <i>BR</i>	1	\$ 219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>?</i>	1	\$ 254.00	
6	FRONT BUMPER SPOILER <i>?</i>	1	\$ 599.00	
7	FRONT BUMPER AIR GUIDE - LH / RH <i>?</i>	2	\$ 144.00	
8	RADIATOR GRILLE <i>BR</i>	1	\$ 2,576.00	
+ 9	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>(RH) - BR</i>	2	\$ 116.00	
10	RADIATOR GRILLE COVER - UPPER <i>?</i>	1	\$ 209.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>?</i>	2	\$ 1,058.00	
12	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 139.00	
13	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 899.00	
14	FRONT BUMPER GUIDE SECTION - LH / RH <i>?</i>	2	\$ 82.00	
15	FRONT BUMPER REINFORCEMENT BEAM COVER <i>(Top can) CR4</i>	1	\$ 143.00	
16	"CAUTION" STICKER <i>MC</i>	1	\$ 16.00	
17	AIR COND STICKER <i>MC</i>	1	\$ 9.00	
18	FRONT BUMPER BRACKET - LH / RH <i>?</i>	2	\$ 508.00	
19	FRONT BUMPER BRACKET <i>?</i>	1	\$ 154.00	
20	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 64.00	
SUB TOTAL SPARE PARTS			\$ 9,680.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 2631 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	POP RIVET <i>✓ MC</i>	4	\$ 4.00	
22	HORN - LH / RH <i>?</i>	2	\$ 273.00	
23	HORN SUPPORT - LH / RH <i>?</i>	2	\$ 66.00	
24	FRONT PARKING AID SENSOR - INNER <i>?</i>	2	\$ 244.00	
25	FRONT PARKING AID SENSOR SEAL RING <i>✓ MC</i>	4	\$ 10.00	
26	FRONT BUMPER WIRING SET <i>?</i>	1	\$ 567.00	
27	BONNET <i>✓ MC</i>	1	\$ 3,491.00	
28	BONNET ATTACHMENT PARTS <i>?</i>	1	\$ 128.00	
29	BONNET HINGE - LH / RH <i>?</i>	2	\$ 932.00	
30	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>✓ MC</i>	3	\$ 93.00	
31	BONNET SOUND ABSORBER <i>X</i>	1	\$ 382.00	
32	BONNET STRIKER - LH / RH <i>?</i>	2	\$ 112.00	
33	BONNET LOCK <i>?</i>	2	\$ 455.00	
34	BONNET BOWDEN CABLE - CENTER <i>?</i>	1	\$ 64.00	
35	BONNET RELEASE CABLE COVER <i>?</i>	1	\$ 11.00	
36	BONNET BOWDEN CABLE OUTER - CENTER <i>?</i>	1	\$ 64.00	
37	BONNET RELEASE LEVER <i>?</i>	1	\$ 15.00	
38	BONNET LOCK CABLE <i>?</i>	1	\$ 82.00	
39	HEADLIGHT - LH / RH <i>✓ MC</i>	1 <i>X</i>	\$ 16,832.00	
40	LIFT CYLINDER - LH / RH <i>?</i>	2	\$ 434.00	
SUB TOTAL SPARE PARTS			\$ 24,259.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 2631 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER BRACKET - LH / RH ?	2	\$ 34.00	
42	LIFT CYLINDER CORRUGATED PIPE ?	1	\$ 100.00	
43	LOCK CARRIER ?	1	\$ 1,127.00	
44	LOCK CARRIER SUPPORT - LH / RH ?	2	\$ 85.00	
45	A/C CONDENSER ?	1	\$ 683.00	
46	REFRIGERANT LINE ?	1	\$ 186.00	
47	REFRIGERANT LINE ?	1	\$ 381.00	
48	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 21.00	
49	CHARGE AIR COOLER ?	1	\$ 654.00	
50	AIR COOLER PRESSURE HOSE ?	1	\$ 413.00	
51	RADIATOR ?	1	\$ 1,010.00	
52	RADIATOR COOLANT ?	6	\$ 282.00	
53	RADIATOR FAN RING ?	1	\$ 291.00	
54	RADIATOR CONTROL UNIT ?	1	\$ 2,483.00	
55	RADIATOR AIR GUIDE OUTER - LH / RH ?	2	\$ 72.00	
56	RADIATOR AIR GUIDE INNER - LH / RH ?	2	\$ 38.00	
57	RADIATOR AIR GUIDE - UPPER ?	1	\$ 19.00	
58	RADIATOR AIR GUIDE - LOWER ?	1	\$ 25.00	
59	INTAKE AIR DUCT - RH ?	1	\$ 25.00	
60	INTAKE AIR GUIDE TOP ?	1	\$ 61.00	
SUB TOTAL SPARE PARTS		:	\$ 7,990.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 2631 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	INTAKE HOSE ?	1	\$ 110.00	
62	AIR MASS METER ?	1	\$ 627.00	
63	AIR FILTER BOX ?	1	\$ 418.00	
64	FRONT DOOR CHROME TRIM - LH / RH ? - BR	21	\$ 342.00	
65	FRONT WHEEL HOUSING LINER - LH / RH ?	2	\$ 598.00	
66	FRONT WHEEL SPOILER - LH / RH ?	2	\$ 164.00	
67	FRONT WHEEL SPOILER LOWER - LH / RH ?	2	\$ 79.00	
68	FRONT NO PLATE - BI	S/N	\$ 100.00	
69	SUNDRIES ?		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 44,767.00	
TOTAL LABOUR CHARGES		:	\$ 15,804.00	
GRAND TOTAL		:	\$ 60,571.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 SUBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (CLKK)
26/1/72, 317

OD-MAL
EX-11-7
PP
by RL by
6 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKX Auto Consultants hence notify the Repairer of the following:

- To ensure the repair is done in a timely manner
- To ensure the repair is done in a professional manner
- To ensure the repair is done in a safe manner
- To ensure the repair is done in a cost-effective manner
- To ensure the repair is done in a way that does not cause any damage to the vehicle
- To ensure the repair is done in a way that does not cause any inconvenience to the customer
- To ensure the repair is done in a way that does not cause any safety hazards
- To ensure the repair is done in a way that does not cause any environmental damage
- To ensure the repair is done in a way that does not cause any health hazards
- To ensure the repair is done in a way that does not cause any fire hazards
- To ensure the repair is done in a way that does not cause any other hazards

Approved by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/01/2022 15:22 (SGT)
Date of Accident	23/01/2022 11:40 (SGT)
Exact Location of Accident	Near 75 E Coast Rd, Singapore 428782
Additional Location Information	ALONG EAST COAST ROAD (AFTER CEYLON ROAD AND OPPOSITE ROXY SQUARE)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD2631R
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	JOHNY TJHENG
NRIC No	SXXXX157I
Email Address	JOHNY780@HOTMAIL.COM
Mobile Phone No	(Phone) +65-81579518
Alternative Phone No	+65-91284642

VEHICLE PARTICULARS

Manufacturer	Audi
Model	A5
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1984

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SP2000439978
Cover Note Number	-

DRIVER

Name of Driver	JOHNY TJHENG
----------------	--------------

ERIC No
 Date Of Birth
 Occupation
 Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

SXXXX1571
 18/06/1984
 Indoor
 08/01/2013
 9 YEARS
 Male
 (Phone) +65-81579518
 +65-91284642
 JOHNY780@HOTMAIL.COM
 35 AMBER GARDENS
 #09-10
 439966
 Yes
 -
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Chain Collision
 Clear
 Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other vehicle or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
 3
 No
 -
 Yes
 3
 No

PASSENGER 1

Name
 Gender

KWEK PEI PEI LISA
 Female

PASSENGER 2

Name
 Gender

ANDRE CHEN YU FENG
 Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No
 No
 -

CIRCUMSTANCES OF ACCIDENT

ON 23/1/22, 1140HRS. I WAS TRAVELLING ALONG EAST COAST ROAD AND COULD NOT BRAKE IN TIME. THEREFOR, HITTING THE BLUE HONDA CIVIC (SCY 3838 M) WHICH IN TURN HIT THE WHITE MAZDA 3 (SMC 3971 H) WHICH WAS VERY CLOSE IN FRONT OF THE BLUE HONDA CIVIC.

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?
 Was there any audio recorded?

Yes
 No
 No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCY3838M
Vehicle Manufacturer	Honda
Vehicle Model	Civic
Vehicle Variant	-
Vehicle Colour	Blue
Vehicle Category	Private car
Name of Driver	SHAWN LEE JINXI
Contact Number	(Phone) +65-82823883
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMC3971H
Vehicle Manufacturer	Mazda
Vehicle Model	3
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Private car
Name of Driver	CHONG FOOK SING
Contact Number	(Phone) +65-98209410
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

SKETCH PLAN

IMPORTANT NOTICE

1. This form is to be completed by the insured or the authorised driver of the vehicle involved in the accident to speed up the claims process.
2. The form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation may result in the insurer's right to repudiate policy liability.
4. The use of this form by the insured or the authorised driver is not an admission of policy liability or an admission of fault.
5. Any false statement may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to my insurer who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope or mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


09:35am
24/01/2022

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan




Describe Circumstances of the Accident


Date/Time: 23 Jan 2022, 11:40am.

I was traveling along East Coast Road and could not brake in time before hitting the blue Honda Civic (SCY3838M), which in turn hit the white (SMC3971H) which was very close in front of the blue Honda Civic.

Declaration

I/we declare the foregoing particulars are true in every respect.



 24/01/2022
Policyholder's Signature / Date & Time
09:49am

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Insured Personnel