



Case Details

Case Reference Number :

TAX/01/22/2047

Company Type : Strides Taxi Pte Ltd

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Type of Repair : Accident Repair

Estimation ID : EST-17298-ID

Accident Date and Time : 21/01/2022 01:00 PM

Vehicle Registration Number : SHB131A

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	de
Standard	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0.00	Not Give	Xm
Standard	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0.00	Not Give	Xm
Standard	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0.00	Not Give	Xm
Standard	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0.00	Not Give	Xm
Standard	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0.00	Not Give	Xm
Standard	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0.00	Check	? Xm
Standard	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.23	Replace	0	0.00	Not Give	Xm
Standard	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.23	Replace	0	0.00	Not Give	Xm
Standard	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0.00	Not Give	Xm
Standard	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0.00	Not Give	Xm
Standard	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0.00	Not Give	Xm
Standard	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0.00	Not Give	Xm
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	Bm
Standard	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.08	Replace	0	0.00	Not Give	Xm
Total Spare Part Cost									6,016.37	Surveyor Total		382.88		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0.00	Not Give	X17
Standard	Main			COVER, ENGINE UNDER CENTER	1	94.50	94.50	25.00	70.88	Replace	0	0.00	Not Give	X17
Standard	Main			COVER, ENGINE UNDER SIDE RH	1	76.90	76.90	25.00	57.68	Replace	0	0.00	Not Give	X17
Standard	Main			COVER, ENGINE UNDER SIDE LH	1	76.90	76.90	25.00	57.68	Replace	0	0.00	Not Give	X17
Standard	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	25.00	682.65	Replace	0	0.00	Not Give	X17
Standard	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0.00	Check	? XM
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0.00	Not Give	X17
Total Spare Part Cost									6,016.37	Surveyor Total		382.88		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									4,813.10	Final Sur Total		306.30		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	676.00	200	
Total:			676.00	200.00	

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	X17
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	X17
Total:			738.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	X17
2	Main	TO REPLACE SUNDRY PARTS	100.00	0	X17
Total:			360.00	40.00	

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	80.00	0 <i>Xnn</i>	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40	
Total:			360.00	40.00 /	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,813.10	306.30
Total Labour Cost	676.00	200.00
Total Spray Painting	738.00	200.00
Other	360.00	40.00
Overall Total	6,587.10	746.30
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	6,600.00	750.00
Surveyor Approved Amount		750.00
No of Repair Days*	4	2
Remarks	-	LUMP SUM REPAIR / AFTER PAINT PHOTO
Surveyor Name		Rasul
Signature		
Survey Date	24/01/2022	<input type="button" value="Save"/> <input type="button" value="Clear"/>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: