

## COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK -

DATE: 19-Jan-22INSURANCE: CHINA TAIPING CP/P)MODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHD6886E

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$459.40 X
	Rear Bumper Reinforcement	1		\$394.80 ?
	Rear Bumper Reinforcement Bracket RH/LH	2	\$138.10	\$276.20 ?
	Rear Bumper Centre Moulding Assy	1		\$451.25 / Scr
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00 X SUC
	Rear Bumper Cover Clips	10	\$2.20	\$22.00 / HPC
	Rear Bumper Tow Cover	1		\$98.80 X SUC
	<b>SUB TOTAL</b>			\$1,857.45
	<b>LESS 20%</b>			\$371.49
	<b>DISCOUNTED TOTAL</b>			\$1,485.96
	Rear Bumper Mat	1		\$50.00 X SUC
	Rear Bumper Reverse Sensor	1		\$180.00 / Cat
	<b>S/NETT TOTAL</b>			\$230.00
	<b>SPARE PARTS TOTAL</b>			\$1,715.96
	<u>Labour Charge</u>			
	Panel Beating			\$400.00 350
	Spray Painting Charge			\$300.00 250
	Remove/Refix Reverse Sensor			\$120.00 30
	<b>TOTAL LABOUR</b>			\$820.00
	<b>ESTIMATE TOTAL</b>			\$2,535.96

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan@Chkauto.com  
 82235769  
 19/1/22 14600  
 12/12 bsr paint photo  
 2clays wp

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 19.01.2022 10:06

Page : 1

Job: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4164217

JC NO 305502017


CUSTOMER AS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P)		REGN NO: <b>SHD6886E</b>	MILEAGE
		MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
		MODEL <b>IONIQ(G3)</b>	DATE/TIME IN <b>18.01.2022 15:15</b>
		YR OF MANU. <b>06.01.2021</b>	TARGET DATE
JUNT CARD NO.		CHASSIS CODE <b>KMHC851CVLU191720</b>	COMPLETION DATE/TIME:

Accident Date: 18.01.2022  
 Accurrence: 3P 18.01.2022

JOB DESCRIPTION

Job NO 00010  
 LABOR CODE PB

DESCRIPTION  
 PANEL BEATING-SHD6886E



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Assignment Slip

Exit Pass

Job: SHD6886E LIMITS

Vehicle No.: SHD6886E

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon completion

To be kept by Security Guard