

TP Budget Direct.

Denise.

HENG KEE WORKSHOP

BLK 1033 EUNOS AVE 5A #01-31 SINGAPORE 409703

HP: 8156 2761

KNAF 5416MLS086982

Specialises In Accident Repair, Insurance Claims & Reporting, Service Repair, Panel Beating & Spray Painting Of Automotive Vehicles.

SMU532S

25.01.2022

Rear Bumper	\$688	✓	Distorted
Rear Bumper Lower	\$298	✓	Distorted
Rear Bumper Side Lamp	\$181 x2	\$362	X } MP Nee.
Rear Bumper Side Lamp Cover	x2	\$78	X }
Rear Bumper Reinforcement	\$378	✓	Distorted
Rear Bumper Bracker	\$79 x2	\$158	✓ Distorted
Rear Bumper Side Retainer	\$36 x2	\$72	✓ New
Rear Bootlid	\$1297	✓	Dented
Rear Bootlid Center Logo	\$54.10		
Rear Bootlid Emblem Cerato	\$58.20		✓ } Nee
Rear Bootlid Emblem Gt	\$45.10		
Rear End Panel	\$374	✓	Distorted
Rear Bootlid Weatherstrip	\$151	✓	cut.
Rear Boot Latch	\$131	✓	Dented.
Rear End Panel Top Garnish	\$71	✓	del.
Rear Reverse Sensor	\$285 x4	\$1140	✓ Dented
To wiring checking	\$60	30	
To Undercoated	\$150	60	
To Spray Painting	\$1200	800	
To Labour charges	\$1200	800	
Rear Exhaust Box	\$757	x 1	MP Nee.

Adnan

H/S 24/01/22.

06 Day.

Supplementary
SMU 5325.

Taillamp x 02 ^{RT added} 675 x 2 = ~~1350~~ ⁶⁷⁵
Bootlid Centre Lamp ^{new} 608 x. 1339
Rear Fender Inner Trim x 02 ^{torn} 302 x 2 = 604. ✓
Rear Fender Inner Trim Clips ^{new} 60. ✓

List: 4915.40
len 10%: 4423.86.
Supplementary: 1205.10
Labour: 1690
total: 7318.96
A/S: 5.8K.
060cups.

11344.4

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: