

Supplementary
SMU 5325.

Taillamp x 02 ^{RT added} 675 x 2 = ~~1350~~ ⁶⁷⁵
Bootlid Centre Lamp ^{new} 608 x. 1339
Rear Fender Inner Trim x 02 ^{torn} 302 x 2 = 604. ✓
Rear Fender Inner Trim Clips ^{new} 60. ✓

List: 4915.40
len 10%: 4423.86.
Supplementary: 1205.10
Labour: 1690
total: 7318.96
A/S: 5.8K.
060cups.

11344.4

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: