

PDSOOM. 2015 March

TP China
Xiao Long

Toyota Hiace. 2982cc

KDH2230022567

Front LH Door	Distorted	1795.80 1611
Front LH Door Lock	2 _{AT} 1 _{an}	292.30 +
Front LH Door Weatherstripe		272.50 +
Front LH Door Inner Trim Board	Gold.	586.90 449.40
Front LH Door Inner Trim Board Clips		30(SN) -
Front LH Door Glass Regulator	2 _{rd}	245.90 -
Front LH Door Glass Regulator Motor	2 _{AT} 1 _{an}	475 +
Front LH Door Wing Mirror	1 _{at}	778 549
Front LH Step Garnish	2 _{AT} 1 _{an}	221.40 +
Front LH Step Garnish Clips		20(SN) +

2855.30 S.N. 30

2141.47

PD 500M.

Panel Beating

~~400~~ 200

Spray Painting

~~400~~ 200

510

Wiring.

~~50~~ 30

To transfer door fittings.

~~150~~ 80

Total: 2681.47.

L/S: J.H.C. ✓

02 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: