



YSK AUTO WORKSHOP

No. 1 Kaki Bukit Avenue 6 @Autobay, #01-71 Singapore 417883
UEN 53311047E

TO: China Taiping Insurance (S) Pte Ltd
3 Anson Rd, #16-00 Springleaf Tower, Singapore
Attn: 6389 6111 Fax: 6222 1033

C/O: LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

Tax Invoice : 202203_040
Date : 17/03/2022
Vehicle : PD500M
Make Model : TOYOTA HIACE 2982cc
Accident Date : 22/01/2022 17:00 (SGT)
Accident Location: 11 LOR 3 TOA PAYOH, SINGAPORE 319579

Particular	Amount
1. COST OF REPAIR & LABOUR	\$2,100.00
2. RENTAL FEE, 03 Days X @\$260.00 per day	\$ 780.00
3. Pre-Repair Inspection for 2 days x @\$260.00 per day	\$ 520.00
4. GIA / LTA SEARCH FEE	\$ 7.45

Singapore Dollars: Three Thousand Three Hundred Seventy-Seven and Cents Forty-Five Only

Total S\$: 3,377.45



YSK Auto Workshop