



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNB5345X

Lee Suet Foong

Blk 201 Bishan Street 21
#06-461
Singapore 570201

Vehicle & Document Information

WIP No 54751
Reg No/Reg Date SNB5345X / 27/08/2021
Date In/Mileage / 0
Chassis No W1K2470842J3027907
Engine No 28291480637233
Make/Model MB/B 180
Colour/Trim 027 787 Mountain Gr/ 041 101 ARTICO Blac

SNB5345X

Account No	Terms	Date/Time Printed	CSE	Operator
WCV46582	CRDVCH	24/01/2022/ 14:19	YK	395 / Yik Chan Hoe
Description of Goods / Services	Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M BPNSUN
POLICY NO/ACC DATE : A300173683QMY // 21/01/2022
DRIVE IN/EXCESS : 24/01/2022 // TP VEH NO GBL6163L CHINA TAIPING
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH

A BPIRES

RESPRAY BONNET, LEFT FRONT FENDER AND FRONT BUMPER. (\$800 PER PANEL)

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT

A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT

M FRONT SUPPORT PANEL

M LEFT HEADLAMP UNIT

M LEFT HEADLAMP CONTROL UNIT, COMPLETE

M LEFT FRONT FENDER

M LEFT FRONT FENDER EDGE GUARD

M LEFT FRONT FENDER LINER FF

M LEFT FRONT FENDER LINER END PIECE

M FRONT BUMPER

M FRONT BUMPER MB EMBLEM

M FRONT BASIC CARRIER FOR BUMPER

970 x 14	3840	1920	4800.00
24m	3000.00		
0.10	380.00		
	120.00		
1.00	620.36	00.00	620.36
1.00	3194.65	00.00	3194.65
1.00	509.35	00.00	509.35
1.00	660.13	00.00	660.13
1.00	7.23	00.00	7.23
1.00	199.70	00.00	199.70
1.00	25.01	00.00	25.01
1.00	1337.11	00.00	1337.11
1.00	79.32	00.00	79.32
1.00	150.82	00.00	150.82

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclectcarriage.com.sg

Steve (LKK) *mm* *rc*
8/2/22, 11:00am *86* *df*
PIP

Confirmed & accepted by

Nett	15,083.68
7% GST on	15083.68
Total Payable	16,139.54

Authorized signatory and company stamp

LKK Auto Consultants hence notify
the Repairer of the following:

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg