



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## Finalization

## ESTIMATE FOR SNB5345X

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

## Vehicle &amp; Document Information

WIP No 54751  
Reg No/Reg Date SNB5345X / 27/08/2021  
Date In/Mileage 08/02/2022 / 4856  
Chassis No W1K2470842J3027907  
Engine No 28291480637233  
Make/Model MB/B 180  
Colour/Trim 027 787 Mountain Gr/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator		
WC000668	Credit	19/02/2022/ 09:16		395 / Yik Chan Hoe		
Description of Goods / Services			Qty	Unit Price	Disc%	Amount

## Z REQUEST

Customer Request  
M-BPNSUN

POLICY NO/ACC DATE : A300173683QMY // 21/01/2022  
DRIVE IN/EXCESS : 24/01/2022 // TP VEH NO GBL6163L CHINA TAIPING  
DATE IN/DATE SURVEY: 08/02/2022 // STEVE LKK  
BY/AUTHORIZED ON : DIRECT SETTLEMENT // JENNY LEW CHINA

## A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW  
BODY PANELS WITH REFINISH

3840.00

## A BPIRES

RESPRAY BONNET, LEFT FRONT FENDER AND FRONT BUMPER. (\$800 PER PANEL)

2400.00

## A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO  
STANDARD SETTINGS. NETT

0.10

380.00

## A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT

120.00

## X LEFT FRONT FENDER

1.00 660.13 00.00

660.13

## X FRONT BUMPER

1.00 1337.11 00.00

1337.11

## X FRONT BUMPER MB EMBLEM

1.00 79.32 00.00

79.32

## X LEFT HEADLAMP CONTROL UNIT, COMPLETE

1.00 509.35 00.00

509.35

## X FRONT SUPPORT PANEL

1.00 620.36 00.00

620.36

## X LEFT HEADLAMP UNIT

1.00 3194.65 00.00

3194.65

## Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed &amp; accepted by

Nett 13,140.92  
7% GST on 13140.92 919.86

Authorized signatory and company stamp

Total Payable 14,060.78

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg