

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22000860/KGA3Q2**Date:** 20/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100487641-05
<b>Claimant Vehicle No :</b>	SJH7749S	<b>Insured Vehicle No :</b>	GBF4361B
Date of Loss:	23/01/2022	Nature of Claim:	TP
		Claim No:	4725664488SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJH7749S</b>	Engine No:	1NZD103570
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603028673
Reg. Date:	23/08/2008 (Man. Year: 2008)	Odometer:	172850 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,528.92	4,999.00	2,529.92	33.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,835.00	1,545.00	45.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,908.92</b>	<b>6,834.00</b>	<b>4,074.92</b>	<b>37.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,908.92</b>	<b>5,400.00</b>	<b>5,508.92</b>	<b>50.50</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,907.45</b>		

INSPECTION

Date of Assignment:	25/01/2022	
Date Inspected:	25/01/2022 Inspected At:	T & B Motor Repairs Services Pte Ltd Blk 160 Sin Ming Drive #08-03, Sin Ming Auto City Singapore 575722
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER R/H	Bent	966.85 FL	*553.20 FL
2	1		*FRONT FENDER INNER SHIELD RH	Cracked	298.25 FL	*298.25 FL
3	10		*FRONT FENDER INNER SHIELD CLIP RH	Necessary	65.00 FL	*65.00 FL
4	1		*(SIDE) FRONT FENDER INNER BRACKER L/H	Distorted	80.40 FL	*80.40 FL
5	1		*FRONT HEAD LAMP R/H	Cracked	1,030.20 FL	*1,030.20 FL
6	1		*FRONT GRILLE	Serviceable	390.70 FL	*- FL
7	4		*FRONT GRILLE CLIPS	Not Necessary	26.00 FL	*- FL
8	1		*FRONT BUMPER	Damaged	1,132.95 FL	*1,020.10 FL
9	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	80.35 FL	*80.35 FL
10	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	80.35 FL	*- FL
11	1		*FRONT BONNET	Bent	1,227.20 FL	*916.20 FL
12	1		*FRONT SUPPORT PANEL	Buckled	1,219.70 FL	*744.60 FL
13	1		*FRONT SHOCK ABSORBER RH	Bent	680.90 FL	*368.80 FL
14	1		*FRONT SHOCK ABSORBER TOP MOUNTING RH	Serviceable	130.20 FL	*- FL
15	1		*FRONT LOWER ARM RH	Distorted	510.15 FL	*419.70 FL
16	1		*FRONT LOWER ARM BALL JOINT	Bent	141.40 FL	*141.40 FL
17	1		*(R/H) FRONT WHEEL KNUCKLE ARM	Bent	381.25 FL	*381.25 FL
18	1		*FRONT WHEEL HUB BEARING ASSY RH	Necessary	149.30 FL	*149.30 FL
19	1		*FRONT TYRE RH	Serviceable	320.00 FL	*- FL
20	1		*FRONT SPORT RIM RH	Repair	500.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,411.15</b>	<b>6,248.75</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,882.23	1,249.75
<b>Total Parts (\$\$)</b>	<b>7,528.92</b>	<b>4,999.00</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK & REPAIR WIRING	New	120.00	20.00
2	COMPUTER ALIGNMENT	New	120.00	60.00
3	TYRE HIGH SPEED BALANNING	New	80.00	15.00
4	SPRAY PAINT ANTI-RUST COATING	New	180.00	60.00
5	DISMANTLE AND FIX BACK UNDERCARRIAGE	New	480.00	200.00
6	SPRAY PAINTING	New	1,200.00	880.00
7	LABOUR TO DO PANEL BEATING	New	1,200.00	600.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,380.00</b>
				<b>1,835.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >