



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

KNAF H222385059655

TP China
Xiao Chen.

LKK

DATE 22703/2022 OUR REF: UAP1518
REPAIR ESTIMATE YOUR INSURED VEHICLE KIA CERATO NO SKV3027H
NETT PRICE

1 FRONT L/H DOOR ASSY <i>Dented.</i>	\$	1,104.00	✓
2 FRONT L/H DOOR HINGES <i>not new</i>	\$	116.00	✗
1 FRONT L/H DOOR LOCK <i>Damaged</i>	\$	353.00	✗ 258
1 FRONT L/H DOOR OUTER HANDLE <i>lt.</i>	\$	212.00	✓
1 FRONT L/H DOOR WEATHERSTRIP <i>not new</i>	\$	226.00	✗
1 FRONT L/H DOOR INNER TRIM BOARD <i>cut d</i>	\$	257.00	✗ 655
1 FRONT L/H DOOR TOP BLACK STICKER <i>given</i>	\$	47.00	✓
1 FRONT L/H DOOR CENTRE BLACK STICKER <i>given</i>	\$	40.00	✓
1 REAR L/H DOOR ASSY <i>Dented</i>	\$	984.00	✓
2 REAR L/H DOOR HINGES <i>not new</i>	\$	116.00	✗
1 REAR L/H DOOR TOP BLACK STICKER <i>given</i>	\$	47.00	✓
1 REAR L/H DOOR CENTRE BLACK STICKER <i>given</i>	\$	40.00	✓
1 REAR L/H DOOR WEATHERSTRIPS <i>lt</i>	\$	222.00	✓
	\$	4,264.00	
	\$	426.40	
	\$	3,837.60	

LESS 10%.....

SPECIAL NETT:-

1 L/H CENTRE SILL PANEL OUTER SPOILER

Deband

\$ 400.00 *350.*

350

LABOUR CHARGES:-

TO DISM/REWIRE DAMAGED PORTION

\$ 100.00 *30.*

TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS

\$ 1,000.00 *500*

TO PUTTY AND RESPRAY DAMAGED PORTION

\$ 900.00 *400*

TO SPARY UNDERCOATING IN REPAIR

\$ 100.00 *30.*

TO DISM/REFIX SEAT, PANEL LINING, ROOF LINING

\$ 100.00 *✗*

\$ 6,437.60

total: 4594.10

L/S: 3.6K.

0 4 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: