

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	🖨	📄	Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref: CS/SMO22000863/Uvf3	
50 RAFFLES PLACE #03-03		Date: 25/01/2022	
SINGAPORE LAND TOWERSINGAPORE 048623		Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 9392Z	Veh. Inspected	GBC 8929D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2200334/MYE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	25/01/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	24/01/2022	Inspection Date	25/01/2022
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			