

FASTTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

Submit to insurance

Not Authorized

25/1/22

L/C # 3500

3 days

VEHICLE No: GBC 8929D

NETT ITEM

1PC	REAR TAILGATE	<i>20/Bent</i>	<i>1389</i>	\$1,860.00	✓
2PCS	REAR TAILGATE LOCK LATCHS @\$380.00			\$760.00	X
2PCS	REAR TAILGATE LOCK LOWER 'L' BRACKETS @\$180.00			\$360.00	X
2PCS	REAR TAILGATE LOCK LOWER "L" BRACKER RUBBERS @\$120.00			\$240.00	X
1PC	REAR TAILGATE 'NISSAN' STICKER	<i>NZ</i>		\$80.00	X
2PCS	TAILLAMPS @\$450.00	<i>one</i>	<i>285 x 2 = 570</i>	\$900.00	✓
2PCS	TAILLAMP HOUSING PANELS @\$180.00	<i>NS</i>		\$360.00	X
1PC	REAR LICENCE PLATE BRACKET	<i>Bent</i>	<i>161.30</i>	\$345.00	✓
1PC	REAR EXHAUST	<i>11</i>		\$1,250.00	X
1PC	REAR EXHAUST MOUNTING	<i>11</i>		\$85.00	X
1PC	REAR END PANEL	<i>20/Bent</i>	<i>544.20</i>	\$685.10	✓
1PC	REAR SPARE TYRE CARRIER & CHAIN	<i>11</i>		\$680.00	X
1PC	DROPSIDE GATE PANEL N/S	<i>R</i>		\$2,290.00	X
1PC	DROPSIDE GATE LOWER MEMBER	<i>R</i>		\$988.00	X
1PC	DROPSIDE GATE PANEL O/S	<i>R</i>		\$2,290.00	X
				\$13,173.10	

S.NETT

1SET	REAR TAILGATE '70km/h & 10pax STICKER	<i>NS</i>		\$50.00	<i>20</i>
1SET	REAR REVERSE SENSOR	<i>short</i>		\$300.00	<i>200</i>
1PC	REAR LICENCE PLATE	<i>SCR</i>		\$50.00	<i>14</i>
1SET	REAR ALUMINIUM PLATE RIVET	<i>NS</i>		\$100.00	<i>50</i>
1PC	REAR ALUMINIUM PLATE	<i>SVC</i>		\$800.00	X
1PC	REAR STEP BRACKET	<i>NT</i>		\$400.00	X

TO CHECK WIRING	\$50.00	<i>20</i>
TO DISMANTLE & REPLACED REVERSE SENSOR	\$100.00	<i>50</i>
TO DISMANTLE & REPLACED REAR CARGO DECK	\$800.00	X
TO STRAIGHTEN & REALIGN CHASSIS	\$1,000.00	X
TO SPRAY RUST PROOFING	\$200.00	<i>50</i>
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,200.00	<i>800</i>
TO PUTTY & SPRAY PAINTING	\$1,800.00	<i>800</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL

\$21,023.10

P-267450

102

P-2407.05

S.N-284

L-1720

4/11/22 3028