

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000865/ETY3N2
Date: 24/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00038612107
Claimant Vehicle No :	SMQ8494L	Insured Vehicle No :	GBA2332A
Date of Loss:	16/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200438/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ8494L	Engine No:	G4FGKH749376
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5052415
Reg. Date:	05/12/2019 (Man. Year: 2019)	Odometer:	16864 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,360.00	1,047.00	1,313.00	55.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,470.00	550.00	27.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,380.00	2,517.00	1,863.00	42.53
+ GST 7.00/7.00% (S\$)	306.60	176.19	130.41	42.53
Nett Amount (S\$)	4,686.60	2,693.19	1,993.41	42.53

INSPECTION

Date of Assignment:	25/01/2022	
Date Inspected:	14/02/2022 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2022)
Parts: 143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMQ8494L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FS	*328.00 FS
2	1		*GARNISH-RADIATOR GRILLE	Broken	38.00 FS	*38.00 FS
3	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FS	*- FS
4	1		*LAMP ASSY-HEAD,LH	Not Necessary	1,219.00 FS	*- FS
5	1		*COVER-FR BUMPER	Broken	633.00 FS	*633.00 FS
6	1		*ORNAMENT-KIA NO 115	Necessary	28.00 FS	*28.00 FS
7	1		*SUNDRY	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	2,360.00	1,047.00
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR FRT BUMPER,REPAIR BONNET	New	640.00	640.00
2	SPRAY PAINT FOR FRT BUMPER	New	1,100.00	550.00
3	CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM	New	280.00	280.00
			Gross Labour Cost (\$)	2,020.00
				1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >