



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
LEE PENG WENG JOSEPH		Cust No/Name	/LEE PENG WENG JOSEPH
53 HILLVIEW AVENUE		Reg No/Reg Date	SMQ8494L*ECB1/ 05/12/201
#06-07		Date In/Mileage	/ 0
SINGAPORE 669566		Chassis No	KNAF3416MK5052415
Contact No Mobile: 96681135		Engine No	G4FGKH749376
		Make/Model	KIA/CERATO 1.6 A EX G333
		Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	24/01/2022/ 09:48		442 / CocoLu	45714

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR FRT BUMPER, REPAIR BONNET				640.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER				550 1100.00
M SUNDRY sundry				20 30.00
A 90000001 CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				280.00
M GRILLE ASSY-RADIATOR	1.00	328.00	00.00	328.00
M GARNISH-RADIATOR GRILLE	1.00	38.00	00.00	38.00
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	00.00	84.00
M LAMP ASSY-HEAD,LH	1.00	1219.00	00.00	1219.00

# Estimate

ster (LKK)  
14/2/22, 10:30am

W PL  
PIP  
by BL by  
3 dy

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer  
Signature:  
Date:

	Nett	3,719.00
7% GST on	3719.00	260.33
<b>Total Payable</b>		<b>3,979.33</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.