



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LEE PENG WENG JOSEPH  53 HILLVIEW AVENUE #06-07 SINGAPORE 669566  Contact No Mobile: 96681135	Cust No/Name	/LEE PENG WENG JOSEPH
	Reg No/Reg Date	SMQ8494L*ECB1/ 05/12/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5052415
	Engine No	G4FGKH749376
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	24/01/2022/ 09:48		442 / CocoLu	45714

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR FRT BUMPER, REPAIR BONNET				640.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER				1100.00
M SUNDRY sundry				30.00
A 90000001 CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				280.00
M GRILLE ASSY-RADIATOR	1.00	328.00	00.00	328.00
M GARNISH-RADIATOR GRILLE	1.00	38.00	00.00	38.00
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	00.00	84.00
M LAMP ASSY-HEAD,LH	1.00	1219.00	00.00	1219.00

Estimate

Confirm &amp; accepted by

7% GST on	7% GST on	3719.00	3,719.00
			260.33
	<b>Total Payable</b>		<b>3,979.33</b>

\_\_\_\_\_  
 Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.