

CHOO MOTOR SPRAY PAINTER  
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY  
SINGAPORE 417883

Not Authorised  
25/11/22  
45 #6700/  
3 days.

VEHICLE No: SMY 5776B

NETT ITEM

1PC FRONT BUMPER  
1PC FRONT BUMPER SIDE RETAINER O/S  
1SET FRONT BUMPER CLIPS  
1PC FRONT BUMPER PDC SENSOR O/S  
1PC FRONT SUPPORT PANEL  
1PC HEADLAMP ASSY O/S  
1PC WIPER WASHER TANK  
1PC FRONT FENDER O/S  
1PC BONNET

960.30

6021.50

1334.20

Torn \$1,160.30 ✓  
nn \$98.20 X  
ner \$50.00 ✓  
11 \$349.20 X  
R \$745.21 X  
cra \$6,921.50 ✓  
su \$366.20 X  
DO \$1,534.20 ✓  
R \$2,108.20 X  
\$13,333.01

1102

TO CHECK WIRING  
TO DISMANTLE & REFIX FRONT PDC SENSOR  
TO REFILL AIR CON GAS  
TO SPRAY RUST PROOFING  
TO RESET & REPROGRAMME SYSTEM  
LABOUR FOR PANEL BEATING & REPLACED PARTS  
TO PUTTY & SPRAY PAINTING

\$50.00 20  
\$80.00 50  
11 \$120.00 X  
\$50.00 30  
11 \$180.00 X  
\$880.00 300  
\$1,180.00 500

TOTAL \$15,873.01

P-8366  
102  
P-7529.40  
L- 900  
8429.40  
252  
6743.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: