

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 14 Jun 2022

Preliminary Advice

Insured Vehicle No : SMQ9554R
TP Vehicle No : SKD2413C Accident Date : 22/01/2022
Make : VOLKSWAGEN SCIROCCO Assignment Date : 25/01/2022
Date of Inspection : 25/01/2022 Est. Duration of Repair : 6
Inspection At : C. S. ONG AUTO PTE LTD (HQ)
BLK 10 ANG MO KIO IND PARK 2A, #02-16 AMK AUTOPOINT
SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	65,027.15
Revised Amount	:S\$	11,655.26
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,655.26
Lump Sum Repair	:S\$	9,300.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	45,394.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,606.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (x) Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.