

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AIG	DATE	: 22/01/2022
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SJY3728P		
MODEL	: TOYOTA COROLLA ALTIS 1.6 A	Asher.	
CHASSIS NO			
ACCIDENT DETAILS			
	DATE	: 22-Jan-22	
	TIME	: 07:50HRS	
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Buckled</i>	1	\$ 769.60	\$ 769.60
2	BOOTLID LOGO	1	\$ 80.00	\$ 80.00
3	BOOTLID EMBLEM 'COROLLA' <i>new</i>	1	\$ 62.40	\$ 62.40
4	BOOTLID EMBLEM 'ALTIS'	1	\$ 55.30	\$ 55.30
5	BOOTLID EMBLEM '1.6'	1	\$ 55.00	\$ 55.00
6	BOOTLID TOP LOCK <i>Dented</i>	1	\$ 162.20	\$ 162.20
7	BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 222.30	\$ 222.30
8	REAR BUMPER <i>Replaced</i>	1	\$ 588.70	\$ 588.70
9	REAR BUMPER SIDE RETAINER FRONT <i>new</i>	2	\$ 62.40	\$ 124.80
10	REAR BUMPER SIDE RETAINER REAR <i>new</i>	2	\$ 55.20	\$ 110.40
11	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 90.00	\$ 180.00
12	REAR BUMPER BRACKET <i>LH Dented</i>	2	\$ 130.00	\$ 260.00
13	REAR BUMPER SPONGE WITH PROTECTOR BAR <i>cracked</i>	1	\$ 166.80	\$ 166.80
14	TAILLAMP <i>blacked cut</i>	1	\$ 375.00	\$ 375.00
15	REAR END PANEL <i>Dented</i>	1	\$ 708.00	\$ 708.00
16	REAR END PANEL TOP GARNISH <i>Not new</i>	1	\$ 126.00	\$ 126.00

TOTAL PRICE \$ 4,046.50

LESS 25% \$ 1,011.63

3263.40

2447.55

SUB TOTAL PRICE \$ 3,034.88

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
2	REAR BUMPER CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00 <i>✓</i>
3	TAILLAMP CLIPS(SET) <i>New</i>	1	\$ 30.00	\$ 30.00 <i>10</i>
4	REAR END PANEL TOP GARNISH CLIPS <i>New</i>	1	\$ 20.00	\$ 20.00 <i>+</i>
5	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
6	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 <i>2w</i>

290

TOTAL \$ 490.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	600	
3	TUFF COAT	\$ 250.00	60	
4	WIRING CHECK	\$ 100.00	30	
5	REMOVE AND REPAIR OCCUPANT SEAT UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
7	TRANSFER BOOTLID MECHANISM	\$ 120.00	60	
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X	

1660

TOTAL \$3,280.00

TOTAL PARTS COST : \$ 3,524.88
TOTAL LABOUR COST : \$ 3,280.00
TOTAL REPAIR COST : \$ 6,804.88

Adrian L
1/s 24/04/22
06 Pyp.

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

total: 4397.55
1/s: 3.5K