

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0063/2022/TF  
DATE : 25/1/202254865  
WIP : 44486

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/1/2022

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. YAP ZONG XING, ERIC  
ADDRESS : 21 ANCHORVALE CRECENT  
#09-24  
SINGAPORE 544654  
TELEPHONE : HP +65 9010 2301  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 7210154384  
VEHICLE NO : SKM 5128 J  
MODEL CODE : A5 SPORTBACK 2.0 TFSI S tronic  
MODEL YEAR : 28/12/2021  
ENGINE NO : DEM 034426  
CHASSIS NO : WAUZZZF5XNA002843  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 22-Jan-22  
PLACE OF ACCIDENT : CTE (AYE) BEFORE EXIT 8A

55 UBI ROAD 1, SINGAPORE 408699


TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKM 5128 J**

| S/N | NATURE OF JOBS                                                                                                                                                                         | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|-----|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 1   | TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. <i>Headlight &amp; sensor remove</i> | S/N \$ 480.00        | / ✓                        |
| 2   | TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM.                                                                                                                                     | S/N \$ 280.00        | / ✓                        |
| 3   | TO REMOVE AND RENEW LHS WING MIRROR ASSY AND DOOR COMPONENTS.                                                                                                                          | S/N \$ 400.00        | X                          |
| 4   | TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                                  | S/N \$ 480.00        | X                          |
| 5   | TO RENEW FRONT WINDSCREEN.                                                                                                                                                             | S/N \$ 400.00        | X                          |
| 6   | TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN AND LHS FRONT DOOR WINDOW GLASS.                                                                                                            | S/N \$ 200.00        | X                          |
|     | TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.                                                                                                                                  | S/N \$ 200.00        | X                          |
|     | <b>SUB-TOTAL LABOUR CHARGES</b>                                                                                                                                                        | <b>: \$ 2,240.00</b> |                            |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKM 5128 J

| S/N                  | NATURE OF JOBS                                                                                                                                                                                                                                               | ESTIMATED CHARGES                   | SURVEYOR'S RECOMMENDATIONS |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|----------------------------|
| 7                    | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR BONNET AND LHS FRONT DOOR. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.<br><i>Roof chrome - 0.5</i> | \$ 4,000.00<br><i>2.5 x 500</i>     | 1250 / ✓                   |
| 8                    | TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS UPPER A-PILLAR AND LHS SILL PANEL TRIM.                                                                                                                                               | \$ 6,000.00<br><i>6 x 550 + 150</i> | 3450 / ✓                   |
| 9                    | TO RENEW LHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT.                                                                                                                                                                                               | S/N \$ 520.00                       | / ✓                        |
| 10                   | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                                                                                               | S/N \$ 192.00                       | / ✓                        |
| TOTAL LABOUR CHARGES |                                                                                                                                                                                                                                                              | : \$ 12,952.00                      |                            |



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 5128 J

|                       |                                                        |     | DAMAGED PARTS & PRICES |         |
|-----------------------|--------------------------------------------------------|-----|------------------------|---------|
| S/N                   | PARTS DESCRIPTION                                      | QTY | S/NETT                 | REMARKS |
| 1                     | FRONT BUMPER / BR                                      | 1   | \$ 2,493.00            | 1994.40 |
| 2                     | FRONT BUMPER SECURING STRIP ? x nn                     | 2   | \$ 79.00               |         |
| 3                     | FRONT BUMPER AIR GUIDE - LH ? x nn                     | 1   | \$ 72.00               |         |
| 4                     | FRONT BUMPER AIR GUIDE GRILLE - LH ? x nn              | 1   | \$ 151.00              |         |
| 5                     | FRONT BUMPER AIR GRILLE TRIM - LH ? x nn               | 1   | \$ 54.00               |         |
| 6                     | FRONT BUMPER GUIDE SECTON - LH ? x nn                  | 1   | \$ 41.00               |         |
| 7                     | FRONT PARKING AID SENSOR ? x nn                        | 1   | TBC                    |         |
| 8                     | FRONT PARKING AID SENSOR SEAL RING - <del>AK</del> Xnn | 4   | \$ 15.00               |         |
| 9                     | FRONT FENDER - LH / nn                                 | 1   | \$ 1,189.00            | 951.20  |
| 10                    | FRONT FENDER ATTACHMENT PARTS ? x nn                   | 1   | \$ 55.00               |         |
| 11                    | FRONT FENDER CLOSING ELEMENT - LH ? x nn               | 1   | \$ 83.00               |         |
| 12                    | FRONT FENDER BRACKET - LH ? x nn                       | 1   | \$ 41.00               |         |
| 13                    | FRONT FENDER DEFORMATION BRACKET - LH ? x nn           | 1   | \$ 55.00               |         |
| 14                    | FRONT FENDER BRACE - LH ? x nn                         | 1   | \$ 132.00              |         |
| 15                    | FRONT FENDER CENTER BRACKET - LH ? x nn                | 1   | \$ 40.00               |         |
| 16                    | FRONT FENDER CHROME TRIM - LH ? / nn                   | 1   | \$ 171.00              | 136.40  |
| 17                    | FRONT WHEEL HOUSING LINER - LH ? x nn                  | 1   | \$ 299.00              |         |
| 18                    | FRONT WHEEL SPOILER - LH ? x nn                        | 1   | \$ 82.00               |         |
| 19                    | FRONT WHEEL SPOILER TRIM - LH ? x nn                   | 1   | \$ 39.00               |         |
| 20                    | FRONT WHEEL SPOILER BRACKET - LH ? x nn                | 1   | \$ 27.00               |         |
| SUB TOTAL SPARE PARTS |                                                        |     | \$ 5,118.00            |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 5128 J

| S/N                  | PARTS DESCRIPTION                         | QTY | DAMAGED PARTS & PRICES |          | REMARKS   |
|----------------------|-------------------------------------------|-----|------------------------|----------|-----------|
|                      |                                           |     | S/NETT                 |          |           |
| 21                   | FRONT FENDER STONE CHIP GUARD - LH / cut  | 1   | \$                     | 57.00    | 45.28     |
| 22                   | FRONT WIND MIRROR MOUNTING - LH / BR      | 1   | \$                     | 2,137.00 | 1709.60   |
| 23                   | FRONT WIND MIRROR COVER - LH / mis        | 1   | \$                     | 308.00   | 246.40    |
| 24                   | FRONT WIND MIRROR - LH / BR               | 1   | \$                     | 1,298.00 | 1038.40   |
| 25                   | ROOF CHROME MOLDING - LH / cut            | 1   | \$                     | 706.00   | 564.80    |
| 26                   | FRONT DOOR UPPER PROTECT SEAL - LH ? X nn | 1   | \$                     | 172.00   |           |
| 27                   | FRONT DOOR WINDOW SLOT SEAL - LH ? X nn   | 1   | \$                     | 446.00   |           |
| 28                   | FRONT WATER DEFLECTOR STRIP - LH X nn     | 1   | \$                     | 75.00    |           |
| 29                   | FRONT DOOR CONER TRIM - LH / cut          | 1   | \$                     | 51.00    | 40.40     |
| 30                   | FRONT DOOR CHROME TRIM - LH / rec         | 1   | \$                     | 171.00   | 136.40    |
| 31                   | FRONT DOOR WINDOW - LH X nn               | 1   | \$                     | 322.00   |           |
| 32                   | FRONT WINDSCREEN X nn                     | 1   | \$                     | 1,625.00 |           |
| 33                   | RAIN SENSOR FOIL X nn                     | 1   | \$                     | 130.00   |           |
| 34                   | RETAINING SPRING X nn                     | 1   | \$                     | 24.00    |           |
| 35                   | SPRING CLIP X nn                          |     | \$                     | 23.00    |           |
| 36                   | FRONT WINDSCREEN CAMERA SILICONE PAD X nn |     | \$                     | 123.00   |           |
| 37                   | PRIMER X nn                               |     | \$                     | 22.00    |           |
| 38                   | FRONT RIM - LH / cut                      |     | \$                     | 1,889.00 | 1511.20   |
| 39                   | SILL PANEL TRIM ATTACHMENT PARTS / rec    |     | \$                     | 136.00   | 108.80    |
| 40                   | SILL PANEL TRIM ADHESIVE TAPES / rec      |     | \$                     | 221.00   | 176.80    |
| 41                   | FRONT HEADLIGHT - LH X nn                 |     | \$                     | 8,172.00 |           |
| 42                   | FRONT WINDSCREEN SEALANT X nn             | S/N | \$                     | 200.00   |           |
| 43                   | SUNDRIES ? / rec                          |     | \$                     | 350.00   | 52.64     |
| TOTAL SPARE PARTS    |                                           |     | :                      | \$       | 23,776.00 |
| TOTAL LABOUR CHARGES |                                           |     | :                      | \$       | 12,952.00 |
| GRAND TOTAL          |                                           |     | :                      | \$       | 36,728.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

: Steve (LKK)  
: 25/1/22, 2.30p  
:  
:  
:  
:

00- M AL  
Excess ?  
PJP  
Ry BL y  
7 dys

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

# PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Supplementary Estimate-1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

**Estimate No.**

**Date**

**Service Advisor**

**Pages**

**Regn No**

**Model No**

PA/OD/0063/2022/TF

28-Jan-22

CHANG


1 of 1

SKM 5128 J

AUDI A5 SPORTBACK 2.0 TFSI

| Quantity           | Description                                    | Unit Price      | Amount   |
|--------------------|------------------------------------------------|-----------------|----------|
| <b>Parts</b>       |                                                |                 |          |
| 1                  | FRT FENDER TOP LEDGE COVER - LH <i>fr</i> 1 nn | \$ 40.00        | <i>X</i> |
| <b>GRAND TOTAL</b> |                                                | <b>\$ 40.00</b> |          |

For Premium Automobiles Pte Ltd



Authorised Signature

*Sten*  
*28/1/22*