

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0063/2022/TF
DATE : 25/1/202254865
WIP : 44486

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/1/2022

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. YAP ZONG XING, ERIC
ADDRESS : 21 ANCHORVALE CRECENT
#09-24
SINGAPORE 544654
TELEPHONE : HP +65 9010 2301
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210154384
VEHICLE NO : **SKM 5128 J**
MODEL CODE : A5 SPORTBACK 2.0 TFSI S tronic
MODEL YEAR : 28/12/2021
ENGINE NO : DEM 034426
CHASSIS NO : WAUZZZF5XNA002843
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Jan-22
PLACE OF ACCIDENT : CTE (AYE) BEFORE EXIT 8A

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKM 5128 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. <i>Headlight & sensor remote</i>	S/N \$ 480.00	✓
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY AND DOOR COMPONENTS.	S/N \$ 280.00	✓
3	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
4	TO RENEW FRONT WINDSCREEN.	S/N \$ 480.00	✓
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN AND LHS FRONT DOOR WINDOW GLASS.	S/N \$ 400.00	X
6	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$ 200.00	X
SUB-TOTAL LABOUR CHARGES		: \$ 2,240.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKM 5128 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR BONNET AND LHS FRONT DOOR. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>Root chrome - 0.5</i>	\$ 4,000.00 <i>2.5 x 500</i>	<i>1250</i>
8	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS UPPER A-PILLAR AND LHS SILL PANEL TRIM. <i>6 x 550 + 150</i>	\$ 6,000.00	<i>3450</i>
9	TO RENEW LHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	/
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 12,952.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 5128 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / BR	1	\$	2,493.00
2	FRONT BUMPER SECURING STRIP ?	2	\$	79.00
3	FRONT BUMPER AIR GUIDE - LH ?	1	\$	72.00
4	FRONT BUMPER AIR GUIDE GRILLE - LH ?	1	\$	151.00
5	FRONT BUMPER AIR GRILLE TRIM - LH ?	1	\$	54.00
6	FRONT BUMPER GUIDE SECTON - LH ?	1	\$	41.00
7	FRONT PARKING AID SENSOR ?	1		TBC
8	FRONT PARKING AID SENSOR SEAL RING - ME	4	\$	15.00
9	FRONT FENDER - LH / OD	1	\$	1,189.00
10	FRONT FENDER ATTACHMENT PARTS ?	1	\$	55.00
11	FRONT FENDER CLOSING ELEMENT - LH ?	1	\$	83.00
12	FRONT FENDER BRACKET - LH ?	1	\$	41.00
13	FRONT FENDER DEFORMATION BRACKET - LH ?	1	\$	55.00
14	FRONT FENDER BRACE - LH ?	1	\$	132.00
15	FRONT FENDER CENTER BRACKET - LH ?	1	\$	40.00
16	FRONT FENDER CHROME TRIM - LH ? / ME	1	\$	171.00
17	FRONT WHEEL HOUSING LINER - LH ?	1	\$	299.00
18	FRONT WHEEL SPOILER - LH ?	1	\$	82.00
19	FRONT WHEEL SPOILER TRIM - LH ?	1	\$	39.00
20	FRONT WHEEL SPOILER BRACKET - LH ?	1	\$	27.00
SUB TOTAL SPARE PARTS		:	\$	5,118.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 5128 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FENDER STONE CHIP GUARD - LH / CUT	1	\$	57.00	
22	FRONT WIND MIRROR MOUNTING - LH / BR	1	\$	2,137.00	
23	FRONT WIND MIRROR COVER - LH / MIS	1	\$	308.00	
24	FRONT WIND MIRROR - LH / BR	1	\$	1,298.00	
25	ROOF CHROME MOLDING - LH / CUT	1	\$	706.00	
26	FRONT DOOR UPPER PROTECT SEAL - LH / ?	1	\$	172.00	
27	FRONT DOOR WINDOW SLOT SEAL - LH / ? X	1	\$	446.00	
28	FRONT WATER DEFLECTOR STRIP - LH X	1	\$	75.00	
29	FRONT DOOR CONER TRIM - LH / CUT	1	\$	51.00	
30	FRONT DOOR CHROME TRIM - LH / MC	1	\$	171.00	
31	FRONT DOOR WINDOW - LH X	1	\$	322.00	
32	FRONT WINDSCREEN X	1	\$	1,625.00	
33	RAIN SENSOR FOIL X	1	\$	130.00	
34	RETAINING SPRING X	1	\$	24.00	
35	SPRING CLIP X		\$	23.00	
36	FRONT WINDSCREEN CAMERA SILICONE PAD X		\$	123.00	
37	PRIMER X		\$	22.00	
38	FRONT RIM - LH / CUT		\$	1,889.00	
39	SILL PANEL TRIM ATTACHMENT PARTS / MC		\$	136.00	
40	SILL PANEL TRIM ADHESIVE TAPES / MC		\$	221.00	
41	FRONT HEADLIGHT - LH X		\$	8,172.00	
42	FRONT WINDSCREEN SEALANT X	S/N	\$	200.00	
43	SUNDRIES ?		\$	350.00	
TOTAL SPARE PARTS		:	\$	23,776.00	
TOTAL LABOUR CHARGES		:	\$	12,952.00	
GRAND TOTAL		:	\$	36,728.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
25/1/22, 2.00p

00- M AL
EXHIBIT - ?
P/P
R1 BL Y
7 dys

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legalised features is allowed
- Supplementary work(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT