

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 12 May 2023 12:11 PM
To: Adeline Chng
Cc: Admin A; claimsdept@sg.cntaiping.com
Subject: [SEEK MANADTE] Your ref: SNM22D200652 // LKK ref : CC6/CTI22000883/Upa3q2
[ACCIDENT INVOLVING GBL5076L(CHINA TAIPING) AND GBG8770Y(TP) ON 15/01/2022]
Attachments: LETTER TO OI.pdf; LKK SURVEY REPORT & PHOTOS.pdf; TP LOD.pdf

Your ref: **SNM22D200652**
LKK ref : CC6/CTI22000883/Upa3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING GBL5076L(CHINA TAIPING) AND GBG8770Y(TP) ON 15/01/2022

We refer to the above matter.

It is a head-to-rear collision. We are of the view that liability is not in our driver's favour.

We seek your approval to offer repairer "**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**" at **\$1,902.00(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair	\$ 2,320.00	\$ 1,500.00
2. Loss of USE (5days x \$100.00)	\$ 500.00	\$ 400.00 (4DAYS X \$100.00)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 2,822.00	<u>\$ 1,902.00</u>

Surveyor recommended 3days for repair + 1PRS = 4DAYS.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 11/05/2023 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

