

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : SATHIAMOORTHY S/O THIRUCHITHAMBALAM  
262 YIO CHU KANG RD  
#09-08  
SINGAPORE 545682

Estimate No: MC1902433  
Date: 22 Jan 2022  
Policy No: MT/00374085/04  
Veh Reg No: SLB5401R  
Make/Model: TOYOTA HARRIER  
ELEGANCE 2.0 A

ATTN:

Your Ref No: SLB5401R  
Claim Type: Third Party  
Accident Date: 21/01/2022  
TP Veh Reg No: GBH6344C

## Estimate Repair Cost to Vehicle No :SLB5401R

| Description                          | Quantity | List Price<br>S\$ | Amount<br>S\$ |
|--------------------------------------|----------|-------------------|---------------|
| <b>SPARE PARTS</b>                   |          |                   |               |
| 1 FRONT DOOR LH                      | 1 PC     | 1,881.30          |               |
| 2 FRONT DOOR TAPE OUTER TOP LH       | 1 PC     | 58.20             |               |
| 3 FRONT DOOR TAPE OUTER RR LH        | 1 PC     | 26.40             |               |
| 4 FRONT DOOR TAPE INNER TOP LH       | 1 PC     | 42.20             |               |
| 5 FRONT DOOR LOWER CHROME MLDG LH    | 1 PC     | 158.70            |               |
| 6 FRONT DOOR RUBBER (AT DOOR) LH     | 1 PC     | 213.30            |               |
| 7 FRONT DOOR RUBBER (AT DOOR) BTM LH | 1 PC     | 87.60             |               |
| 8 FRONT DOOR LOCK LH                 | 1 PC     | 561.90            |               |
| 9 REAR DOOR LH                       | 1 PC     | 1,550.40          |               |
| 10 REAR DOOR TAPE OUTER FRT LH       | 1 PC     | 26.40             |               |
| 11 REAR DOOR TAPE OUTER TOP LH       | 1 PC     | 47.40             |               |
| 12 REAR DOOR TAPE OUTER RR LH        | 1 PC     | 26.40             |               |
| 13 REAR DOOR TAPE INNER FRT LH       | 1 PC     | 31.80             |               |
| 14 REAR DOOR TAPE INNER TOP LH       | 1 PC     | 18.50             |               |
| 15 REAR DOOR LWR CHROME MLDG LH      | 1 PC     | 142.50            |               |
| 16 REAR DOOR RUBBER (AT DOOR) LH     | 1 PC     | 181.60            |               |
| 17 REAR DOOR RUBBER (AT DOOR) BTM LH | 1 PC     | 55.50             |               |
| 18 REAR DOOR RUBBER (AT BODY) LH     | 1 PC     | 346.10            |               |
| 19 REAR DOOR HINGE LH TOP & BTM      | 2 PC     | 197.80            |               |
| 20 REAR DOOR LOCK LH                 | 1 PC     | 667.40            |               |
| 21 REAR DOOR WINDOW REGULATOR LH     | 1 PC     | 231.00            |               |
| 22 REAR DOOR WINDOW MOTOR LH         | 1 PC     | 974.10            |               |
| 23 SIDE SKIRT LH                     | 1 PC     | 734.20            |               |
| 24 REAR FENDER LH                    | 1 PC     | 1,531.10          |               |
| 25 REAR FENDER COWLING LH            | 1 PC     | 169.80            |               |
| 26 REAR FENDER COWLING CLIPS         | 8 PC     | 36.00             |               |
| 27 REAR BUMPER                       | 1 PC     | 1,511.70          |               |
| 28 REAR BUMPER LOWER GARNISH         | 1 PC     | 411.70            |               |
| 29 REAR BUMPER SIDE RETAINER LH      | 1 PC     | 82.70             |               |
| 30 REAR BUMPER SIDE SEAL LH          | 1 PC     | 79.00             |               |
| 31 REAR BUMPER CLIPS                 | 8 PC     | 36.00             |               |
| 32 REAR WHEEL BEARING + HUB LH       | 1 PC     | 1,008.80          |               |
| 33 SPORTS RIM LHR (R17)              | 1 PC     | 2,982.70          |               |
|                                      |          | 16,110.20         |               |
|                                      | Less 25% | 4,027.55          | 12,082.65     |

Special Nett

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : SATHIAMOORTHY S/O THIRUCHITHAMBALAM  
262 YIO CHU KANG RD  
#09-08  
SINGAPORE 545682

Estimate No: MC1902433  
Date: 22 Jan 2022  
Policy No: MT/00374085/04  
Veh Reg No: SLB5401R  
Make/Model: TOYOTA HARRIER  
ELEGANCE 2.0 A

ATTN:

Your Ref No: SLB5401R  
Claim Type: Third Party  
Accident Date: 21/01/2022  
TP Veh Reg No: GBH6344C

## Estimate Repair Cost to Vehicle No :SLB5401R

| Description                                                                                                                                                                       | Quantity | List Price | Amount     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|------------|
|                                                                                                                                                                                   |          | <u>S\$</u> | <u>S\$</u> |
| 34 INNER SEAL                                                                                                                                                                     | 1 PC     | 20.00      |            |
| 35 WINDSCREEN SEALANT                                                                                                                                                             | 1 PC     | 40.00      |            |
| 36 TYRE LHF - CHECK PRICE                                                                                                                                                         | 1 PC     | 0.00       |            |
|                                                                                                                                                                                   |          | 60.00      | 60.00      |
| <b>LABOUR</b>                                                                                                                                                                     |          |            |            |
| 37 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.                                                                                                                                        | 1 PC     | 80.00      |            |
| 38 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.                                                  | 1 PC     | 120.00     |            |
| 39 TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS.                                                                                                                                 | 1 PC     | 60.00      |            |
| 40 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.                                                       | 1 PC     | 180.00     |            |
| 41 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.                                                                                                                             | 1 PC     | 120.00     |            |
| 42 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.                                                                                                            | 1 PC     | 80.00      |            |
| 43 TO DISMANTLE AND INSTALL STEERING WHEEL AIR-BAG, PASSENGER AIR-BAG, SEATBELTS AND AIR-BAG CONTROL BOX.                                                                         | 1 PC     | 180.00     |            |
| 44 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.                                                                                                                     | 1 PC     | 60.00      |            |
| 45 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT                                                                                                                 | 1 PC     | 200.00     |            |
| 46 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.                                                                                                                                  | 1 PC     | 60.00      |            |
| 47 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER LH.TO KNOCK & REPAIR REAR FENDER INNER,ROCKER PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. | 1 PC     | 1,000.00   |            |
| 48 TO SPRAY FRONT DOOR LH,REAR DOOR LH,SIDE SKIRT LH,ROCKER PANEL LH,REAR FENDER LH,REAR BUMPER.                                                                                  | 1 PC     | 1,200.00   |            |
|                                                                                                                                                                                   |          | 3,340.00   | 3,340.00   |

*Zila*  
Ah Lim Motor Company

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : SATHIAMOORTHY S/O THIRUCHITHAMBALAM  
262 YIO CHU KANG RD  
#09-08  
SINGAPORE 545682

Estimate No: MC1902433  
Date: 22 Jan 2022  
Policy No: MT/00374085/04  
Veh Reg No: SLB5401R  
Make/Model: TOYOTA HARRIER  
ELEGANCE 2.0 A

ATTN:

Your Ref No: SLB5401R  
Claim Type: Third Party  
Accident Date: 21/01/2022  
TP Veh Reg No: GBH6344C

## Estimate Repair Cost to Vehicle No :SLB5401R

| Description          | Quantity | List Price<br>S\$ | Amount<br>S\$ |
|----------------------|----------|-------------------|---------------|
| Total                |          |                   | S\$ 15,482.65 |
| Add GST @ 7%         |          |                   | 1,083.79      |
| Total Amount Payable |          |                   | S\$ 16,566.44 |

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND FIVE HUNDRED SIXTY SIX AND CENTS FORTY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

Zila  
Ah Lim Motor Company  
AUTHORISED SIGNATURE

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 041D

### Vehicle Details

Vehicle No.: SLB5401R  
Vehicle to be Exported: No  
Intended Deregistration Date: 21 Jan 2022  
Vehicle Make: TOYOTA  
Vehicle Model: HARRIER ELEGANCE 2.0 A  
Primary Colour: White  
Manufacturing Year: 2015  
Engine No.: 3ZRB730067  
Chassis No.: ZSU600072500  
Maximum Power Output: 111.0 kW (148 bhp)  
Open Market Value: \$29,726.00  
Original Registration Date: 13 Apr 2016  
First Registration Date: 13 Apr 2016  
Transfer Count: 0  
Actual ARF Paid: \$28,617.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 12 Apr 2026  
PARF Rebate Amount: \$20,031.00

### Intended COE Rebate Details

COE Expiry Date: 12 Apr 2026  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$47,000.00  
COE Rebate Amount: \$19,866.00  
Total Rebate Amount: \$39,897.00

The information contained herein is correct as at 21 Jan 2022

OK