

Engine/Chassis
Date of accident
Damaged area

List items

N

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

T

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SATHIAMOORTHY S/O THIRUCHITHAMBALAM
262 YIO CHU KANG RD
#09-08
SINGAPORE 545682

Estimate No: MC1902433
Date: 22 Jan 2022
Policy No: MT/00374085/04
Veh Reg No: SLB5401R
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0 A

ATTN:

Your Ref No: SLB5401R
Claim Type: Third Party
Accident Date: 21/01/2022
TP Veh Reg No: GBH6344C

Click 2pm
Not Authorised
61 Rm 858 50h
Recovery After Paint
6 days

Estimate Repair Cost to Vehicle No :SLB5401R

Description	Quantity	List Price	Amount
SPARE PARTS			
1 FRONT DOOR LH	1 PC	1,881.30	✓
2 FRONT DOOR TAPE OUTER TOP LH	1 PC	58.20	✓
3 FRONT DOOR TAPE OUTER RR LH	1 PC	26.40	✓
4 FRONT DOOR TAPE INNER TOP LH	1 PC	42.20	✓
5 FRONT DOOR LOWER CHROME MLDG LH	1 PC	158.70	X
6 FRONT DOOR RUBBER (AT DOOR) LH	1 PC	213.30	X
7 FRONT DOOR RUBBER (AT DOOR) BTM LH	1 PC	87.60	X
8 FRONT DOOR LOCK LH	1 PC	561.90	X
9 REAR DOOR LH	1 PC	1,550.40	✓
10 REAR DOOR TAPE OUTER FRT LH	1 PC	26.40	✓
11 REAR DOOR TAPE OUTER TOP LH	1 PC	47.40	✓
12 REAR DOOR TAPE OUTER RR LH	1 PC	26.40	✓
13 REAR DOOR TAPE INNER FRT LH	1 PC	31.80	✓
14 REAR DOOR TAPE INNER TOP LH	1 PC	18.50	✓
15 REAR DOOR LWR CHROME MLDG LH	1 PC	142.50	✓
16 REAR DOOR RUBBER (AT DOOR) LH	1 PC	181.60	X
17 REAR DOOR RUBBER (AT DOOR) BTM LH	1 PC	55.50	X
18 REAR DOOR RUBBER (AT BODY) LH	1 PC	346.10	X
19 REAR DOOR HINGE LH TOP & BTM	2 PC	197.80	X
20 REAR DOOR LOCK LH	1 PC	667.40	X
21 REAR DOOR WINDOW REGULATOR LH	1 PC	231.00	X
22 REAR DOOR WINDOW MOTOR LH	1 PC	974.10	X
23 SIDE SKIRT LH	1 PC	734.20	X
24 REAR FENDER LH	1 PC	1,531.10	X
25 REAR FENDER COWLING LH	1 PC	169.80	X
26 REAR FENDER COWLING CLIPS	8 PC	36.00	✓
27 REAR BUMPER	1 PC	1,511.70	✓
28 REAR BUMPER LOWER GARNISH	1 PC	411.70	X
29 REAR BUMPER SIDE RETAINER LH	1 PC	82.70	X
30 REAR BUMPER SIDE SEAL LH	1 PC	79.00	X
31 REAR BUMPER CLIPS	8 PC	36.00	✓
32 REAR WHEEL BEARING + HUB LH	1 PC	1,008.80	X
33 SPORTS RIM LHR (R17)	1 PC	2,982.70	✓
		16,110.20	
Less 25%		4,027.55	12,082.65

Special Nett

2,750

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SATHIAMOORTHY S/O THIRUCHITHAMBALAM
262 YIO CHU KANG RD
#09-08
SINGAPORE 545682

Estimate No: MC1902433
Date: 22 Jan 2022
Policy No: MT/00374085/04
Veh Reg No: SLB5401R
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0 A

ATTN:

Your Ref No: SLB5401R
Claim Type: Third Party
Accident Date: 21/01/2022
TP Veh Reg No: GBH6344C

Estimate Repair Cost to Vehicle No :SLB5401R

Description	Quantity	List Price	Amount
34 INNER SEAL	1 PC	SS 20.00	SS
35 WINDSCREEN SEALANT	1 PC	na 40.00	
36 TYRE LHF - CHECK PRICE	1 PC	na 0.00	
		60.00	60.00
LABOUR			
37 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	60
38 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	120.00	60
39 TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS.	1 PC	na 60.00	x
40 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	80
41 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	na 120.00	x
42 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	na 80.00	x
43 TO DISMANTLE AND INSTALL STEERING WHEEL AIR-BAG, PASSENGER AIR-BAG, SEATBELTS AND AIR-BAG CONTROL BOX.	1 PC	na 180.00	x
44 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	50
45 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	1 PC	na 200.00	x
46 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30
47 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER LH.TO KNOCK & REPAIR REAR FENDER INNER,ROCKER PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	600
48 TO SPRAY FRONT DOOR LH,REAR DOOR LH,SIDE SKIRT LH,ROCKER PANEL LH,REAR FENDER LHS,REAR BUMPER	1 PC	880	
		3,340.00	3,340.00

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: