

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SATHIAMOORTHY S/O THIRUCHITHAMBALAM
262 YIO CHU KANG RD
#09-08
SINGAPORE 545682

Estimate No: MC1902433
Date: 22 Jan 2022
Policy No: MT/00374085/04
Veh Reg No: SLB5401R
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0 A

ATTN:

Your Ref No: SLB5401R
Claim Type: Third Party
Accident Date: 21/01/2022
TP Veh Reg No: GBH6344C

Click 2pm
NOT Authorized
6/1/2022
Returning After Paint

Estimate Repair Cost to Vehicle No :SLB5401R

6days

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 FRONT DOOR LH	1 PC	1,881.30	✓
2 FRONT DOOR TAPE OUTER TOP LH	1 PC	58.20	✓
3 FRONT DOOR TAPE OUTER RR LH	1 PC	26.40	✓
4 FRONT DOOR TAPE INNER TOP LH	1 PC	42.20	✓
5 FRONT DOOR LOWER CHROME MLDG LH	1 PC	158.70	X
6 FRONT DOOR RUBBER (AT DOOR) LH	1 PC	213.30	X
7 FRONT DOOR RUBBER (AT DOOR) BTM LH	1 PC	87.60	X
8 FRONT DOOR LOCK LH	1 PC	561.90	X
9 REAR DOOR LH	1 PC	1,550.40	✓
10 REAR DOOR TAPE OUTER FRT LH	1 PC	26.40	✓
11 REAR DOOR TAPE OUTER TOP LH	1 PC	47.40	✓
12 REAR DOOR TAPE OUTER RR LH	1 PC	26.40	✓
13 REAR DOOR TAPE INNER FRT LH	1 PC	31.80	✓
14 REAR DOOR TAPE INNER TOP LH	1 PC	18.50	✓
15 REAR DOOR LWR CHROME MLDG LH	1 PC	142.50	✓
16 REAR DOOR RUBBER (AT DOOR) LH	1 PC	181.60	X
17 REAR DOOR RUBBER (AT DOOR) BTM LH	1 PC	55.50	X
18 REAR DOOR RUBBER (AT BODY) LH	1 PC	346.10	X
19 REAR DOOR HINGE LH TOP & BTM	2 PC	197.80	X
20 REAR DOOR LOCK LH	1 PC	667.40	X
21 REAR DOOR WINDOW REGULATOR LH	1 PC	231.00	✓
22 REAR DOOR WINDOW MOTOR LH	1 PC	974.10	✓
23 SIDE SKIRT LH	1 PC	734.20	X
24 REAR FENDER LH	1 PC	1,531.10	X
25 REAR FENDER COWLING LH	1 PC	169.80	X
26 REAR FENDER COWLING CLIPS	8 PC	36.00	✓
27 REAR BUMPER	1 PC	1,511.70	✓
28 REAR BUMPER LOWER GARNISH	1 PC	411.70	X
29 REAR BUMPER SIDE RETAINER LH	1 PC	82.70	X
30 REAR BUMPER SIDE SEAL LH	1 PC	79.00	X
31 REAR BUMPER CLIPS	8 PC	36.00	✓
32 REAR WHEEL BEARING + HUB LH	1 PC	1,008.80	X
33 SPORTS RIM LHR (R17) <i>P17</i>	1 PC	2,982.70	✓
		16,110.20	
	Less 25%	4,027.55	12,082.65

Zita
Ah Lim Motor Company

Special Nett

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SATHIAMOORTHY S/O THIRUCHITHAMBALAM
262 YIO CHU KANG RD
#09-08
SINGAPORE 545682

Estimate No: MC1902433
Date: 22 Jan 2022
Policy No: MT/00374085/04
Veh Reg No: SLB5401R
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0 A

ATTN:

Your Ref No: SLB5401R
Claim Type: Third Party
Accident Date: 21/01/2022
TP Veh Reg No: GBH6344C

Estimate Repair Cost to Vehicle No :SLB5401R

Description	Quantity	List Price	Amount
34 INNER SEAL	1 PC	20.00	20.00
35 WINDSCREEN SEALANT	1 PC	40.00	40.00
36 TYRE LHF - CHECK PRICE	1 PC	0.00	0.00
		60.00	60.00
LABOUR			
37 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	80.00
38 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	120.00	120.00
39 TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS.	1 PC	60.00	60.00
40 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	180.00
41 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	120.00	120.00
42 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	80.00	80.00
43 TO DISMANTLE AND INSTALL STEERING WHEEL AIR-BAG, PASSENGER AIR-BAG, SEATBELTS AND AIR-BAG CONTROL BOX.	1 PC	180.00	180.00
44 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	60.00
45 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	1 PC	200.00	200.00
46 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	60.00
47 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER LH.TO KNOCK & REPAIR REAR FENDER INNER,ROCKER PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	1,000.00
48 TO SPRAY FRONT DOOR LH,REAR DOOR LH,SIDE SKIRT LH,ROCKER PANEL LH,REAR FENDER LH,REAR BUMPER.	1 PC	1,200.00	1,200.00
		3,340.00	3,340.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission
Date of Accident 21/01/2022 16:34 (SGT)
Exact Location of Accident 21/01/2022 06:40 (SGT)
Additional Location Information Yio Chu Kang Rd, Singapore
Country/State of Loss -
Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLB5401R
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner SATHIMOORTHY S/O THIRUCHITHAMBALAM
NRIC No SXXXXX041D
Email Address SSATHIAMOORTHY@HOTMAIL.COM
Mobile Phone No (Phone) +65-91836967
Alternative Phone No +65-91836967

VEHICLE PARTICULARS

Manufacturer Toyota
Model Harrier
Variant HARRIER ELEGANCE 2.0 A
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1986


INSURANCE COMPANY

Name of Insurance Company Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number MT/00374085/04
Cover Note Number 13/04/2021 - 12/04/2022

DRIVER

Name of Driver SATHIMOORTHY S/O THIRUCHITHAMBALAM
NRIC No SXXXXX041D

Date of accident: 21-1-2023 Time: 6:40am Location: Yio Chu Kang Road
 My Vehicle A: SLR 5401R Vehicle B: GBH 6344C Vehicle C: —
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Yio Chu Kang Road going towards
 Serangoon Gardens.
 A van GBH 6344C come out from
 Poh Hyat Road
 It hit me. We came down take
 photographs. Exchange hp numbers.
 He was rushing to hospital for his
 wife's treatment.
 He told me claim from his insurance.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

ZM
 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Zila
 Ah Lim Motor Company
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: